# **Environmental Quality Commission**



### **SPECIAL MEETING AGENDA**

Date: 8/31/2016 Time: 6:30 p.m.

City Hall/Administration Building 701 Laurel St., Menlo Park, CA 94025

- A. Call To Order
- B. Roll Call Bedwell, DeCardy, Dickerson, Vice Chair London, Marshall, Chair Martin, Smolke
- C. Public Comment

Under "Public Comment," the public may address the Commission on any subject not listed on the agenda. Each speaker may address the Commission once under Public Comment for a limit of three minutes. Please clearly state your name and address or political jurisdiction in which you live. The Commission cannot act on items not listed on the agenda and, therefore, the Commission cannot respond to non-agenda issues brought up under Public Comment other than to provide general information.

### D. Regular Business

- D1. Make a determination on an appeal for one heritage Redwood tree at 1080 San Mateo Drive (Attachment) 1hr
- D2. Consider a recommendation to the Planning Commission and City Council on a request to remove 39 heritage trees on property located at 350 Sharon Park Drive (Attachment) 1 hour Kaitlin Meador, Associate Planner
- D3. Consider a recommendation to the Planning Commission and City Council on a request to remove 59 heritage trees on property located at 1300 El Camino Real (Attachment) 1 hour Thomas Rogers, Principal Planner
- D4. Approve June 22, 2016 Environmental Quality Commission meeting minutes (Attachment) 2 mins
- E. Reports and Announcements
- E1. Update on Heritage Tree Ordinance implementation and revisions 5 minutes Christian Bonner, Vanessa Marcadejas, and Heather Abrams
- E2. Future agenda items 5 mins
- F. Adjournment

Agendas are posted in accordance with Government Code Section 54954.2(a) or Section 54956. Members of the public can view electronic agendas and staff reports by accessing the City website at <a href="https://www.menlopark.org">www.menlopark.org</a> and can receive e-mail notification of agenda and staff report postings by subscribing to the "Notify Me" service at <a href="menlopark.org/notifyme">menlopark.org/notifyme</a>. Agendas and staff reports may also be obtained by contacting Heather Abrams, Environmental Programs Manager, at 650-330-6765. (Posted: 8/26/16)

At every Regular Meeting of the Commission, in addition to the Public Comment period where the public shall have the right to address the Commission on any matters of public interest not listed on the agenda, members of the public have the right to directly address the Commission on any item listed on the agenda at a time designated by the Chair, either before or during the Commission's consideration of the item.

At every Special Meeting of the Commission, members of the public have the right to directly address the Commission on any item listed on the agenda at a time designated by the Chair, either before or during consideration of the item.

Any writing that is distributed to a majority of the Commission by any person in connection with an agenda item is a public record (subject to any exemption under the Public Records Act) and is available for inspection at the City Clerk's Office, 701 Laurel St., Menlo Park, CA 94025 during regular business hours.

Persons with disabilities, who require auxiliary aids or services in attending or participating in Commission meetings, may call the City Clerk's Office at 650-330-6620.

### **Public Works**



### **STAFF REPORT**

Environmental Quality Commission
Meeting Date: 8/31/2016
Staff Report Number: 16-009-EQC

Regular Business: Issue determination on appeal of staff's approval of

one Heritage Tree removal permit for 1080 San

Mateo Dr.

### Recommendation

Staff recommends the Environmental Quality Commission (EQC) deny the appeal and uphold staff's decision to approve the Heritage Tree removal permit application at 1080 San Mateo Dr.

### **Policy Issues**

The proposed action is consistent with City policies.

### **Background**

On April 13, 2016 project arborist, Donald Araki submitted a Heritage Tree removal permit application on behalf of property owner, Lynn Segal to remove one coast redwood Heritage Tree located at 1080 San Mateo Dr. The permit application was submitted with completed arborist form and associated images (Attachment A) and stated the following reasons for removal request:

- Property damage to garage foundation
- Proximity to driveway and neighboring pool (1090 San Mateo)

The City Arborist reviewed the application, inspected the subject tree and evaluated the tree condition, location and reported property damage (Attachment B). The City Arborist approved the permit application based on the following:

- Property damage to garage foundation, associated use of garage door, and fence.
- The proximity of the tree to garage foundation and door, driveway, and neighboring fence and pool.
- Root pruning to repair foundation as an alternative to removal would take place within the critical root zone (CRZ) and would likely have an adverse effect on tree stability and health.

On June 29, 2016, Horace and Betsy Nash filed a heritage tree appeal to the EQC to deny the permit to remove the subject tree (Attachment C).

### **Analysis**

Chapter 13.24 of Menlo Park's Heritage Tree Ordinance (Municipal Code) stated intent is to establish regulations of the removal of Heritage Trees within the city in order to preserve as many trees as possible consistent with the purpose of this chapter and the reasonable economic enjoyment of private property.

**Section 13.24.040**, **of said chapter** requires staff and the EQC to consider the following eight factors when determining whether there is good cause for permitting removal of a heritage tree:

- (1) The condition of the tree or trees with respect to disease, danger of falling, proximity to existing or proposed structures and interference with utility services;
- (2) The necessity to remove the tree or trees in order to construct proposed improvements to the property;
- (3) The topography of the land and the effect of the removal of the tree on erosion, soil retention and diversion or increased flow of surface waters;
- (4) The long-term value of the species under consideration, particularly lifespan and growth rate:
- (5) The ecological value of the tree or group of trees, such as food, nesting, habitat, protection and shade for wildlife or other plant species;
- (6) The number, size, species, age distribution and location of existing trees in the area and the effect the removal would have upon shade, privacy impact and scenic beauty;
- (7) The number of trees the particular parcel can adequately support according to good arboricultural practices;
- (8) The availability of reasonable and feasible alternatives that would allow for the preservation of the tree(s).

Staff's approval of the removal permit was based on the following Heritage Tree Ordinance conditions:

- (1) The condition of the tree or trees with respect to disease, danger of falling, proximity to existing or proposed structures and interference with utility services;
- (8) The availability of reasonable and feasible alternatives that would allow for the preservation of the tree(s).

With respect to criteria one, concerns related to the proximity to existing or propose structures were assessed:

- The subject tree has prominent root collar, enlarged area at base of trunk. It is approximately twice the size of the trunk diameter and its growth has raised the grade of the surrounding soil greater than 24 inches (Attachment D).
- The root collar is abutting and displacing property line fence between 1080 San Mateo and 1090 San Mateo (Attachment E).
- The roots of subject tree are causing structural damage to foundation of adjacent garage located approximately 6 feet from root collar (Attachment F).
- Displacement of the garage foundation cause by root development is limiting the function of the garage door (Attachment G).
- The roots are growing in close proximity to the neighboring pool, located at 1090 San Mateo, and are likely to cause future damage (Attachment H, #4).
- The driveway has required recent replacement due to uplifting caused by surfacing roots
  (Attachment I). Work required root pruning and was completed in 2014 at a cost of approximately
  \$25,000 according to property owner.

With respect to criteria eight, reasonable and feasible alternatives were considered:

- The subject tree is located approximately six feet from the garage foundation and, in the opinion of the City Arborist, is within the CRZ.
- Root pruning with in the CRZ is likely to have an adverse effect on the subject tree's stability and health (Attachment J).

Staff recommends the Environmental Quality Commission (EQC) deny the appeal and uphold staff's decision to approve the Heritage Tree removal permit application based on these findings.

### **Impact on City Resources**

There are no additional City resources required for this item.

### **Environmental Review**

An Environmental Review is not required for this item.

### **Public Notice**

Public Notification was achieved by posting the agenda, with the agenda items being listed, at least 72 hours prior to the meeting.

### **Attachments**

- A. Heritage Tree Removal Permit Application
- B. City Arborist Tree Evaluation Form
- C. Appellants Appeal of the Removal Approval
- D. Pronounced Root Collar
- E. Property Fence Displacement
- F. Structural Engineer's Report
- G. Garage Foundation/Door Damage
- H. Registered Professional Forester's Report
- I. Encroachment Permit for Driveway Repair
- J. Critical Root Zone

Report prepared by: Christian Bonner, City Arborist

Report reviewed by:

Vanessa Marcadejas, Senior Sustainability Specialist



Heritage Tree Removal Permit Application

This application must be submitted with the Arborist Report Form
Please submit completed forms to:
701 Laurel Street, Menio Par k, CA 94025

Application No. HTR2016-00090

Purpose of application: Removal Pruning of more than 25%
Permit Fee: \$135.00 (each tree, up to 3 trees); \$90 each additional tree (separate forms required for each tree)
PLEASE PRINT CLEARLY
Site Address: 1080 San Mater Dr
Phone 405-2021-100 FFAX
Mailing Address: NGC A) EVA 24- AUS Email:
Type of Tree: (creston Reposition on property: Tonck 1/1220)
TO CLUSE THE GORAGE, DRIVE, DAY AND NEIGHBIES
P 1 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1 2
IF TREE IS DEAD or DAMAGING STRUCTURE PLEASE ATTACH PHOTOS DEMONSTRATING CONDITION.
ARE YOU CONSIDERING ANY CONSTRUCTION ON YOUR PROPERTY IN THE NEXT 12 MONTHS?
Yes D No D  If yes, please submit additional information describing what type of construction is planned and a site plan.
Tree may not be removed (or pruned over 25%) unless and until the applicant has received final permission  Tree may not be removed (or pruned over 25%) unless and until the applicant has received final permission.
from the City as indicated below.  The signed permit approval form must be on site and available for inspection while the tree works being
A suitable replacement tree, 15 gallon size or targer with a mature height of 40 feet or more, is to be installed in
the time frame indicated below.
I (we) hereby agree to hold the City harmless from all costs and expenses, including attorney's fees, incurred RV by the City, including but not limited to, all cost in the City's defense of its actions in any proceeding brought by the City, including but not limited to, all cost in the City's defense of its actions in any proceeding brought.
by the City, including but not limited to, all cost in the City's determined it as a state of its determined in any State or Federal Court challenging the City's actions with respect to the proposed tree temoval.
Incomplete applications will not be processed.
Signature of property owner authorizing access and inspection of tree in his/her absence
deal Date 4/11/16
Date Hill
PLEASE DO NOT WRITE BELOW THIS LINE
PERMIT APPROVED PERMIT DENIED 1.1
TIMING OF REMOVAL  TIMING OF REPLANTING  Within 30 days of Heritage Tree removal
Pulpon receipt of this approved permit for associated   L1 Prior to final building inspection of associated
construction construction
Staff Signature: All 18. E. Date: 6/14/16
Staff Signature: Date: Date:
Print name and title: CTTY ATCSOTTST



# **Arborist Form**

Please complete one form for each tree. Mark each tree with colored ribbon or tape prior to our inspection.

Site Address: 1080 SAN MATED DEIJE
ARBORIST INFORMATION: Name of Certified Arborist  DON ALD Μ Δ RAK.
ISA or ASCA number: WE-65474 Menlo Park Business License number: 63 394
Company: TREE SPECIACISE JNC.
Address: NAS NEJADA ANG
Phone: 405-209-1007 FAX: Email: mutre especialiste yahous
TREE INFORMATION:
Date of Inspection:
Common Name: Coastal redward Botanical Name: Segudia Sempervirum
Location of Tree: FROUT MARO LEFT Height of Tree: 50'
Diameter of tree at 54 inches above natural grade: 57.67
Circumference of tree at 54 inches above natural grade 161 "
Condition of Tree:
6220
If recommending removal or pruning, please list <u>all</u> reasons:
FO CLOSE TO THE GARAGE, BRENEING THE GARAGE SLAB ALSO TO CLOSE THE NEIGHBUR POOL
Suggested Replacement Tree:
Signature of Arborist: Handle Date: 3   10   16

















# **City Arborist Tree Evaluation Form**

Address/Tree Location: 1080 San Mateo Dr. Tree Species: Sequoia sempervirens	Permit #HTR2016-00090 DBH: 58" Height: 60'					
	AD, HAZARD, PEST INFESTATION – WAIVE APPEAL					
	ACTORS					
Topography Flat X Slope ☐% Other Heritage Trees						
Site Changes None ☐ Grade Change ☐ Site Clearing ☐ Root Cu Comments: Raised planter bed						
Soil Conditions Limited Volume X Saturated Shallow Compacted Pavement Over Roots X 33%  Comments:						
TREE HEALTH AND	SPECIES PROFILE					
Vigor Low ☐ Normal X Foliage None (seasonal) ☐ None (dead) ☐ Pest/Disease	Normal 85% Chlorotic 5% Necrotic 10% -					
Tree Health Poor ☐ Fair ☐ Good X						
	RE & CONDITIONS					
	d Branches -					
Unbalanced crown ☐ LCR: 90% Dieback ☐	Cracks□ Lightning Damage □					
Dead Twigs/Branches% overall Max. Dia	Co-dominant 🗆 Included Bark 🗆					
Broken/Hangers Number Max. Dia Over-Extended Branches	Weak Attachments □ Cavity/Nest Hole% circ.					
Pruning/ Maintenance History	Cankers/Galls/Burls ☐ Sap Ooze ☐ Conks/Mushrooms ☐					
Crown Cleaned ☐ Thinned ☐ Raised X Reduced X Topped ☐	Previous Limb Failures 🗆					
Lion-Tailed ☐ Flush Cuts ☐ Stub Cuts ☐ Cabling ☐ Mortar ☐	Vines/Mistletoe ☐ Dead/ Missing Bark ☐ Response Growth ☐					
Other 🗆	Conks ☐ Heartwood Decay ☐ Sapwood Damage/Decay ☐					
Concern(s)/Notes: Normal seasonal dead foliage, minor dead in lower crow						
Crown Density Sparse ☐ Normal X Dense ☐ Reduced ☐ Interior Br	anches Few □ Normal X Dense □					
- Trunk -	- Roots and Root Collar -					
Dead/ Missing Bark ☐ Abnormal Bark Texture/Color ☐	Collar Buried/Not Visible ☐ Depth Surfacing Roots ☐					
Co-dominant Stems ☐ Included Bark ☐ Cracks ☐	Girdling Roots ☐ Stem Girdling ☐ Dead ☐ Decay ☐ Sap Ooze ☐					
Sapwood Damage/Decay ☐ Cankers/Galls/Burls ☐	Conks/Mushrooms ☐ Cavity ☐% circ. Depth					
Sap Ooze ☐ Lightning Damage ☐ Heartwood Decay ☐	Cracks ☐ Cut/Damaged Roots X Distance From Trunk: 10-12'					
Conks/Mushrooms ☐ Exit Holes/Pitch Tubes ☐ Frass ☐	Root Plate Lift ☐ Soil Weakness ☐ Property Damage X					
Cavity/Nest Hole% circ. Depth Poor Taper  Lean * Corrected? Response Growth: Concern(s)/ Notes: Normal	Response Growth: pronounced root collar with epicormic suckers Concern(s)/ Notes: Abutting and displacing wood fence. Lifting garage foundation and displacing garage door.					
Tree Structure Poor ☐ Fair ☐ Good X						
CATEGORY						
Structural Defects Diseased/Pest Infestation High Risk Dead/Severe Decline Proximity to Structures X Utility Conflict Construction						
☐ Topography ☐ Long Term Value ☐ Ecological Value ☐ Grove ☐ Aesthetic Impact ☐ Overcrowding ☐ Alternatives ☐ Other ☐						
CONCLUSIONS						
Relative Tolerance of Development Impacts Poor  Fair Good N/A Suitability for Retention Poor Fair Good N/A						
Permit Approved X Permit Denied  Tentative Permit Approval (Subject to Planning)  Tentative Permit Denial (Subject to Planning)						
No Permit Decision (Further Evaluation is Recommended)						
SIGNATURE						

pad \$200 € RECEIVED

Subject: Appeal of Heritage Tree Removal Application

JUN 29 2016

June 29, 2016

City Clerk's Office City of Menlo Park

Ladies and Gentlemen:

We recently became aware that our neighbors at 1080 San Mateo Drive seek approval to remove a 60' Coastal Redwood (Sequoia sempervirens) that is in perfect health. Because we just found out about this yesterday, we have not had a chance to talk to the property owner before today's appeal deadline.

The tree sits at the edge of the property, near the fence line and well away from any foundations. The nearby driveway shows no signs of damage. The City arborist tree evaluation form states that the tree is healthy. The notice posted on site says that the tree has caused "property damage" and the City arborist cites damage to the fence as property damage sufficient to serve as the reason to support removal. We were astonished to read that the arborist recommends that the permit be approved under these circumstances. Surely it is simpler, cheaper, and more consistent with City policies to fix the fence than it is to remove this beautiful heritage tree. Surely the City does not want to establish a precedent that any tree along any fence line can be removed. If the structural damage concern is cracks to the garage slab, as claimed in the application, surely a more reasonable solution is simply to cut the root that may be causing the crack, rather than removing the whole tree.

Menlo Park has a long-standing commitment to preserving heritage trees. Menlo Park advertises itself as Tree City USA, and the Menlo Park canopy throughout the city is an important civic feature. Trees delight our citizens, attract new residents and create a unique ambiance for the entire community.


The beautiful tree at 1080 San Mateo is probably 70 years old – quite young in a species that lives for hundreds of years. "Sequoia sempervirens" literally translates to "Long-lived Sequoia." It is a prized California native tree, healthy, doing no harm while benefiting the entire community by its presence. Please review the property owner's application with these considerations in mind, and help the property owner find a solution that does not require removal of this tree.


Thank you.

Horace and Betsy Nash, 1224 Santa Cruz Ave.

Sally Cole, 1235 Santa Cruz Ave.

# Appeal of Heritage Tree Removal at 1080 San Mateo Drive





Appeal of Heritage Tree Removal at 1080 San Mateo Drive











May 19, 2016

Mr. Lynn Segal 1080 San Mateo Drive, Menlo Park, CA 94025

RE: Tree Removal at Residence located at

1080 San Mateo Drive Menlo Park, CA.

### Dear Sirs:

We visited the site and made observations of the Redwood tree that is located approximately 5 feet from your garage and also 5 feet from your neighbors swimming pool. We checked the garage slab which has sever cracking. The roots are causing structural damage to the house already and will continue to do future damage to the house.

The state of your neighbors swimming pool is also in jeopardy due the extent of the roots. The tree is approximately 100 feet tall and the trunk is approximately 5 feet diameter. We are very concerned about both the safety of the structures due to root uplifting and also the safety of inhabitants of both properties from falling branches which can be deadly to persons and cause extensive damage to the structures.

It is our professional opinion that the tree should be removed.

Should you require further information or clarifications on these matters, please do not hesitate to call.

Sincerely, BCA Structural Engineering, Inc.

Geoffrey Clifford, S.E. President



# ATTACHMENT G









# Ralph Osterling Consultants, Inc.

1650 Borel Place, Suite 204 San Mateo, CA 94402-3508

July 20, 2016

Kelly Bryant via email: cjw architecture.com

RE: Redwood Tree Removal Application

1080 San Mateo Drive Menlo Park

### Dear Kelley:

This letter is in response to our telephone conversation regarding the above redwood tree growing adjacent to the driveway at 1080 San Mateo Drive and your property. Having a large vigorous redwood growing very close to your turf and pool area can and will be very problematic. Several things must be considered if the removal application is denied:

- 1. This coast redwood is a forest scale tree capable of rapidly growing 6-8 feet in diameter and 200 feet tall.
- 2. The roots for such a large tree extend into surrounding garden and moist areas were water and nutrients are available, aka, your garden and pool area.
- 3. The roots extended heavily under the driveway and will do so again, plus under the garage floor. I noted cracks in the garage floor which I professionally feel are caused by the roots. This situation will only get worse.
- 4. Based on my professional opinion the roots are already extending under your pool decking and probably under the coping. On another similar situation, the feeder roots had extended under the coping and into the pool. I looked quickly along the pool edge and I suggest you do so to spot root intrusion into the pool.
- 5. Cutting the roots on one side as was done for the repair of the driveway leaves the tree less stable with some 35 or more percent of the roots cut and removed.

As I stated in my earlier letter, I professionally recommend, or urge this tree be promptly removed to eliminate future damages. Should you or others have questions or comments, please contact me at your convenience.

Respectfully,

Ralph Osterling, President, ACF, CLFA Registered Professional Forester #38

State of California

RSO:js

RALPH S.
OSTERLING
#38

SALE OF CALIFORNIA

Phone: (650) 573-8733 Fax: (650) 345-7890 Email: ralph@ralphosterling.com

### ATTACHMENT I



City of Menlo Park 701 Laurel Street Menlo Park, CA 94025 Engineering Division

Phone:(650) 330-6740

Permit No.: ENG2014-00020

Issued:1/16/2014

Keep this permit at the work site at all times

Call 24 hours in advance of working in the public right of way AND for each inspection request.

Uninspected work will be rejected.

City Mandated Repair	Major End	croachmen	nt [	Otl	her:	_ 12 1		
Minor Encroachment	Debris Box							
over 12 to the post to the first of the control of	ONE PE	RMIT P	ER ADD	RES	S			
Name of Applicant (person)	Representing Location of work							
VISTA LANDSCAPING	X Contract	X Contractor 1080 San Mateo Drive						
Name of Owner	Address	ejorg arti i	halls ub	City		State	Zip	Telephone
SEGAL LYNN	1080 SAN MA	TEO DR	MENLO PARE		LO PARK	CA	94025-	
Name of Contractor	Address	no 10 /	and the second	City		State	Zip	Telephone
VISTA LANDSCAPING	1049 MIDDLE	FIELD RD	295	SALI	NAS	CA	93906	the office
CA Contractor License No	Menlo Parl	k Business	License N	lo	Est. Star	t Date	Est. C	ompletion Date
	100000 A 10000				1/16/2014		2/16/20	14
Estimated Construction Cost			700	THY I	Bond pro	vided by	v	
(Estimate work in city R/W	D. Green Halfs (1995)			Titlan I	nipues	,		
only. Do not include value of utility.)	g Digues e a See.			36.6.5				
	1				,			
Description of work to be done:								
Remove and replace AC parking strip.								
Call U	Inderground Se	rvice Alert	(USA) at 8	811 bej	fore you di	g		7 4
GENER	AL CONDITION	ONS OF P	ERMIT:	(See a	ttached sh	eet)		
Signature below acknowledges th						10250	d troffic	control plan
I hereby acknowledge that I have read this permit authorized agent of the owner, and that I agree to any governmental agency involved.								
ou Fip								
Signature of Applicant (Owner or authorized agent)	Title				Date			
Approved by Director of Engineering S	Services	Date	<b>Permi</b> 4/16/2		res Fe	es (retain	ned by city)	500-
		19		2	То	tal due	to City	
1								3500000 - 11 - 1616-2- 300 - 300 - 300 - 12- 300 - 300

**ENCROACHMENT PERMIT** 

\* Bond or deposit requests must originate from the bond/deposit provider.

A copy of the original receipt must accompany the refund request. All deposits or bonds are subject to forfeiture to comply with City Codes or Ordinances.

# **Pre-Construction Phase**

The pre-construction phase is the period between the planning and construction phases. Tree removals, tree protection zone establishment, building layout and road construction occur during this phase. This is the appropriate time to have a meeting with the arborist, builder, owner, architect, and regulatory agency representative to ensure understanding of the scope of the tree conservation activities and penalties.

## **Defining the Tree Protection Zone**

A tree's Critical Root Zone (CRZ) is the area around the trunk where roots essential for tree health and stability are located. A Tree Protection Zone (TPZ) is an arborist-defined area surrounding the trunk intended to protect roots and soil within the critical root zone and beyond, to ensure future tree health and stability. There are many methods for determining size for a TPZ (see Matheny and Clark's *Trees and Development*). The dripline method uses the tree's canopy dripline to define the boundary of the TPZ (Figure 1). The entire area within the dripline is considered the TPZ.




Figure 1. Dripline method of establishing a TPZ.

### AGENDA ITEM D-2

# Community Development



STAFF REPORT

Environmental Quality Commission

Meeting Date: 8/31/2016

Staff Report Number: 16-008-EQC

Regular Business: Heritage Tree Permit/Maximus Real Estate/350

**Sharon Park Drive** 

### Recommendation

Staff recommends that the Environmental Quality Commission (EQC) review and discuss the applicant's proposed request to remove 39 heritage trees due to existing health and/or structure at the 15.6-acre subject site and provide a recommendation on the heritage tree removal request. The proposed project includes exterior modifications of eighteen existing apartment buildings, one existing clubhouse and three accessory buildings located at 350 Sharon Park Drive.

### **Policy Issues**

Each heritage tree permit request is considered individually. The Environmental Quality Commission should review and provide recommendations on the requested 39 heritage tree removals, the proposed heritage tree replacement planting plan, and the replacement ratio for the project.

### **Background**

### Site Location

The project site is located at 350 Sharon Park Drive in the R-3-A-X (Garden Apartment, Conditional Development) zoning district, and occupies the entire city block. For the purposes of this report, Sharon Park Drive is considered to be in an east/west orientation. The site is bounded by Sharon Park Drive to the south, Monte Rosa Drive to the west, Eastridge Avenue to the north, and Sharon Road to the east. A location map is included in Attachment A.

Parcels to the north of the site along Eastridge Avenue are located within the R-2 zoning district. The parcels are generally occupied by duplexes and multi-family developments. To the west of the site along Monte Rosa Drive, the parcels are located in the R-3-A-X zoning district and are occupied by multi-story, multi-family complexes. The Sharon Heights Shopping Center and a multi-story office building are located across Sharon Park Drive to the south of the site. The shopping center is zoned C-2 and the office building is zoned C-1-X. The Sharon Oaks and Sharon Glen condominium complexes are located to the east of the site across from Sharon Road. Both housing complexes are located within the R-3-A-X zoning district.

### **Proposed Project**

The applicant is requesting an architectural control permit which would include façade improvements to all of the existing apartment buildings, three accessory buildings, and clubhouse. The applicant is also

proposing a comprehensive update of the site landscaping, which includes the removal of 39 heritage trees. As part of the overall site improvements, additional on-site amenities will be incorporated, such as a bocce ball court, enclosed children's play area, and new BBQ courtyards. The overall site layout has been designed to minimize impacts to the existing trees. It should be noted that none of the heritage trees proposed for removal are due to conflicts with the proposed construction. A copy of the site plan, tree removal plan, tree replacement plan and preliminary landscape plans are provided in Attachment B.

The subject property contains 296 units, varying in size from one bedroom to three bedrooms, located in 18 multi-story apartment buildings with a combined recreation center and leasing office, and three multi-level parking structures. The Sharon Heights area was originally developed with a conditional development permit (CDP) and multiple subdivisions in the 1960s and 1970s. In 2013, an application for the removal of 42 heritage trees was requested in association with an Architectural Control project for a more extensive redevelopment of the site and landscaping, including changes to the CDP that would have required City Council review. The EQC provided recommendations on these removals; however, the application was later withdrawn prior to action.

Since the current development project does not require City Council review and action, the project would be acted upon by the Planning Commission, and subsequently the EQC would not be involved in reviewing the project, unless the City arborist's actions on the heritage tree application were appealed. However, since the previous request for heritage trees removals went to the EQC, staff is requesting that the EQC review the proposed heritage tree removals and provide a recommendation. The EQC recommendation will be provided to the Planning Commission as context for their deliberations and actions on the proposed architectural control, and the City Arborist will likewise consider the EQC input prior to actions on the heritage tree removal permits.

### **Analysis**

The applicant has submitted an arborist report which evaluates the 464 heritage and non-heritage trees on site and documents the size, heritage status, and tree condition. The report also provides tree removal recommendations and tree protection measures to mitigate potential impacts to the existing trees during construction. The report was prepared by Jonathan Cardenas of Arborwell Professional Tree Management, a Board-Certified Arborist. A copy of the report is provided in Attachment C. The 39 heritage tree removals are summarized in the following table:

Heritage Tree Removal Summary					
Tree Type	Number of Trees				
Monterey Pine (Pinus radiata)	15				
Evergreen Pear (Pyrus kawakamii)	2				
Red Gum (Corymbia ficifolia)	1				
Tulip (Liriodendron tulipifera)	1				
Red Ironbark (E. sideroxylon)	4				

Sycamore (Platanus hispanica)	2
Acacia (Axaxia melanoxylon)	2
Red Flowering Gum (Eucalyptus spp.)	2
Blue Oak (Quercus douglassi)	1
Shamel Ash (Feazimus uhdei)	6
Silver Dollar Eucalyptus (E. polyanthemos)	3
Total Tree Removals	39

The City's contracting arborist, Fujitrees Consulting, has reviewed the arborist report and conducted a site visit to independently evaluate the health and condition of the heritage trees proposed for removal. Fujitrees Consulting determined that the heritage tree removal requests were warranted. The evaluation is included as Attachment D. The City arborist also reviewed the consulting arborist's report.

### Municipal Code Requirements

Section 13.24.040 of Menlo Park's Heritage Tree Ordinance, requires consideration of the following eight factors when determining whether there is good cause for permitting removal of a heritage tree:

- 1. The condition of the tree or trees with respect to disease, danger of falling, proximity to existing or proposed structures and interference with utility services;
- 2. The necessity to remove the tree or trees in order to construct proposed improvements to the property;
- 3. The topography of the land and the effect of the removal of the tree on erosion, soil retention and diversion or increased flow of surface waters;
- 4. The long-term value of the species under consideration, particularly lifespan and growth rate;
- 5. The ecological value of the tree or group of trees, such as food, nesting, habitat, protection and shade for wildlife or other plant species;
- 6. The number, size, species, age distribution and location of existing trees in the area and the effect the removal would have upon shade, privacy impact and scenic beauty;
- 7. The number of trees the particular parcel can adequately support according to good arboricultural practices;
- 8. The availability of reasonable and feasible alternatives that would allow for the preservation of the tree(s).

Criteria 1 and 4 are relevant to this request. The heritage trees identified for removal are all being removed due to either poor health, structure, or location, and several species have limited long-term value. These trees pose a significant risk to structures and/or pedestrians on the subject site, and the risk of failure or other damage cannot be reasonably lessened with mitigation. When the trees were originally planted on the site, many of them were planted too close together and to structures which has contributed to their poor heath and/or structure.

While the number of proposed heritage tree removals (39) is large, they represent a small portion of the total trees (approximately 464, including heritage and non-heritage) currently on what is a fairly large 15.6-acre site. In addition, many of the proposed heritage tree removals are Monterey pines, ash, black acacia, and eucalyptuses which are susceptible to disease and which some landscape professionals no longer consider recommended trees for this area or confined spaces. The trees proposed for removal are mature or overly mature.

### Heritage Tree Replacements

The applicant is proposing to provide 39 heritage tree replacements to compensate for the loss of 39 heritage trees, which represents a 1:1 replacement ratio for each heritage tree proposed for removal. The proposed heritage tree replacements include five, 15-gallon tulip (Liriodendron tulipifera); one, 15-gallon American sweetgum (Liquidambar styraciflua); five, 15-gallon Southern magnolia (Magnolia grandiflora); four, 15-gallon California sycamore (Plantanus racemose 'Multi'); three, 15-gallon California live oak (Quercus agrifolia); 17, 15-gallon coast redwood (Sequoia sempervirens); and four, 15-gallon Chinese elm (Ulmus parvifolia 'True Green') trees. Shrubs and groundcover would also be planted throughout the site. The new landscaping would be required to comply with the Water Efficient Landscaping Ordinance (WELO). Staff believes that this comprehensive landscaping revision, including the replacement plantings of preferred species, is appropriate.

### Correspondence

The applicant indicates that four community outreach meetings were held to inform the public of the proposed project and discuss any questions and concerns. The notification for these meetings was performed by distributing invitations to properties within a 300 foot radius of the subject site. During the City's notification process, staff received one comment from a resident of the complex. The letter expressed concerns about the number of redwood tree removals and the size of the replacement trees (Attachment E).

### Conclusion

The proposed heritage tree removals are related to the existing health and/or long-term value of the trees, and they represent a small proportion of the overall trees on a relatively large site. Replacement plantings of preferred species would be provided at a one-to-one ratio. Staff recommends that the Environmental Quality Commission recommend approval of the heritage tree removal permits.

### **Impact on City Resources**

The project sponsor is required to pay Planning, Building and Public Works permit fees, based on the City's Master Fee Schedule, to fully cover the cost of staff time spent on the review of the project.

### **Environmental Review**

The project is categorically exempt under Class 1 (Section 15301, "Exisiting Facilities") of the current California Environmental Quality Act (CEQA) Guidelines.

### **Public Notice**

Public Notification was achieved by posting the agenda, with the agenda items being listed, at least 72 hours prior to the meeting. Public notification also consisted of notification by mail of owners and occupants within a 300-foot radius of the subject property.


### **Attachments**

- A. Location Map
- B. Project Plans
- C. Arborist Report and Tree inventory, prepared by Arborwell, dated May 24, 2016
- D. Peer Review of Arborist Report and Tree inventory, prepared by Fujitrees Consulting, dated July 12, 2016
- E. Correspondence

Report prepared by: Kaitie Meador, Associate Planner

Report reviewed by: Thomas Rogers, Principal Planner

## ATTACHMENT A





# **CITY OF MENLO PARK**

LOCATION MAP 350 SHARON PARK DRIVE

DRAWN: THR CHECKED: KMM DATE: 08/31/16 SCALE: 1" = 300' SHEET: 1



# THIS PAGE INTENTIONALLY LEFT BLANK

# **Sharon Green Apartments**

Schematic Landscape Drawings August 1, 2016

### **Sheet Index**

### **Master Plan Exhibits**

- Landscape Cover Sheet & Sheet Index
- L-2 Landscape Concept Zones Diagram
- L-3 Landscape Concept Zones Descriptions
- 1-4 Tree Removal Plan
- L-5 Tree Replacement Plan
- L-6 Landscape Illustrative Master Plan

### **Amenity Area Enlargements**

- L-7 Main Entrance & Sports Court Plan
- L-8 Main Entrance & Sports Court Site Section
- Main Entrance & Sports Court Imagery L-9
- Clubhouse Pool Area & Leasing Courtyard Plan
- Clubhouse Pool Area & Leasing Courtyard Imagery
- Amenity Space A: "Backyard Garden" Plan
- Amenity Space A: "Backyard Garden" Site Section
- Amenity Space A: "Backyard Garden" Imagery
- Amenity Space B: "Open Space Recreation" Plan (North)
- Amenity Space B: "Open Space Recreation" Plan (South)
- Amenity Space B: "Open Space Recreation" Imagery
- Amenity Space C: "Children's Adventure Park" Plan
- Amenity Space C: "Children's Adventure Park" Imagery
- Amenity Space C: "Children's Adventure Park" Key Activity Images
- L-21 Amenity Space C: "Children's Adventure Park" Key Activity Images
- Amenity Space C: "Children's Adventure Park" Key Activity Images

### **Appendicies**

- Proposed Plant Palettes & Imagery Trees
- Proposed Plant Palettes & Imagery Shrubs
- L-25 Proposed Plant Palettes & Imagery - Perennials & Groundcover
  - Proposed Plant Palettes & Imagery Meadow
- Irrigation Retrofit Design Intent Statement

### ıma 960 atlantic avenue

SB ARCHITECTS

1 Beach Street, Suite 101 San Francisco, CA 94133 415-673-8990

Maximus Real Estate Parts 575 Florida Street, Suite 150 San Francisco, CA 94110

# **Drawings** Sharon Green Apts. Landscape

Issued August 1, 2016

No.	Description	Date
-		
-		_
$\neg$		

Landscape Cover Sheet & Sheet Index



ima

SB ARCHITECTS 1 Beach Street, Suite 101 San Francisco, CA 94133 415-673-8990

Maximus Real Estate Partn 575 Florida Street, Suite 150 San Francisco, CA 94110

# Sharon Green Apts. Landscape Drawings



Landscape Concept Zones

Diagram

50% Schematic Design



### Main Entrance / "Marketing Window"

- New Way-finding & Information Signs
- Enhanced / New Lighting
- Repair Damaged Asphalt / Concrete surface
- Enhanced Planting
- New sidewalk Connect from Street to the Leasing Office
- Relocation or update of Monument Sign
- New Retaining Walls to Hold Grades



# **Pool & Spa Courtyard**

- Demolish existing concrete pool deck and replace with permeable concrete pavers
- Enhance existing concrete steps
- Add an ADA ramp between leasing pavilion and pool deck
- Refurbish pool and spa
- Add new furniture



# **Amenity Spaces**

### A "Backyard Garden" Courtyard

- Renovated Amenity Building (Stove-top, Sink, Refrigerator, Accessible Counters)
- Remove / Fill-in Existing Pool
- Remove Pool Fence, Equipment & Paving
- New Paving, Stairs, & Walls
- New Site Furnishings (Dining Table & Chairs, Lounge Seating, Flexible Seating)
- New Lighting & Information Signs
- Potential New Amenities: Gas BBQ & Fire Feature, String / Festoon Lighting on Posts

### (B) "Activity Courts and Open Space"

- Renovated Amenity Building (Auxiliary Support and Staging for Events)
- Remove Existing Gazebo
- New 'Plaza' (Stepped Lawn Court)
- New Lighting & Information Signs
- New Site Furnishings
- Re-grade Turf Area for Flex Use as Sports Field

### G "Adventure Park" Kids Play Area

- Renovated Amenity Building (Potential 'Parent's Lounge')
- Potential Adventure Play Structures
- New Site Furnishings / Shade Structures
- New Lighting & Information Signs
- Potential New Permeable Paving (DG)
- Re-grade Turf Area to Create Mounds



### **Enhanced Streetscape** Planting

- Low-Height Trees and Flowering Shrubs Random Mix of Planting Strip along with the Sharon Park Dr. and Monte Rosa Dr.



# Open Lawn

- Continuous, Flat (or Gently Sloped), Unobstructed for Passive Recreation



### **Interior Passive** Landscape

- Repair/Replacement of Damaged or Cracked Concrete
- Remove all 'Step Pavers' in favor of Concrete, Decomposed Granite (DG) and/or Stairs (with Handrails) where Required
- Remove Lawn where appropriate
- Add Concrete Header to DG Areas
- New Lighting & Information Signs
- New Site Furnishings
- New Drought-tolerant, Native /Adapted Planting
- Irrigation System Retrofit (Drip, Hydro Zones, ET Controller)
- Selective Removal of Mature Trees due to one or more of the following:
- Disease/Decay per Arborist Report - Structural/Foundation Damage
- Root Intrusion into Storm & Sewer Pipes as evidenced by scoping
- Interference with Proposed Fire Sprinkler Line Routing



### Redwood & Heritage Tree Grove

- and Recommendations
- Zones, ET Controller)
- Potential New Drought-tolerant, Cover Planting



- Refinished (Sign Text will remain the same content and height)
- Maximum Dimensions: 52 sq foot (max height of 8 feet) 18 inches tall letterings\*

for Signs

### Perimeter Passive Landscape

- Repair/Replacement of Damaged or Cracked Concrete
- Remove all 'Step Pavers'
- Remove Lawn where appropriate
- New Lighting & Information Signs
- New Drought-tolerant, Native/ Adapted Planting
- Irrigation System Retrofit (Drip, Hydro Zones, ET Controller)
- Selective Removal of Mature Trees due to one or more of the following:
- Disease/Decay per Arborist Report
- Structural/Foundation Damage
- Root Intrusion into Storm & Sewer Pipes as evidenced by scoping
- Interference with Proposed Fire Sprinkler Line Routing



- Protect-in-Place per Arborist Report
- Irrigation System Retrofit (Drip, Hydro
- Potential Addition of like-Specimens
- Native/ Adapted Shrub & Ground



### **Community Monument** Sign

- Existing Monument Signs to be

\*Refer to City of Menlo Park - Design Guidelines

# **General Landscape Renovation**

- Areas damaged by building new entries will be replaced with similar plant materials
- Add similar species planting as a foreground landscape along Sharon Park Dr. and Monta Rosa Dr.
- Add new similar species planting at orange
- Add new upgraded enhanced planting between Monta Rosa Dr. and the leasing office entry



SB ARCHITECTS

1 Beach Street, Suite 101 San Francisco, CA 94133 415-673-8990

Maximus Real Estate Partn 575 Florida Street, Suite 150 San Francisco, CA 94110

# Landscape Drawings Sharon Green Apts.

Issued August 1, 2016

Landscape Concept Zones Descriptions



ima 960 atlantic avenue alameda, ca 94501

510.353.3950 www.imadesign.com

SB ARCHITECTS 1 Beach Street, Suite 101 San Francisco, CA 94133 415-673-8990

BKF Engineers 255 Shoreline Drive, Suite 200 Redwood City, CA 94065 650-482-6375

BAMO 1000 Brannan Street, Suite 300 San Francisco, CA 94103 415-979-9880

Maximus Real Estate Partners 575 Florida Street, Suite 150 San Francisco, CA 94110

# Landscape Drawings Sharon Green Apts. 350 Sharon Park Dr. Menlo Park, CA


Issued August 1, 2016 50% Schematic Design



Tree Removal Plan

Phase 50% Schematic Design





ima 960 atlantic avenue alameda, ca 94501

SB ARCHITECTS 1 Beach Street, Suite 101 San Francisco, CA 94133 415-673-8990

BKF Engineers 255 Shoreline Drive, Suite 200 Redwood City, CA 94065 650-482-6375

Maximus Real Estate Parts 575 Florida Street, Suite 150 San Francisco, CA 94110

# Sharon Green Apts. Landscape Drawings



Landscape Ilustrative

Master Plan

Phase 50% Schematic Design



# Description


The Monte Rosa Dr. entrance is the 'Front Dooor' of Sharon Green Apartments as visitors and potential residents will be directed here and to the leasing office. New and enhanced planting areas and hardscape will create a fresh look for this Main Entrance. The sports courts and shaded seating areas will be renovated and enhanced to keep with the updated renovated theme.

### Legend

- 1 Existing Parking Stalls
  - Repaved Driveway
- New Enhanced Paving Sidewalk
- Relocated Project Monument Sign
- Direction Sign to Leasing Office
- New Concrete Walk
- Full-Size Basketball Court
- New Chain-link Fence to match Height of Existing Chain-link Fence
- Umbrella/Cabana with Movable Base
  - Planter Pots
- Sight Triangle

### Keymap





ima 960 atlantic avenue alameda, ca

510.353.3950

SB ARCHITECTS 1 Beach Street, Suite 101 San Francisco, CA 94133 415-673-8990

BKF Engineers 255 Shoreline Drive, Suite 200 Redwood City, CA 94065 650-482-6375

Maximus Real Estate Part 575 Florida Street, Suite 15 San Francisco, CA 94110

Landscape Drawings Sharon Green Apts.



Main Entrance & Sports Court Plan



### Legend

- Parking
- 2 Driveway to Parking Garage
  - New Sidewalk
- **Retaining Wall**
- New Monumental Sign
- Flowering Shrubs
- New Accent Tree

# ima 960 atlantic avenue alameda, ca 94501

SB ARCHITECTS 1 Beach Street, Suite 101 San Francisco, CA 94133 415-673-8990

BKF Engineers 255 Shoreline Drive, Suite 200 Redwood City, CA 94065 650-482-6375

Maximus Real Estate Partr 575 Florida Street, Suite 150 San Francisco, CA 94110

# Sharon Green Apts. Landscape Drawings

Issued August 1, 2016 50% Schematic Design

NO.	Description	Date
_		
-		_
-		
-		

Main Entrance & Sports Court Site Section

Place 50% Schematic Design













510.353.3950 www.imadesign.com

SB ARCHITECTS 1 Beach Street, Suite 101 San Francisco, CA 94133 415-673-8990

BKF Engineers 255 Shoreline Drive, Suite 200 Redwood City, CA 94065 650-482-6375

Maximus Real Estate Partner 575 Florida Street, Suite 150 San Francisco, CA 94110

# Sharon Green Apts. Landscape Drawings 350 Sharon Park Dr. Menlo Park, CA

Issued August 1, 2016 50% Schematic Design

No.	Description	Date
_		
_		
_		
_		
_		_
_		
_		

Main Entrance &

Sports Court Imagery

Fluse 50% Schematic Design



### Description

The pool area is located to the North of the Leasing Office and Main Clubhouse. As the primary Amenity Area, the resort style pool, spa and al fresco dining area offer residents elements of a high-end lifestyle. An enhanced indoor-outdoor amenity space becomes an extended living room with views to the luxurious pool and spa area.

### Legend

- Outdoor Fitness/Flexible Event Space with Lawn
- 2 Chaise Lounge Chairs
- Movable Cabanas
- Spa
- Renovated Pool
- 6 New Concrete Paving
- ADA Ramp
- 8 Stairs
- BBQ with Built-in Masonry Counter
- n Dining Table and Lounge Furniture

## Keymap





0 5 10

# ima 960 atlantic avenue alameda, ca 94501

510.353.3950 www.imadesign.com

SB ARCHITECTS 1 Beach Street, Suite 101 San Francisco, CA 94133 415-673-8990

BKF Engineers 255 Shoreline Drive, Suite 200 Redwood City, CA 94065 650-482-6375


Maximus Real Estate Part 575 Florida Street, Suite 150 San Francisco, CA 94110

# Landscape Drawings Sharon Green Apts.

Issued August 1, 2016

No.	Description	Date
_		_
_		_
_		

Clubhouse Pool Area & Leasing Courtyard Plan















# 960 atlantic avenue alameda, ca 94501

# 510.353.3950 www.imadesign.com

SB ARCHITECTS 1 Beach Street, Suite 101 San Francisco, CA 94133 415-673-8990

BKF Engineers 255 Shoreline Drive, Suite 200 Redwood City, CA 94065 650-482-6375

# Maximus Real Estate Partners 575 Florida Street, Suite 150 San Francisco, CA 94110

# Sharon Green Apts. Landscape Drawings

350 Sharon Park Dr. Menlo Park, CA


Issued August 1, 2016 50% Schematic Design

No.	Description	Date
_		_
-		_
-		

Clubhouse Pool Area &

Leasing Courtyard Imagery

Place 50% Schematic Design



# Description

Taking advantage of the existing topography, this courtyard is designed as a split-level outdoor living space with dining and lounge areas. At the raised deck area in front of the renovated amenity building, a BBQ Counter and a large table and chairs are propsed for dining and entertaining. The lower deck is furnished with a comfortable table, and chairs and outdoor lounge seating. A fire pit adds to the ambiance for a small group gathering area.

### Legend

- Renovated Amenity Building
- 2 Existing Trees
- 3 Proposed Accent Trees
- 4 Shrub Planting
- **5** BBQ Counter
- 6 Natural Gas Fire Pit
- Gathering Area
- 8 Steps with Handrails
- Seat Wall
- Retaining Wall
- 1 Dining Tables, Chairs and Movable Umbrellas
- Concrete Paving
- Deck

## Keymap





ima 960 atlantic avenue alameda, ca 94501

SB ARCHITECTS 1 Beach Street, Suite 101 San Francisco, CA 94133 415-673-8990

BKF Engineers 255 Shoreline Drive, Suite 200 Redwood City, CA 94065 650-482-6375

Maximus Real Estate Pi 575 Florida Street, Suite : San Francisco, CA 94110

# **Landscape Drawings** Sharon Green Apts.



Amenity Space A: "Backyard Garden" Plan

Street No. L-12



# Legend

- 1 Renovated Amenity Building
- 2 Existing Trees
- 3 Proposed Accent Trees
- 4 Shrub / Ground Covers
- **5** Festoon String Lights and Posts
- 6 Movable Umbrella
- BBQ Counter
- 8 Steps
- Seat Wall
- Retaining Wall
- 1 Lounge Furniture

ima

SB ARCHITECTS 1 Beach Street, Suite 101 San Francisco, CA 94133 415-673-8990

BKF Engineers 255 Shoreline Drive, Suite 200 Redwood City, CA 94065 650-482-6375

Maximus Real Estate Parts 575 Florida Street, Suite 150 San Francisco, CA 94110

# Sharon Green Apts. Landscape Drawings

Issued August 1, 2016

No.	Description	Date
_		-
_		

Amenity Space A:
"Backyard Garden" Site Section

Place 50% Schematic Design

State No. L-13













# 960 atlantic avenue alameda, ca 94501

510.353.3950 www.imadesign.com

SB ARCHITECTS 1 Beach Street, Suite 101 San Francisco, CA 94133 415-673-8990

BKF Engineers 255 Shoreline Drive, Suite 200 Redwood City, CA 94065 650-482-6375

BAMO 1000 Brannan Street, Suite 300 San Francisco, CA 94103 415-979-9880

Maximus Real Estate Partners 575 Florida Street, Suite 150 San Francisco, CA 94110

# Sharon Green Apts. Landscape Drawings 350 Sharon Park Dr. Menlo Park, CA

Issued August 1, 2016 50% Schematic Design

	Description	
$\blacksquare$		
$\vdash$		
$\overline{}$		
$\vdash$		_

Amenity Space A:
"Backyard Garden" Imagery

Place 50% Schematic Design



## **Description**

As the grand open space of this apartment community, this amenity area is designated for active recreation opportunities for the residents. The turf area with the large sycamore tree alle becomes a symbolic corridor and active lawn, playing host to numerous programmed and ad hoc events. The adjacent renovated amenity building serves as an anchor to the space, offering a place to host guests and food/drinks.

### Legend

- Decomposed Granite 'Plaza'
- 2 Removable Posts Sleeves for Game Nets
- 3 Movable Tables, Chairs and Umbrellas
- Private Backyards
- **5** Movable Bistro Tables and Chairs
- 6 Planting Buffer
- 7 Flowering Perennial Planting Area
- 8 Existing Trees
- 9 Existing Walkway to Sharon Road
- Renovated Amenity Building

### Keymap





ima

SB ARCHITECTS 1 Beach Street, Suite 101 San Francisco, CA 94133 415-673-8990

BKF Engineers 255 Shoreline Drive, Suite 200 Redwood City, CA 94065 650-482-6375

Maximus Real Estate Part 575 Florida Street, Suite 150 San Francisco, CA 94110

Sharon Green Apts. Landscape Drawings



Amenity Space B: "Open Space Recreation" Plan (North)

50% Schematic Design



## Legend

- 1 Turf Activity Area
- 2 Benches
- 3 Bocce Ball Court
- 4 Existing Trees
- S New Accent Trees
- 6 New Concrete Walk

# ima 960 atlantic avenue alameda, ca 94501

SB ARCHITECTS 1 Beach Street, Suite 101 San Francisco, CA 94133 415-673-8990

BKF Engineers 255 Shoreline Drive, Suite 200 Redwood City, CA 94065 650-482-6375

Maximus Real Estate Partri 575 Florida Street, Suite 150 San Francisco, CA 94110

# Sharon Green Apts. Landscape Drawings

# Keymap



0 5 10



Amenity Space B:
"Open Space Recreation" Plan (South)

Place 50% Schematic Design













# 960 atlantic avenue alameda, ca 94501

510.353.3950 www.imadesign.com

SB ARCHITECTS 1 Beach Street, Suite 101 San Francisco, CA 94133 415-673-8990

BKF Engineers 255 Shoreline Drive, Suite 200 Redwood City, CA 94065 650-482-6375

BAMO 1000 Brannan Street, Suite 300 San Francisco, CA 94103 415-979-9880

Maximus Real Estate Partners 575 Florida Street, Suite 150 San Francisco, CA 94110

# Sharon Green Apts. Landscape Drawings

350 Sharon Park Dr. Menlo Park, CA

Issued August 1, 2016 50% Schematic Design

No.	Description	Date
$\perp$		
$\vdash$		
-		
$\vdash$		
-		_
-		
-		

Amenity Space B:
"Open Space Recreation" Imagery

Fluse 50% Schematic Design



- Climbing Wall
- **Net Play Structure**
- Game Area (Turf)
- Renovated Amenity Building

- Tables and Chairs / Lounge Furniture
- Existing Trees
- 16 Rubber Play Surface Paving or DG
- Shrub and Groundcover

### Description


The playground is designed for several essential types of play and children's activities, as well as areas for seating and passive play. This amenity area is divided into two separate zones for different age groups; 2-5 and 5-12 year olds. Each area features various activities for their respective challenge and development abilities. The space is anchored by the renovated Amenity Building which will serve as the "Parent's Lounge".

### Legend

- 1 Play Mound (Rubber Surfaced)
- Swing
- Monkey Bar
- 4 Slide
- **5** Balance Rope
- 6 Stepping Platforms
- Patio with Table and Chairs
- 8 Balance Steps with Rope
- 9 Log and Rope

# Keymap





# ima

SB ARCHITECTS 1 Beach Street, Suite 101 San Francisco, CA 94133 415-673-8990


BKF Engineers 255 Shoreline Drive, Suite 200 Redwood City, CA 94065 650-482-6375

Maximus Real Estate Part 575 Florida Street, Suite 150 San Francisco, CA 94110

# **Landscape Drawings** Sharon Green Apts.



Amenity Space C: "Children's Adventure Park"













510.353.3950 www.imadesign.com

SB ARCHITECTS 1 Beach Street, Suite 101 San Francisco, CA 94133 415-673-8990

BKF Engineers 255 Shoreline Drive, Suite 200 Redwood City, CA 94065 650-482-6375

Maximus Real Estate Partners 575 Florida Street, Suite 150 San Francisco, CA 94110

# Sharon Green Apts. Landscape Drawings 350 Sharon Park Dr. Menlo Park, CA

Issued August 1, 2016 50% Schematic Design

No.	Description	Date
-		_
_		

Amenity Space C:
"Children's Adventure Park" Imagery

Fluse 50% Schematic Design

# **Essential Playground Activities**

Activity List	0-5 Years	5-12 Years	12-Adult
Climbing	•	•	
Balance	•	•	
Swing/Hanging	•	•	
Extra Challenges		•	
Game		•	• 0
Slide	•		
Touch/Feel (Sensory)	0		
Relax/Talk	0	0	0

● Active Play ○ Passive Play













Balance

# ima

SB ARCHITECTS 1 Beach Street, Suite 101 San Francisco, CA 94133 415-673-8990

Maximus Real Estate Partn 575 Florida Street, Suite 150 San Francisco, CA 94110

# Sharon Green Apts. Landscape Drawings

Issued August 1, 2016 50% Schematic Design

No.	Description	Date
_		
$\perp$		


Amenity Space C:
"Children's Adventure Park"

Key Activity Images Fluse 50% Schematic Design

















Swing/Hanging










Extra Challenges











Game

# 960 atlantic avenue alameda, ca 94501

510.353.3950 www.imadesign.com

SB ARCHITECTS 1 Beach Street, Suite 101 San Francisco, CA 94133 415-673-8990

# BKF Engineers 255 Shoreline Drive, Suite 200 Redwood City, CA 94065 650-482-6375

# BAMO 1000 Brannan Street, Suite 300 San Francisco, CA 94103 415-979-9880

Maximus Real Estate Partners 575 Florida Street, Suite 150 San Francisco, CA 94110

# Sharon Green Apts. Landscape Drawings 350 Sharon Park Dr. Menlo Park, CA

Issued August 1, 2016 50% Schematic Design

1	
_	
_	
_	

Amenity Space C:
"Children's Adventure Park" Key Activity Images

Fluse 50% Schematic Design




















Hide / Relax

Touch / Feel

# 960 atlantic avenue alameda, ca 94501

510.353.3950 www.imadesign.com

SB ARCHITECTS 1 Beach Street, Suite 101 San Francisco, CA 94133 415-673-8990

# BKF Engineers 255 Shoreline Drive, Suite 200 Redwood City, CA 94065 650-482-6375

# BAMO 1000 Brannan Street, Suite 300 San Francisco, CA 94103 415-979-9880

Maximus Real Estate Partners 575 Florida Street, Suite 150 San Francisco, CA 94110

# Sharon Green Apts. Landscape Drawings 350 Sharon Park Dr. Menlo Park, CA

Issued August 1, 2016 50% Schematic Design

No.	Description	Date
_		
_		
_		_

Amenity Space C: "Children's Adventure Park" Key Activity Images

Fluse 50% Schematic Design









Umbellularia californica - California Laurel



Quercus douglasii - Blue Oak

Quercus agrifolia

- Coast Live Oak



Arbutus menziesii Madrone



Cercis occidentalis - Western Redbud



Oak Woodland Clearing



- California Sycamore

### Trees

Acer spp. - Maple species Arbutus 'Marina' - Strawberry Tree Arbutus menziesii - Madrone Cedrus deodora - Deodor Cedar Cercis occidentalis - Western Redbud Cercocarpus betuloides - Mountain Mahogany Cinnamomum camphora - Camphor Tree Garrya elliptica - Silk Tassel Lophostemon confertus - Brisbane Box Lyonothamnus floribundus - Catalina Ironwood Magnolia spp. - Magnolia species

Quercus spp. - Oak species Pinus spp. - Pine species Platanus racemosa - California Sycamore Podcarpus spp. - Fern Pine species Prunus ilicifolia - Holly-leafed Cherry Sequoia sempervirens - Coast Redwood Tristania conferta - Brisbane Box Ulmus parvifolia - Evergreen Elm Umbellularia californica - California Laurel Zelkova serrata - Sawleaf Zelkova

SB ARCHITECTS

# Landscape Drawings Sharon Green Apts.

Issued August 1, 2016

No.	Description	Date
$\rightarrow$		
-		
$\rightarrow$		
-		
-		
$\rightarrow$		
-		

Proposed Plant Palettes &

Imagery - Trees



Heteromeles arbutifolia - Toyon




Rhus trilobata - Squaw Bush Sumac



Rhamnus californica - Coffeeberry



Fremontodendron californicur - California flannelbush



Myrica californica - Pacific Wax Myrtle



Arctostaphylos densiflora - Vine Hill Manzanita



Ceanothus spp. - California Lilac Fremontodendron californicum



Arctostaphylos spp. - Manzanita
Artemisia californica - California Sagebrush
Aspidistra elatior - Cast Iron Plant
Camellia spp. - Camellia varieties
Ceanothus spp. - California Lilac
Eriogonum heermannii - Heermans Buckwheat
Fremontodendron californicum - California flannelbush
Heteromeles arbutifolia - Toyon
Ligustrum j. 'Texanum' - Wax-leaf Privet
Liriope spp. - Lily Turf varieties

Myrica californica - Pacific Wax Myrtle
Pittosporum spp. - Pittosporum varieties
Rhamnus californica - Coffeeberry
Rhaphiolepis indica 'Clara' - Indian Hawthorne
Rhus trilobata - Squaw Bush Sumac
Ribes sanguineum - Pink-Flowered Currant
Rosa californica - California Wild Rose
Rosmarinus spp. - Rosemary varieties
Salvia spp. - Sage varieties
Trichstema lanatum - Woolly Blue Curls

ima

4501

510.353.3950 www.imadesian.com

Use of the plans and specifications contained breins shall be restricted to the original site for which they were prepared, policitation thereof is expressly limited to such use. Reproduction, publication, or resear by any method, in whole or in part, without the express without consent of in is prohibited. Title to said plans remain the soil property of irrs, visual content shall constitute or property of irrs, visual content shall constitute.

### Consultants

SB ARCHITECTS

1 Beach Street, Suite 101 San Francisco, CA 94133 415-673-8990

BKF Engineers 255 Shoreline Drive, Suite 20

0-482-6375

1000 Brannan Street, Suite 30 San Francisco, CA 94103

Maximus Real Estate Partners

575 Florida Street, Suite 150 San Francisco, CA 94110

# Sharon Green Apts. Landscape Drawings

Issued August 1, 2016

heet Title Project No. 2160

Proposed Plant Palettes & Imagery - Shrubs

Phase 50% Schematic Design



Zauschneria californica mexicana - California Fuschia



Iris longipetala - Long Petaled Iris



Lupinus spp. - Lupines



Baccharis pilularis - Coyote Bush



Polypodium californicum - California Polybody



Woodwardia fimbriata - Giant Chain Fern



Asclepias spp. - Milkweed



Juncus patens - Common Rush

### **Perennials**

Asclepias spp. - Milkweed
Corethrogyne filaginifolia - California Aster
Diplacus aurantiacus - Sticky monkey Flower
Iris spp. - Iris
Linum lewisii - Blue Flax
Lupinus spp. - Lupines
Monardella antonina - Butterfly Mint Bush
Penstemon centranthifolius - Scarlet Bugler
Romneya coulteri - Matilija Poppy
Salvia spathacea - Hummingbird Sage
Zauschneria californica mexicana - California Fuschia

### **Grasses & Groundcovers**

Baccharis pilularis - Coyote Bush
Carex tumulicola - Foothill Sedge
Carex praegracilis - Clustered Field Sedge
Elymus condensatus - Giant Wild Rye
Euonymus fortunei 'Coloratus' - Wintercreeper
Juncus patens - Common Rush
Muhlenbergia rigens - Deer Grass
Stipa coronata - Giant Needlegrass
Vinca minor - Dwarf Periwinkle
Trachelospermum jasminoides - Star Jasmine

### **Ferns**

Adiantum jordanii - California Maiden-Hair Polypodium californicum - California Polybody Woodwardia fimbriata - Giant Chain Fern Dryopteris arguta - Wood Fern into

E10 3E3 30E0

Use of the plans and specifications contained herein shall be restricted to the original side for which they were prepared, publication she not expressly limited to such use. Reproduction publication, or reuse by any method, in publication, or reuse by any method, in part, without the express written consent of in prohibited. Title to said plans remains the in

### Consultants

SB ARCHITECTS

1 Beach Street, Suite 101 San Francisco, CA 94133 415-673-8990

KF Engineers 55 Shoreline Drive, Suite 200 edwood City, CA 94065

0-482-6375

100 Brannan Street, Suite 300 an Francisco, CA 94103

Maximus Real Estate Partners 575 Florida Street, Suite 150

# Sharon Green Apts. Landscape Drawings

Issued August 1, 2016



est Title Project No. 2160

Proposed Plant Palettes & Imagery - Perennials & Groundcover

Phase 50% Schematic Desig



Lupinus spp. - Lupines



Carex praegracilis - Clustered Field Sedge



Elymus condensatus - Giant Wild Rye



- California Sagebrush



Carex tumulicola - Foothill Sedge



Muhlenbergia rigens - Deer Grass



Stipa pulchra - Purple Needlegrass

## Meadow (Hydroseed Mix)

Artemisia californica - California Sagebrush Eriogonum heermannii - Heermans Buckwheat Asclepias spp. - Milkweed Corethrogyne filaginifolia - California Aster Linum lewisii - Blue Flax Lupinus spp. - Lupines Monardella antonina - Butterfly Mint Bush Salvia spathacea - Hummingbird Sage Sisyrinchium bellum - Blue-eyed Grass **Annual Wildflower Varieties** Carex tumulicola - Foothill Sedge

Carex praegracilis - Clustered Field Sedge Festuca rubra - Red Fescue Juncus patens - Common Rush Muhlenbergia rigens - Deer Grass Stipa pulchra - Purple Needlegrass Elymus condensatus - Giant Wild Rye

SB ARCHITECTS 1 Beach Street, Suite 101 San Francisco, CA 94133 415-673-8990

# Sharon Green Apts. Landscape Drawings

Issued August 1, 2016

No.	Description	Date

Proposed Plant Palettes &

Imagery - Meadow

### **State Requirements**

Reduced landscape water usage is a statewide requirement as well as a significant component in the retrofit of the landscape design of this project.

Under the California Department of Natural Resources Title 23, Chapter 2.7. Model Water Efficient Landscape Ordinance (MWELO) & Governor Brown's Exec. Order No. B-29-15, Landscape should:

"...use water efficiently without waste by setting a Maximum Applied Water Allowance (MAWA) as an upper limit for water use and reduce water to the lowest practical amount"

A Maximum Applied Water Allowance, or MAWA, is the the maximum annual gallons per year of water allowed for a landscape area.

## **City Requirements**

The City of Menlo Park Water Efficient Landscape Code, Chapter 12.44, states:

### "12.44.020 Applicability

- (a) The provisions of this chapter shall apply to all of the following landscape proiects:
- (2) Rehabilitated landscape projects with an aggregate landscape area equal to or greater than one thousand (1,000) square feet requiring a building or landscape permit, plan check, or design review."

This project will seek to comply with the Code by means of the Water Budget Calculation Option for Nonresidential Projects, as outlined by the following Code Sections:

- "12.44.080 Water Budget Calculations"
- "12.44.090 Landscape Design Plan"
- "12.44.100 Irrigation Design Plan"

## **Retrofit Design Intent Statement**

The existing Water Use on-site will be calculated to create a Baseline for the current Maximum Applied Water Allowance (MAWA) based on the following:

- 1. The existing approximate square foot area of Hydrozone Landscape Areas (i.e. Turf, High-Water-Use Shrubs, Low-Water-Use Shrubs, etc.)
- 2. The existing Plant Factors from WUCOLS.
- 3. The exisiting Irrigation Controller Type.
- 4. The existing Irrigation Emitter Type (spray).
- 5. Any existing Special Landscape Areas.

### Conclusion

The Estimated Total Water Use (ETWU) for the proposed Retroft Design will be calculated using the equation outlined in the Water Ordinance "12.44.080" Water Budget Calculations" so that the sum of the ETWU calculated for all hydrozones will not exceed the MAWA.



SB ARCHITECTS

1 Beach Street, Suite 101 San Francisco, CA 94133 415-673-8990

BKF Engineers 255 Shoreline Drive, Suite 200 Redwood City, CA 94065 650-482-6375

Maximus Real Estate Pi 575 Florida Street, Suite San Francisco, CA 94110

# **Drawings** Sharon Green Apts. Landscape

Irrigation Retrofit Design Intent Statemen

# THIS PAGE INTENTIONALLY LEFT BLANK







JUN 0 7 2016

CITY OF MENLO PARK PLANNING

May 24, 2016

OFFICE: (888) 969-8733

WWW.ARBORWELL.COM

MAIN FAX: (510) 881-5208

Dave Ruth
Director of Capital Projects
Maximus Real Estate Partners
575 Florida Street, Suite 150
San Francisco, CA 94110

RE: Sharon Green Apartments, 350 Sharon Park Drive

# **Assignment**

It was requested that Arborwell re-evaluate the trees at Sharon Green Apartments and update the Tree Inventory report dated October 30, 2013.

The purpose of this re-evaluation is:

- To verify and update all data on the existing spreadsheet (See attached Tree Inventory Report dated 5/19/16)
- To re-evaluate trees previously recommended for removal and determine if any can be preserved.

# **Background**

The last Tree Inventory report was produced October 30, 2013. At that time, out of the 464 trees that were evaluated, 62 heritage trees were slated for removal. These trees were classified for removal due to health, structural, or location (proximity to structures and foundations) concerns. The majority of these trees were Monterey pine, Eucalyptus (various species) and Acacia and the inherent problems with these types of trees have been well documented.

The City's Arborist, Mr. Walt Fuji reviewed and supported all recommended removals and identified 12 additional trees that should be removed.

Soon thereafter, the prior property owner (BRE at that time) requested a re-evaluation of the recommended heritage removals, to see if there was any possibility to preserve some if extensive mitigation was performed. Each of the 62 proposed removals were re-evaluated and trees were identified that could be preserved if certain mitigation techniques were performed. At the end of this process of re-evaluation, 42 heritage trees were identified as requiring



OFFICE: (888) 969-8733

WWW.ARBORWELL.COM

MAIN FAX: (510) 881-5208

removal. On February 10, 2014 the Planning Commission recommended the City Council adopt a resolution approving the removal permits for the 42 heritage trees.

For some unknown reasons, BRE did not pursue the tree removals further and the condition of the trees has continued to deteriorate. In late 2015, Sharon Green was acquired by a new ownership group and Maximus assumed management of the property. Maximus requested Arborwell develop a comprehensive tree maintenance program for the property. Pursuant to this request, all the trees were measured and their condition evaluated for changes from the 2013 survey. Care recommendations from the previous survey were revised accordingly on the Tree Inventory.

## Tree Inventory

The attached updated Tree Inventory shows all heritage and non-heritage removals as well as the reason for the removal. Additionally, it identifies other trees recommended for removal but at the request of ownership have been re-evaluated and classified as trees that can be considered for preservation with certain mitigation performed to lessen the risk of failure or other damage.

Please note that in some cases the required mitigation techniques may be detrimental to the health of the tree. For example, in most cases the trees are noted for their poor structure which poses a danger of limb failure. The necessary mitigation in this case would include pruning the tree significantly to reduce risk to a satisfactory level. The required pruning may be such that it strains the health of the subject tree and can lead to future failure.

# **Heritage Trees recommended for removal**

This section discusses heritage tree removals. These were recommended for removal for one or more of the following reasons: 1) Poor health: meaning the trees health was poor enough to call into question its viability and or it safety. 2) Poor structure: meaning the limbs and or leaders in the tree are poorly attached and pose a significant risk to structures and or pedestrians. Or 3) poor location, meaning the trees close proximity to a structure is actively causing damage or poses a significant risk to do damage to the structure to which it is adjacent.

<u>Tree # 33 - 36 Monterey pine - Average 24.5" dbh building I</u>. Comments: These trees are grouped close to each other and the building. The health of these trees is poor as is exhibited by their thin canopies. Trees 34 & 36 have a significant lean over building I. Trees 33 & 35 lean towards Sharon Road. Each of these trees represents a risk to residents and pedestrians. Due to the fact that these trees are clustered together these trees and their canopies have grown



somewhat reliant on each other. Therefore it is advisable that they are all removed at the same time. No amount of mitigation can reduce the risk that these trees represent.

<u>Tree # 47 Evergreen pear - 20" dbh building L</u>. Comments: Tree has significant lean due to overcrowding, structure is fair but will never develop correctly due to close proximity to building and other trees.

<u>Tree # 48 Evergreen pear - 15" dbh building L</u>. Comments: Tree has significant lean due to overcrowding, structure is fair but will never develop correctly due to close proximity to building and other trees.

<u>Tree # 75 Red gum – 15"dbh building N.</u> Comments: Tree is in good health, but the structure of this tree is very poor, imbalanced and weighted towards the building, limbs are poorly attached and pose a risk of limb failure. Its close proximity to the building makes preservation impractical.

<u>Tree #'s 87 & 88 Monterey pine - 42" dbh building L</u>. Comments: These very large trees are located between buildings M and L. The root systems are exerting pressure on the foundation of building M and a retaining wall associated with building L which is exhibiting signs of strain. These canopies have long and dangerously heavy branches that extend over the roof line that pose a risk to residents. Due to the close proximity to the structures and the impact on foundations, mitigating these risks is not possible.

<u>Tree # 90 Tulip – 22" dbh building N</u>. Comments: Health of this tree is very poor. Branches are weakly attached with included bark. The trunk has significant decay and the tree is at high risk of failure.

<u>Tree # 95 & 96 Monterey pine – Average 30.5" dbh building P.</u> Comments: These very large trees are located between buildings P and N. The root systems are exerting pressure on the foundations of both buildings. The canopies have long and dangerously heavy branches that extend over the roof lines that pose a risk to residents. Due to the close proximity to the structures, mitigating these risks is not possible.

<u>Tree #177 Monterey pine - 30"dbh building F.</u> Comments: Base of tree is in contact with the building. Tree is still actively growing and serious damage to structure is likely. Additionally, the canopy is very heavy over the structure and the walkway. Due to the close proximity to the structures, mitigating these risks is not possible.

<u>Tree #206 Red Ironbark – 19" dbh building H.</u> Comments: Tree is in good health, however, it is located very close to the structure and root system is actively lifting adjacent patio. Limbs are poorly attached and pose a risk of limb failure. Due to the close proximity to the structures, mitigating these risks is not possible.

2337 AMERICAN AVE, HAYWARD, CA 94545
2949 EDISON WAY, REDWOOD CITY, CA 94063
1592 LITTLE ORCHARD STREET, SAN JOSE, CA 95110
3207 FITZGERALD ROAD, RANCHO CORDOVA, CA 95742
5601 EASTGATE DRIVE, SAN DIEGO, CA 92121
24551 RAYMOND WAY, SUITE 151, LAKE FOREST, CA 92630

OFFICE: (888) 969-8733 MAIN FAX: (510) 881-5208 WWW.ARBORWELL.COM



OFFICE: (888) 969-8733

WWW.ARBORWELL.COM

MAIN FAX: (510) 881-5208

<u>Tree #272 Sycamore – 15" dbh building I.</u> Comments: The health of this tree is fair however its structure is poor. Due to competition from neighboring trees and its proximity to the structure the canopy in unbalanced. Additionally, it is too close to the sidewalk as it has caused the hardscape to lift and crack over the years. Due to its poor location, mitigation measures are not recommended.

<u>Tree #285 Sycamore - 17" dbh building J and Parking Structure.</u> Comments: The health of this tree is fair however its structure is poor. Due to competition from neighboring trees and its proximity to the parking structure the canopy in unbalanced. Additionally, the base of the tree is within a few inches of the sidewalk and is causing lifting and cracking. Due to its poor location, mitigation measures are not recommended.

<u>Tree #'s 294 & 295 Acacia – Average 19" dbh building T</u>. Comments: Trees have extremely poor structure. Both trees have had multiple limb failures in the past and future limb failure is likely. They are located in a tight space between building T and the parking structure. The canopies are currently growing over both the building and the parking garage. The potential of limb failure combined with many potential targets (cars & residents) makes preservation of these trees impractical.

<u>Tree # 296 & 297 Red flowering qum - Average 19" dbh building T.</u> Comments: Trees have extremely poor structure. They are located in a tight space between building T and the parking structure. The canopies are currently growing over both the building and the parking garage. The potential of limb failure combined with many potential targets (cars & residents) makes preservation of these trees impractical.

<u>Tree # 298 Monterey pine – 28"dbh building T.</u> Comments: Tree has significant lean over parking structure and poses a significant risk of failure. Due to the close proximity to the parking structure and the nature of its lean, mitigating these risks is not possible. The potential of limb failure combined with many potential targets (cars & residents) makes preservation of this tree impractical.

<u>Tree # 315 Blue Oak – 27"dbh building L and Parking Structure.</u> Comments: Tree is in fair health however, due to competition and age the canopy is in decline. Tree is overcrowded and is growing into the parking structure. Has large decaying limb that poses a danger if it were to fail. Mitigation does not seem practical in this case due to the reasons mentioned above.

<u>Tree # 342 Monterey pine - 42"dbh building Q.</u> Comments: Tree is in fair health but has poor structure. Many limbs are very long and heavy and some have failed. One limb is currently sagging and resting on the roof. This limb should be removed. Due to its poor location and large size it is causing damage to the surrounding hardscape. Additionally, falling pine cones pose a threat to individuals using the pool area.

2337 AMERICAN AVE, HAYWARD, CA 94545
2949 EDISON WAY, REDWOOD CITY, CA 94063
1592 LITTLE ORCHARD STREET, SAN JOSE, CA 95110
3207 FITZGERALD ROAD, RANCHO CORDOVA, CA 95742
5601 EASTGATE DRIVE, SAN DIEGO, CA 92121
24551 RAYMOND WAY, SUITE 151, LAKE FOREST, CA 92630



<u>Tree #'s 350 – 355 Shamel ash – Average 20" dbh building R.</u> Comments: This group of 6 trees is located between building R and the walk way. The collective root systems of these trees are exerting pressure on the walkways as well as the foundation of the building. These trees are still actively growing and will do further damage. Additionally, the canopies have weak branch attachments and long heavy limbs that extend over the roof line. Due to the close proximity to the structures, mitigating the risks in these trees is not possible.

<u>Tree # 356 Monterey pine – 35" dbh building S.</u> Comments: This tree is much too large for its location and is in poor health. Canopy has many long heavy branches extending over the tennis court and building S. The risk of failure of these limbs poses a significant threat to pedestrians and those that utilize the court. Root system is heaving the side walk and is near utilities that could also be damaged.

<u>Tree # 373 Silver dollar eucalyptus – 16" dbh building T.</u> Comments: Tree is located close to building and is structured very poorly. Due to topping many years ago, the resulting re-growth is poorly attached as is at risk of failure. No amount of mitigation pruning can fix these defects.

<u>Tree # 391 Monterey pine - 32" dbh building A.</u> Comments: This tree is much too large for its location and its health is in decline. Tree has a history of branch failures and has lost one large main leader. Canopy has many long heavy branches extending over the building. The risk of failure of these limbs poses a significant threat to the residents, pedestrians and cars utilizing the parking spaces nearby.

<u>Tree # 402 Red Ironbark – 24" dbh building B.</u> Comments: Tree is in good health, however, it is located very close to the structure and is exerting pressure on the foundation. Limbs are poorly attached and pose a risk of limb failure both over the building and over the pedestrian area. Due to the close proximity to the structures, mitigating these risks is not possible.

<u>Tree # 405 Silver dollar eucalyptus – 32" dbh building E</u>. Comments: Tree is much too large for its location. Canopy is comprised of 3 main leaders all of which are appear to be very heavy and poorly attached. These leaders (or trunks) extend over the building and the pedestrian area. Due to the close proximity to the structure, mitigating these risks through pruning is not possible.

<u>Tree # 410 Monterey pine - 31" dbh between buildings E and D.</u> Comments: Tree's health seems to be exhibiting signs of decline. Tree has long heavy limbs that pose a threat to pedestrians and residents. The trees close proximity to the surrounding hardscape is problematic and is causing significant damage which in turn is causing trip hazards for pedestrians.



OFFICE: (888) 969-8733

WWW.ARBORWELL.COM

MAIN FAX: (510) 881-5208

<u>Tree # 411 Red ironbark - 27" dbh building C.</u> Comments: Tree is much too large for its location between buildings C and D and is very close to the structure. The canopy has 4 main leaders some of which are poorly attached and extend over the roof line of the adjacent structures. Additionally, many years ago the tree was topped and the resulting regrowth is also poorly attached and at risk of failure. Due to the close proximity to the structure, mitigating these risks through pruning is not possible.

<u>Tree # 412 Red ironbark – 31" dbh building C and laundry.</u> Comments: The structure of this tree is very poor in part due to the nature of the species and due to the fact that years ago the tree was topped and the resulting regrowth is poorly attached and poses a risk of failure. Despite a regular maintenance program, this tree has had multiple limb failures in the past 5 years.

<u>Tree #417 Silver dollar eucalyptus – 17" dbh building B.</u> Comments: Tree has very poor structure and an imbalanced canopy. Additionally, it is located too close to the building.

<u>Tree # 450 Monterey pine - 26" dbh building C.</u> Comments: This tree is located between building C and the parking garage. It has two main leaders that are attached at approximately 3' above grade. This branch attachment is severely included. With this condition, the leader that is growing over the parking garage is at significant risk of failure.

# Construction

It should be noted that this re-evaluation was done concurrently with preliminary design of a proposed renovation to all existing buildings on the property and installation of a new fire sprinkler system. Arborwell coordinated with the design team to ensure the fire sprinkler main line was routed so as to minimize the need for any tree removals

As a result of this close coordination, only three trees (all non-heritage) require removal to facilitate installation of the new fire sprinkler lines. These trees are identified as #'s 333, 418 and 445 on the attached Tree Inventory

# Conclusion

As a result of this re-evaluation and a reduction in the scope of the construction project, the number of trees being recommended for removal has been reduced from the 42 (proposed in 2013) to 39 now recommended for removal.



OFFICE: (888) 969-8733

WWW.ARBORWELL.COM

MAIN FAX: (510) 881-5208

Sharon Green has many mature trees that truly add value to the community of Menlo Park. Unfortunately, there are also a number of large trees that were unwisely planted too close to buildings many years ago that now are causing significant problems to the community and are threatening the safety of its residents. Over the last few years since the time of the last evaluation, there have been a number of limb failures due the poor condition and structure of many of the trees. One of the fundamental principles of arboriculture is having the right tree in the right location. Moving forward with the proposed removals and their replacements will help this site to have many more trees that are placed in such a way so that the community can truly benefit from them.

Respectfully submitted,

Jonathan Cardenas

Certified Arborist WC #4333A

925-260-3186



JUN 0 7 2016

#### Sharon Green Tree Inventory May 2016 Draft



CITY OF MENI O PARK TREE 2=Fair Removal Reason **BOTANICAL NAME COMMON NAME DBH** COMMENTS NO. 3=Good Recommendation (Structural/Health, Heritage Tree? 4=Very Good Construction) 5=Excellent Liquidambar 1 **Liquidambar** 12 3 Young tree; excellent health styraciflua Preserve Non-heritage Liquidambar 2 Liquidambar 17 3 Healthy tree; heavy on the ends styraciflua Preserve Heritage Liquidambar 3 Liquidambar 13 Tree falled; was removed 10/29/13 styraciflua 4 Prunus cerasifera Plum 8 Tree damaged by the failure of tree #3; was removed on 10/29/13 Liquidambar 5 Liquidambar 19 3 Good health and vigor styraciflua Preserve Heritage Removal recommended; tree has very poor structure and is a poor specimen. It is 6 Prunus cerasifera Plum 10 1 Remove Structural/Health showing signs of trunk and root decay. Recently lost major limb. Non-heritage **Liquidombar** 7 **Liquidambar** 14 3 Good health and vigor styraciflua Preserve Non-heritage Removal recommended; heavily weighted on one side, showing signs of uprooting and is 8 Pinus radiata Monterey Pine 24 2 causing damage to patio. Mitigation: If tree is to be retained, significantly reduce branch Mitigation Structural/Health Heritage end weight through pruning and monitor. Liquidambar 9 Liquidambar 14 3 Good health and vigor styraciflua Preserve Non-heritage Removal recommended; poor structure at very top and could lose large limbs at any Liquidombar 10 Liquidombar 15 2 time, is located near a walkway. Mitigation: If tree is retained, prune to reduce branch styrociflua Mitigation Heritage Structural/Health end weight and monitor. Liquidambar 11 Liquidambar 14 3 Healthy tree; many water sprouts styraciflua Preserve Non-heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	DBH	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
12	Prunus cerasifera	Plum	7	1	Removal recommended; this tree has very poor structure and is a poor specimen. It is showing signs of trunk and root decay.	Remove	Structural/Health	Non-heritage
13	Liquidambar styraciflua	Liquidambar	17	3	Heavy on the ends; good health	Preserve		Heritage
14	Liquidambar styraciflua	Liquidambar	12	3	Healthy with good structure	Preserve		Non-heritage
15	Liquidambar styraciflua	Liquidambar	11	3	Healthy young tree	Preserve		Non-heritage
16	Liquidambar styraciflua	Liquidambar	8	1	Removal recommended; overcrowded with severe trunk decay. If tree is retained, prune to reduce branch end weight and monitor. Mitigation: If tree is retained, prune to reduce branch end weight and monitor.	Mitigation	Structural/Health	Non-heritage
17	Quercus ilex	Holly Oak	13	2	Good health; thin canopy	Preserve		Non-heritage
18	Liquidambar styraciflua	Liquidambar	13		This tree was removed.			Non-heritage
19	Liquidambar styraciflua	Liquidambar	7	1	Removal recommended; overcrowded with severe root decay. Mitigation: If tree is retained, prune to reduce branch end weight and monitor.	Mitigation	Structural/Health	Non-heritage
20	Liquidambar styraciflua	Liquidambar	12	3	Poor structure; good health	Preserve		Non-heritage
21	Liquidambar styraciflua	Liquidambar	8	2	Removal recommended; may have root decay; poor structure and will be growing over the building in the future. Mitigation: If tree is retained, prune to reduce branch end weight and monitor.	Mitigation	Structural/Health	Non-heritage
22	Liquidambar styrociflua	Liquidambar	10	3	Heavy on one side - slightly imbalanced	Preserve		Non-heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	DBH	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
23	Sequoia sempervirens	Redwood	40	4	Good health	Preserve		Heritage
24	Sequola sempervirens	Redwood	19	4	Good health	Preserve		Heritage
25	Prunus cerasifera	Plum	13	2	Removal recommended; poor structure, losing branching	Remove	Structural/Health	Non-heritage
26	Sequola sempervirens	Redwood	26	4	Good health	Preserve		Heritage
27	Sequola sempervirens	Redwood	27	4	Good health	Preserve		Heritage
28	Sequoia sempervirens	Redwood	26	4	Good health	Preserve		Heritage
29	Sequola sempervirens	Redwood	25	4	Good health	Preserve		Hentage
30	Sequoia sempervirens	Redwood	20	4	Good health	Preserve		Heritage
31	Sequoia sempervirens	Redwood	15	4	Excellent health	Preserve		Heritage
32	Sequoia sempervirens	Redwood	19	4	Excellent health	Preserve		Heritage
33	Pinus radiata	Monterey Pine	24	2	Removal recommended; canopy looks thin; tree is in close proximity and leaning over building and may cause damage to foundation and pipes.	Remove	Structural/Health	Heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	DBH	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
34	Pinus radiata	Monterey Pine	25	2	Removal recommended; canopy looks thin; tree is in close proximity and leaning over building and may cause damage to foundation and pipes.	Remove	Structural/Health	Heritage
35	Pinus radiata	Monterey Pine	23	2	Removal recommended; tree is in close proximity to building and may cause damage to foundation and pipes.	Remove	Structural/Health	Heritage
36	Pinus radiata	Monterey Pine	26	2	Removal recommended; canopy looks thin; tree is in close proximity and leaning over building and may cause damage to foundation and pipes.	Remove	Structural/Health	Heritage
37	Pinus radiata	Monterey Pine	30	2	Removal recommended; tree is in close proximity to building and may cause damage to foundation and pipes. Mitigation: If tree is retained, prune to reduce branch end weight and monitor.	Mitigation	Structural/Health	Heritage
38	Ulmus parvifolia	Chinese Elm	18	3	Good health and vigor	Preserve		Heritage
39	Urlodendron tulipifera	Tulip Tree	9	3	Good health and vigor; heavy ended	Preserve		Non-heritage
40	Liriodendron tulipifera	Tulip Tree	18	3	Good health and vigor; heavy ended	Preserve		Heritage
41	Uriodendron tulipifera	Tulip Tree	11	3	Good health and vigor; heavy ended	Preserve		Non-heritage
42	Liriodendron tulipifera	Tulip Tree	13	3	Good health and vigor; heavy ended	Preserve		Non-heritage
43	Liriodendron tulipifera	Tulip Tree	15	3	Good health and vigor; heavy ended	Preserve		Heritage
44	Liriodendron tulipifero	Tulip Tree	14	3	Good health and vigor; heavy ended	Preserve		Non-heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	DBH	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
45	Urlodendron tulipifera	Tulip Tree	14	3	Good health and vigor; heavy ended	Preserve		Non-heritage
46	Liriodendron tulipifera	Tulip Tree	15	. 3	Good health, heavy ended	Preserve		Heritage
47	Pyrus kowakamii	Evergreen Pear	20	3	Removal recommended; has developed a heavy lean due to overcrowding, structure is fair but will never develop correctly due to close proximity to the building and other trees.	Remove	Structural/Health	Heritage
48	Pyrus kawakamii	Evergreen Pear	15	3	Removal recommended; has developed a heavy lean due to overcrowding, structure is fair but will never develop correctly due to close proximity to the building and other trees.	Remove	Structural/Health	Heritage
49	Pyrus kawakamii	Evergreen Pear	9	3	Removal recommended; has developed a heavy lean due to overcrowding, structure is fair but will never develop correctly due to close proximity to the building and other trees.	Remove	Structural/Health	Non-heritage
50	Pinus radiata	Monterey Pine	58	2	Deadwood	Preserve		Heritage
51	Liriodendron tulipifera	Tulip Tree	25	3	Good health, heavy ended	Preserve		Heritage
52	Liriodendron tulipifera	Tulip Tree	23	3	Good health, heavy ended	Preserve		Heritage
53	Quercus lobata	Valley Oak	13	1	Removal recommended; tree is in decline, has minimal branches and is overcrowded; removal will allow others to grow. Mitigation: If tree is retained, prune to to remove dead wood and monitor.	Mitigation	Structural/Health	Heritage
54	Quercus lobata	Valley Oak	42	3	Some branches have decay	Preserve		Heritage
55	Betula pendula	White Birch	8	5	Young tree; excellent health	Preserve		Non-heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	DBH	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
56	Betula pendula	White Birch	8	5	Young tree; excellent health	Preserve		Non-heritage
57	Lagerstroemia	Crape Myrtle	4.5	5	Young tree; excellent health	Preserve		Non-heritage
58	Lagerstroemia	Crape Myrtle	4.5	5	Young tree; excellent health	Preserve		Non-heritage
59	Sequola sempervirens	Redwood	17	5	Healthy tree	Preserve		Heritage
60	Sequoia sempervirens	Redwood	57	5	Low Branches	Preserve		Heritage
61	Sequoia sempervirens	Redwood	41	2	Removal recommended; tree has a hard lean and is showing signs of uprooting; is located near a walkway. Mitigation: If tree is retained, prune to reduce branch end weight, crown thin and monitor.	Mitigation	Structural/Health	Heritage
62	Malus floribunda	Crab Apple	4	3	Good health, poor structure	Preserve		Non-heritage
63	Alnus rhombifolia	Alder	22	3	Good health; heavy ended	Preserve		Heritage
64	Quercus labata	Valley Oak	19	3	Canopy looks thin	Preserve		Heritage
65	Quercus lobata	Valley Oak	27	3	Good health; heavy ended	Preserve		Heritage
66	Liriodendron tulipijera	Tulip Tree	13	3	Good health and vigor	Preserve		Non-heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	DBH	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
67	Liriodendron tulipifera	Tulip Tree	29	3	Good health and vigor	Preserve		Heritage
68	Liriodendron tulipifera	Tulip Tree	17	3	Good health and vigor	Preserve		Heritage
69	Liriodendron tulipifera	Tulip Tree	20	3	Good health and vigor	Preserve		Heritage
70	Malus floribunda	Crab Apple	10	3	Overgrown	Preserve		Non-heritage
71	Quercus lobata	Valley Oak	35	3	Good health	Preserve		Heritage
72	Quercus labata	Valley Oak	33	3	Good health	Preserve		Heritage
73	Quercus lobata	Valley Oak	24	3	Good health	Preserve		Heritage
74	Corymbia ficifolia	Red Gum	20	2	Removal recommended; good health, poor structure. Mitigation: Significantly reduce branch end weight through pruning and monitor.	Mitigation	Structural/Health	Heritage
75	Corymbia ficifolia	Red Gum	15	2	Removal recommended; good health, poor structure	Remove	Structural/Health	Heritage
76	Sequoia sempervirens	Redwood	32	4	Good health and structure	Preserve		Heritage
77	Sequoia sempervirens	Redwood	38	4	Good health and structure	Preserve		Heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	DBH	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
78	Sequoia sempervirens	Redwood	39	4	Good health and structure	Preserve		Heritage
79	Sequola sempervirens	Redwood	32	4	Good health and structure	Preserve		Heritage
80	Sequola sempervirens	Redwood	41	4	Good health and structure	Preserve		Heritage
81	Sequola sempervirens	Redwood	40	4	Good health and structure	Preserve		Heritage
82	Malus floribunda	Crab Apple	7	3	Poor structure	Preserve		Non-heritage
83	Malus floribunda	Crab Apple	6	3	Poor structure	Preserve		Non-heritage
84	. Sequaia sempervirens	Redwood	23	3	Good health and structure, but thin canopy	Preserve		Heritage
85	Sequola sempervirens	Redwood	25	3	Good health and structure, but thin canopy	Preserve		Heritage
86	Sequoia sempervirens	Redwood	25	3	Good health and structure, but thin canopy	Preserve		Heritage
87	Pinus radiata	Monterey Pine	42	2	Removal recommended; located very close to building and retaining wall and is causing damage to foundation and pipes. Canopy has dieback.	Remove	Structural/Health	Heritage
88	Pinus radiota	Monterey Pine	42	2	Removal recommended; located very close to building and retaining wall and is causing damage to foundation and pipes.	Remove	Structural/Health	Heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	DBH	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
89	Liriodendran tulipifera	Tulip Tree	17	3	Good health	Preserve		Heritage
90	Liriodendron tulipifera	Tulip Tree	22	1	Removal recommended; included bark and poor health; severe trunk decay, potential failure.	Remove	Structural/Health	Heritage
91	Liriodendron tulipifera	Tulip Tree	16	3	Good health; poor structure	Preserve		Heritage
92	Liriodendron tulipifera	Tulip Tree	21	3	Good health; poor structure	Preserve		Heritage
93	Liriodendron tulipifera	Tulip Tree	19	3	Good health; poor structure	Preserve		Heritage
94	Liriodendron tulipifera	Tulip Tree	17	3	Good health; poor structure	Preserve		Heritage
95	Pinus radiata	Monterey Pine	30	2	Removal recommended; too close to building and causing damage to foundation and pipes.	Remove	Structural/Health	Heritage
96	Pinus radiata	Monterey Pine	31	2	Removal recommended; too close to building and causing damage to foundation and pipes.	Remove	Structural/Health	Heritage
97	Eucalyptus spp.	Gum	25	1	Removal recommended; overgrown and poorly structured; limbs break often and is a danger to residents. Mitigation: Significantly reduce branch end weight through pruning and monitor.	Mitigation	Structural/Health	Heritage
98	Juniperus chinensis	Juniper	19	3	Good Health; canopy is dense	Preserve		Heritage
99	Uriodendron tulipifera	Tulip Tree	19	3	End weight is a problem, but otherwise healthy	Preserve		Heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	DBH	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
100	Liriodendron tulipifera	Tulip Tree	19	3	End weight is a problem, but otherwise healthy	Preserve		Heritage
101	Liriodendron tulipijera	Tulip Tree	22	3	End weight is a problem, but otherwise healthy	Preserve		Heritage
102	Liriodendron tulipifera	Tulip Tree	20	3	End weight is a problem, but otherwise healthy	Preserve		Heritage
103	Quercus lobata	Valley Oak	38	3	Good health and structure	Preserve		Heritage
104	Quercus lobata	Valley Oak	46	3	Good health and structure	Preserve		Heritage
105	Sequoia sempervirens	Redwood	31	3	Good health	Preserve		Heritage
106	Sequoia sempervirens	Redwood	28	4	Overcrowded	Preserve		Heritage
107	Sequoia sempervirens	Redwood	18	4	Overcrowded, multiple broken branches, cause unknown	Preserve		Heritage
108	Sequola sempervirens	Redwood	14	3	Canopy looks thin and the trunk has a gash	Preserve		Non-heritage
109	Arbutus marina	Arbutus	11	3	Healthy young tree, poor structure	Preserve		Non-heritage
110	Sequoia sempervirens	Redwood	11	3	Very thin canopy	Preserve		Non-heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	DBH	CONDITION  1=Poor  2=Fair  3=Good  4=Very Good  S=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
111	Pinus radiata	Monterey Pine	39	2	Poor vigor and lot of deadwood	Preserve		Heritage
112	Quercus alba	White Oak	26	3	Young tree; excellent health	Preserve		Heritage
113	Liriodendron tulipifera	Tulip Tree	19	2	Under stress	Preserve		Heritage
114	Sequola sempervirens	Redwood	12	3	Young healthy tree; potentially over watered	Preserve		Non-heritage
115	Sequola sempervirens	Redwood	18	3	Young healthy tree; potentially over watered	Preserve		Heritage
116	Liriodendron tulipifera	Tulip Tree	15	3	Stressed; potentially over watered	Preserve		Heritage
117	Malus floribunda	Crab Apple	6	3	Young tree; excellent health	Preserve		Non-heritage
118	Betula pendula	White Birch	9	3	Healthy vigor and structure	Preserve		Non-heritage
119	Betula pendula	White Birch	10	3	Heavy on the ends; good health	Preserve		Non-heritage
120	Pinus radiata	Monterey Pine	52	2	Removal recommended; very large tree close to parking garage; poor structure and potentially presents a risk of failure. Has lost large limbs. Mitigation: Significantly reduce branch end weight through pruning and monitor.	Mitigation	Structural/Health	Heritage
121	Pinus radiata	Monterey Pine	36	2	Canopy thinning	Preserve		Heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	DBH	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
122	Pinus radiata	Monterey Pine	30	3	Healthy tree. Leaning significantly towards the street.	Preserve		Heritage
123	Pinus radiata	Monterey Pine	30	2	Canopy thinning, with a large amount of deadwood.	Preserve		Heritage
124	E. sideroxylon	Red Ironbark	29	2	Removal recommended; very large tree close to buildings; poor structure and presents a risk of failure. Mitigation: Significantly reduce branch end weight through pruning and monitor.	Mitigation	Structural/Health	Heritage
125	Liriodendron tulipifera	Tulip Tree	20	3	Large healthy tree, heavy ended	Preserve		Heritage
126	Liriodendron tulipifera	Tulip Tree	17	3	Large healthy tree, heavy ended	Preserve		Heritage
127	Liriodendron tulipifera	Tulip Tree	19	3	Large healthy tree, heavy ended	Preserve		Heritage
128	Liriodendron tulipifero	Tulip Tree	14	2	Removal recommended; young tree; may be receiving to much water	Remove	Structural/Health	Non-heritage
129	Sequoia sempervirens	Redwood	17	4	Healthy trees, lots of crossing branches	Preserve		Heritage
130	Sequala sempervirens	Redwood	23	4	Healthy trees, lots of crossing branches	Preserve		Heritage
131	Sequala sempervirens	Redwood	13	4	Healthy trees, lots of crossing branches	Preserve		Non-heritage
132	Sequola sempervirens	Redwood	18	4	Healthy trees, lots of crossing branches	Preserve		Heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	DBH	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
133	Sequola sempervirens	Redwood	19	4	Healthy trees, lots of crossing branches	Preserve		Heritage
134	Sequoia sempervirens	Redwood	39	4	Healthy trees, lots of crossing branches	Preserve		Heritage
135	Sequoia sempervirens	Redwood	34	3	Healthy trees, being over watered	Preserve		Heritage
136	Sequoia sempervirens	Redwood	41	3	Healthy trees, being over watered	Preserve		Heritage
137	Cinnamomum camphora	Camphor	16	3	Young healthy tree	Preserve		Heritage
138	Sequola sempervirens	Redwood	37	3	Large healthy tree, good vigor and structure	Preserve		Heritage
139	Sequola sempervirens	Redwood	27	3	Large healthy tree, good vigor and structure	Preserve		Heritage
140	Betula pendulo	White Birch	12	3	Healthy tree, overcrowded by Redwood	Preserve		Non-heritage
141	Betula pendula	White Birch	11	3	Healthy tree, overcrowded by Redwood	Preserve		Non-heritage
142	Betula pendula	White Birch	13	3	Healthy tree, overcrowded by Redwood	Preserve		Non-heritage
143	Sequola sempervirens	Redwood	15	3	Young tree, seems to be browning due to overcrowding and possibly too much water	Preserve		Heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	DBH	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
144	Sequoia sempervirens	Redwood	15	3	Young tree, seems to be browning due to overcrowding and possibly too much water	Preserve		Heritage
145	Sequola sempervirens	Redwood	14	3	Young tree, seems to be browning due to overcrowding and possibly too much water	Preserve		Non-heritage
146	Sequoia sempervirens	Redwood	14	3	Young tree, seems to be browning due to overcrowding and possibly too much water	Preserve		Non-heritage
147	Sequoia sempervirens	Redwood	19	3	Young tree, seems to be browning due to overcrowding and possibly too much water	Preserve		Heritage
148	Sequoia sempervirens	Redwood	30	3	Young tree, seems to be browning due to overcrowding and possibly too much water	Preserve		Heritage
149	Sequola sempervirens	Redwood	6	2	Removal recommended; small; overcrowded and declining; should be removed to allow others to grow. Mitigation: Remove deadwood and monitor	Mitigation	Structural/Health	Non-heritage
150	Sequola sempervirens	Redwood	15	3	Good Health and vigor	Preserve		Heritage
151	Betula pendula	White Birch	10	3	Good Health and vigor	Preserve		Non-heritage
152	Betula pendula	White Birch	9	3	Overcrowded and poor structure	Preserve		Non-heritage
153	Betula pendula	White Birch	14	3	Overcrowded and poor structure	Preserve		Non-heritage
154	Sequala sempervirens	Redwood	14	3	Good health, vigor and structure	Preserve		Non-heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	DSH	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
155	Sequola sempervirens	Redwood	19	3	Good health, vigor and structure	Preserve		Heritage
156	Sequola sempervirens	Redwood	18	3	Good health, vigor and structure	Preserve		Heritage
157	Sequola sempervirens	Redwood	16	3	Good health, vigor and structure	Preserve		Heritage
158	Pinus radiata	Monterey Pine	24	2	Trees in decline; thin and heavy on ends	Preserve		Heritage
159	Pinus radiata	Monterey Pine	39	2	Trees in decline; thin and heavy on ends	Preserve		Heritage
160	Quercus ilex	Holly Oak	11	3	Canopy seems thin	Preserve		Non-heritage
161	Sequoia sempervirens	Redwood	24	2	Has included bark but good health	Preserve		Heritage
162	Sequaia sempervirens	Redwood	12	2	Tree is in decline	Preserve		Non-heritage
163	Sequoia sempervirens	Redwood	10	2	Tree is in decline	Preserve	`	Non-heritage
164	Quercus ilex	Hally Oak	9	2	Tree has lots of water spots, and is stressed	Preserve		Non-heritage
165	Pinus radiata	Monterey Pine	39	2	Removal recommended; tree has potential for failure and has lost large limbs in the past, poor structure indicates it will lose more. Mitigation: Significantly reduce branch end weight through pruning, remove large limb over Eastridge Ave. and monitor.	Mitigation	Structural/Health	Heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	рвн	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
166	Pinus radiata	Monterey Pine	36	2	Removal recommended; tree has large potential for failure and has lost large limbs in the past, poor structure indicates it will lose more. Mitigation: Significantly reduce branch end weight through pruning install cable and monitor.	Mitigation	Structural/Health	Heritage
167	Betula pendula	White Birch	6	3	Healthy young trees	Preserve		Non-heritage
168	Juniperus chinensis	Juniper	9	3	Healthy young trees	Preserve		Non-heritage
169	Uquidambar styraciflua	Liquidambar	10	3	Healthy young trees	Preserve		Non-heritage
170	Platanus hispanica	Sycamore	12	2	Removal recommended; health is fair, but overcrowded and one-sided. Poor structure dominated by neighboring pine.	Remove	Structural/Health	Non-heritage
171	Platanus hispanica	Sycamore	8	2	Healthy vigor and structure, but overcrowded and one-sided	Preserve		Non-heritage
172	Platanus hispanica	Sycamore	9	2	Healthy vigor and structure, but overcrowded and one-sided	Preserve		Non-heritage
173	Platanus hispanica	Sycamore	8	2	Healthy vigor and structure, but overcrowded and one-sided	Preserve		Non-heritage
174	Platanus hispanica	Sycamore	10	2	Healthy vigor and structure, but overcrowded and one-sided	Preserve		Non-heritage
175	Platanus hispanica	Sycamore	10	2	Healthy vigor and structure, but overcrowded and one-sided	Preserve		Non-heritage
176	Prunus cerasifera	Plum	6	3	Good health, but poor structure	Preserve		Non-heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	DBH	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
177	Pinus radiata	' Monterey Pine	30	2	Removal recommended; tree is growing directly against the building and is causing damage to foundation and pipes	Remove	Structural/Health	Heritage
178	Prunus cerasifera	Plum	6	3	Good health, but poor structure	Preserve		Non-heritage
179	Platanus hispanica	Sycamore	10	3	Very thin due to overcrowding	Preserve		Non-heritage
180	Platanus hispanica	Sycamore	12	3	Tree is overgrown due to crowding	Preserve		Non-heritage
181	Platanus hispanica	Sycamore	12	3	Tree is overgrown due to crowding	Preserve		Non-heritage
182	Platanus hispanica	Sycamore	12	3	Tree is overgrown due to crowding	Preserve		Non-heritage
183	Platanus hispanica	Sycamare	12	3	Tree is overgrown due to crowding	Preserve		Non-heritage
184	Platanus hispanica	Sycomore	10	3	Tree is overgrown due to crowding	Preserve		Non-heritage
185	Platanus hispanica	Sycamore	12	3	Tree is overgrown due to crowding	Preserve		Non-heritage
186	Cinnamomum camphora	Camphor	10	2.5	Fair health; canopy is thin	Preserve		Non-heritage
187	Cinnamomum comphora	Camphor	11	2.5	Fair health; canopy is thin	Preserve		Non-heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	DBH	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
188	Cinnamomum comphora	Camphor	12	2.5	Fair health; canopy is thin	Preserve		Non-heritage
189	Cinnamomum camphora	Camphor	13	2.5	Fair health; canopy is thin	Preserve		Non-heritage
190	Cinnamomum camphora	Camphor	12	2.5	Fair health; canopy is thin	Preserve		Non-heritage
191	Cinnamomum camphora	Camphor	11	2.5	Fair health; canopy is thin	Preserve		Non-heritage
192	Pinus radiata	Monterey Pine	32	2	Removal recommended; showing potential for failure; causing damage to walkways and posing a danger to residents. Mitigation: Significantly reduce branch end weight through pruning and monitor.	Mitigation	Structural/Health	Heritage
193	Pinus radiata	Monterey Pine	34	2	Removal recommended; showing potential for failure; causing damage to walkways and posing a danger to residents. Mitigation: Significantly reduce branch end weight through pruning and monitor.	Mitigation	Structural/Health	Heritage
194	Platanus hispanica	Sycamore	15	3	Healthy tree, but overcrowded	Preserve		Heritage
195	Platanus hispanica	Sycamore	15	3	Tree is overgrown and very one-sided	Preserve		Heritage
196	Platanus hispanica	Sycamare	13	3	Tree is overgrown and very one-sided	Preserve		Non-heritage
197	Platanus hispanica	Sycamore	15	3	Tree is overgrown and very one-sided	Preserve		Heritage
198	Platanus hispanica	Sycamore	16	3	Tree is overgrown and very one-sided	Preserve		Heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	DBH	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
199	Platanus hispanica	Sycamore	17	3	Tree is overgrown and very one-sided	Preserve		Heritage
200	Platanus hispanica	Sycamore	17	3	Tree is overgrown and very one-sided	Preserve		Heritage
201	Pittosporum eugenioides	Pittosporum	10	3	Lots of crossing and dead branches	Preserve		Non-heritage
202	Pittasporum eugenioides	Pittosporum	10	3	Lots of crossing and dead branches	Preserve		Non-heritage
203	Platanus hispanica	Sycomore	19	3	Removal recommended; high potential risk tree; significant lean, overgrown and is causing damage to pipes and foundation; very poor structure, with pruning risk can be somewhat mitigated	Mitigation	Structural/Health	Heritage
204	Platanus hispanica	Sycamore	18	3	Removal recommended; high potential risk tree; significant lean, overgrown and is causing damage to pipes and foundation; very poor structure, with pruning risk can be somewhat mitigated	Mitigation	Structural/Health	Heritage
205	E. sideroxylon	Red Ironbark	18	2	Removal recommended; high risk tree; significant lean, overgrown and may damage building; very poor structure and has had numerous limb fallures; located near walkways and poses a danger to residents. Mitigation: Significantly reduce branch end	Mitigation	Structural/Health	Heritage
206	E. sideroxylon	Red Ironbark	19	2	Removal recommended; high risk tree; significant lean, overgrown and may damage building; very poor structure and has had numerous limb failures; located near walkways and poses a danger to residents	Remove	Structural/Health	Heritage
207	Prunus caroliniana	Carolina Cherry	9	3	Healthy tree, but heavy ended	Preserve		Non-heritage
208	Cinnamomum comphora	Camphor	15	3	Healthy tree, but heavy ended	Preserve	e)	Heritage
209	Magnolia grandiflora	Magnolia	14	3	Good health, vigor and structure	Preserve		Non-heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	DBH	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
210	Prunus cerasifera	Plum	10	3	Good health, very poor structure	Preserve		Non-heritage
211	Magnolia grandiflora	Magnolia	9	1	Removal recommended; dead nearly dead	Remove	Structural/Health	Non-heritage
212	Magnolia grandiflora	Magnolia	10	1	Removal recommended; tree shows large amounts of die back; declining due to lack of light and overcrowding	Remove	Structural/Health	Non-heritage
213	Prunus cerasifera	Plum	10	3	Good health; but overcrowded and overgrown	Preserve		Non-heritage
214	Platanus hispanica	Sycamore	18	2	Removal recommended; tree is one-sided; overgrown and lifting the sidewalk; located too close to building and will soon cause damage to foundation. Mitigation: Prune away from building and monitor.	Mitigation	Structural/Health	Heritage
215	Platanus hispanica	Sycamore	14	2	Removal recommended; tree is one-sided; overgrown and lifting the sidewalk; located too close to building and will soon cause damage to foundation. Mitigation: Prune away from building and monitor.	Mitigation	Structural/Health	Non-heritage
216	Platanus hispanica	Sycomore	15	2	Removal recommended; tree is one-sided; overgrown and lifting the sidewalk; located too close to building and will soon cause damage to foundation. Mitigation: Prune away from building and monitor.	Mitigation	Structural/Health	Heritage
217	Platanus hispanica	Sycamore	11	2	Removal recommended; tree is one-sided; overgrown and lifting the sidewalk; located too close to building and will soon cause damage to foundation. Mitigation: Prune away from building and monitor.	Mitigation	Structural/Health	Non-heritage
218	Platanus hispanica	Sycamore	20	2	Removal recommended; tree is one-sided; overgrown and lifting the sidewalk; located too close to building and will soon cause damage to foundation. Mitigation: Prune away from building and monitor.	Mitigation	Structural/Health	Heritage
219	Prunus cerasifera	Plum	6	1	Removal recommended; poor structure, canopy looks poor; not aesthetically pleasing.	Remove	Structural/Health	Non-heritage
220	Prunus cerasifera	Plum	12	2	Healthy and vigorous; fair structure	Preserve		Non-heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	DBH	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
221	Ulmus parvifolia	Chinese Elm	10	3	Healthy and vigorous; but very heavy ends	Preserve		Non-heritage
222	Ulmus parvifolia	Chinese Elm	15	3	Health and vigorous; but very heavy ends	Preserve		Heritage
223	Ulmus parvifolia	Chinese Elm	11	3	Healthy and vigorous; but very heavy ends	Preserve		Non-heritage
224	Ulmus parvifolia	Chinese Elm	11	3	Healthy and vigorous; but very heavy ends	Preserve		Non-heritage
225	Platanus hispanica	Sycamare	21	3	Tree is healthy; but overgrown	Preserve		Heritage
226	Platanus hispanica	Sycamore	17	3	Tree is healthy; but overgrown	Preserve		Heritage
227	Platanus hispanica	Sycamore	8	1	Removal recommended; overcrowded, and poor structure; should be removed so others can grow. Mitigation: Prune and monitor,	Mitigation	Structural/Health	Non-heritage
228	Platanus hispanica	Sycamore	22	3	Healthy tree with long heavy branches	Preserve		Heritage
229	Platanus hispanica	Sycamore	21	3	Healthy tree with long heavy branches	Preserve		Heritage
230	Platanus hispanica	Sycamore	10	1	Removal recommended; overcrowded, and poor structure; should be removed so others can grow. Mitigation: Prune and monitor.	Mitigation	Structural/Health	Non-heritage
231	Platanus hispanica	Sycamore	16	3	Large healthy tree	Preserve		Heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	DBH	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
232	Platanus hispanica	Sycamore	19	3	Large healthy tree	Preserve		Heritage
233	Quercus lobata	Valley Oak	11	3	Young healthy tree; one-sided, due to overcrowding	Preserve		Heritage
234	Quercus lobata	Valley Oak	10	3	Young healthy tree; one-sided, due to overcrowding	Preserve		Heritage
235	Quercus lobata	Valley Oak	10	3	Young healthy tree; one-sided, due to overcrowding	Preserve		Heritage
236	Prunus caroliniana	Carolina Cherry	9	2	Removal recommended; overcrowded, and poor structure; should be removed so others can grow. Mitigation: Prune and monitor.	Mitigation	Structural/Health	Non-heritage
237	Liriodendron tulipifera	Tulip Tree	19	3	Healthy tree, but has heavy ends	Preserve		Heritage
238	Liriodendron tulipifera	Tulip Tree	15	3	Healthy tree, but has heavy ends	Preserve		Heritage
239	Liriodendron tulipifera	Tulip Tree	13	3	Healthy tree, but has heavy ends	Preserve		Non-heritage
240	Liriodendron tulipifera	Tulip Tree	13	2	Removal recommended; bad case of included bark; located too close to drain and is causing damage to pipes.	Remove	Structural/Health	Non-heritage
241	Betula pendula	White Birch	8		Tree died, remaved summer of 2013			
242	Betula pendula	White Birch	6		Tree died, removed summer of 2013			



TREE NO.	BOTANICAL NAME	COMMON NAME	DBH	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
243	Pyrus kawakamii	Evergreen Pear	9	3	Healthy, but overgrown	Preserve		Non-heritage
244	Pyrus kawakamii	Evergreen Pear	10	3	Healthy, but overgrown	Preserve		Non-heritage
245	Pyrus kawakamii	Evergreen Pear	8	3	Healthy, but overgrown	Preserve		Non-heritage
246	Ulmus parvifolia	Chinese Elm	17	3	Healthy tree, poor structure	Preserve		Heritage
247	Pyrus kawakamii	Evergreen Pear	10	3	Good health and vigor, poor structure	Preserve		Non-heritage
248	Pinus pinea	Stone Pine	32	4	Healthy tree, but heavy on ends	Preserve		Heritage
249	Pinus pinea	Stone Pine	29	4	Healthy tree, but heavy on ends	Preserve		Heritage
250	Liriodendron tulipifera	Tulip Tree	15	3	Healthy tree; good structure, ends are weighted	Preserve		Heritage
251	Liriodendron tulipifera	Tulip Tree	9	3	Healthy tree, good structure, ends are weighted	Preserve		Non-heritage
252	Liriodendron tulipifera	Tulip Tree	12	3	Healthy tree, good structure, ends are weighted	Preserve		Non-heritage
253	Liriodendron tulipifera	Tulip Tree	11	3	Healthy tree, good structure, ends are weighted	Preserve		Non-heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	D8H	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
254	Liriodendron tulipifera	Tulip Tree	10	2	Tree looks better since last evaluation, continue to monitor	Preserve		Non-heritage
255	Quercus lobata	Valley Oak	36	3	Old healthy tree; heavy on one side	Preserve		Heritage
256	Platanus hispanica	Sycamore	18	3	Large healthy tree; good structure	Preserve		Heritage
257	Platanus hispanica	Sycamore	9	2	Removal recommended; small overcrowded tree with poor structure; should be removed to allow others to grow. Mitigation: Prune and monitor.	Mitigation	Structural/Health	Non-heritage
258	Platanus hispanica	Sycamore	14	3	Healthy tree with long ends	Preserve		Non-heritage
259	Platanus hispanica	Sycamore	15	3	Healthy tree with long ends	Preserve		Heritage
260	Platanus hispanica	Sycamore	10	2	Removal recommended; small overcrowded tree with poor structure; should be removed to allow others to grow. Mitigation: Prune and monitor.	Mitigation	Structural/Health	Non-heritage
261	Platanus hispanica	Sycamore	7	2	Removal recommended; small overcrowded tree with poor structure; should be removed to allow others to grow. Mitigation: Prune and monitor.	Mitigation	Structural/Health	Non-heritage
262	Platanus hispanica	Sycamore	15	3	Healthy tree overcrowding others	Preserve		Heritage
263	Platanus hispanica	Sycamore	8	2	Removal recommended; small overcrowded tree with poor structure; should be removed to allow others to grow. Mitigation: Prune and monitor.	Mitigation	Structural/Health	Non-heritage
264	Pinus radiata	Monterey Pine	28	3	Removal recommended; located too close to building and is causing damage to the foundation, pipes, and walkways. Mitigation: Prune away from building and monitor.	Mitigation	Structural/Health	Heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	DBH	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
265	Platanus hispanica	Sycamore	20	3	Healthy tree one-sided due to crowding	Preserve		Heritage
266	Platanus hispanica	Sycamore	15	3	Healthy tree one-sided due to crowding	Preserve		Heritage
267	Platanus hispanica	Sycamore	15	3	Healthy tree one-sided due to crowding	Preserve		Heritage
268	Prunus cerasifera	Plum	8	3	Healthy tree one-sided due to crowding	Preserve		Non-heritage
269	Platanus hispanica	Sycamore	18	3	Removal recommended; showing signs of trunk decay; lifting sidewalk. Mitigation: Prune and monitor.	Mitigation	Structural/Health	Heritage
270	Platanus hispanica	Sycamore	14	3	Some trunk decay	Preserve		Non-heritage
271	Platanus hispanica	Sycamore	14	3	Large tree one-sided	Preserve		Non-heritage
272	Platanus hispanica	Sycamore	15	3	Large tree with one sided canopy. Is causing significant damage to hardscape.	Remove	Structural/Health	Heritage
273	Prunus cerasifera	Plum	8	3	Healthy tree, but overcrowded with poor structure	Preserve		Non-heritage
274	Platanus hispanica	Sycamore	15	3	Healthy tree, but overgrown	Preserve		Heritage
275	Platanus hispanica	Sycamore	13	3	Healthy tree, but overgrown	Preserve		Non-heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	рвн	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
276	Platanus hispanica	Sycamore	14	3	Healthy tree, but overgrown	Preserve		Non-heritage
277	Pinus radiata	Monterey Pine	31	2	Showing signs of decline	Preserve		Heritage
278	Sequoia sempervirens	Redwood	25	3	Young healthy tree; a little overcrowded	Preserve		Heritage
279	Sequaia sempervirens	Redwood	25	3	Young healthy tree; a little overcrowded	Preserve		Heritage
280	Sequala sempervirens	Redwood	22	3	Young healthy tree, a little overcrowded	Preserve		Heritage
281	Sequola sempervirens	Redwood	19	3	Young healthy tree, a little overcrowded	Preserve		Heritage
282	Sequola sempervirens	Redwood	20	3	Young healthy tree, a little overcrowded	Preserve		Heritage
283	Sequoia sempervirens	Redwood	18	3	Young healthy tree, a little overcrowded	Preserve		Heritage
284	Sequola sempervirens	Redwood	7	1	Removal recommended; small overcrowded tree; should be removed to allow others to grow. Mitigation: Purne and munitor.	Mitigation	Structural/Health	Non-heritage
285	Platanus hispanica	Sycamore	17	3	Tree health good, lifting & cracking sidewalk. Located too close to the hardscape for mitigation	Remove	Structural/Health	Heritage
286	Platanus hispanica	Sycamore	14	3	Healthy tree with good structure, but lifting sidewalk	Preserve		Non-heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	DBH	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
287	Platanus hispanica	Sycamore	15	3	Healthy tree with good structure, but lifting sidewalk	Preserve		Heritage
288	Platanus hisponico	Sycamore	11	3	Healthy tree with good structure, but lifting sidewalk	Preserve		Non-heritage
289	Platanus hispanica	Sycamore	15	3	Healthy tree with good structure, but lifting sidewalk	Preserve		Heritage
290	Prunus cerasifera	Plum	6	3	Young healthy tree, but overcrowded	Preserve		Non-heritage
291	Prunus cerasifera	Plum	10	3	Young healthy tree, but overcrowded	Preserve		Non-heritage
292	Quercus lobata	Valley Oak	29	3	Removal recommended; growing into parking garage and could cause damage to the structure. Mitigation: Prune away from structure to extent possible and monitor.	Mitigation	Structural/Health	Heritage
293	Platanus hispanica	Sycamore	13	2	Showing signs of die back	Preserve		Non-heritage
294	Acacia melanoxylon	Acacia	17	1	Removal recommended; tree has lost large limbs in the past and structure shows it will lose many more in the future; is a danger to residents.	Remove	Structural/Health	Heritage
295	Acacia melanoxylon	Acacia	21	1	Removal recommended; tree has lost large limbs in the past and structure shows it will lose many more in the future; is a danger to residents.	Remove	Structural/Health	Heritage
296	Eucalyptus spp.	Gum	22	2	Removal recommended; poor structure; tree has very few branches due to overcrowding and is too close to building; removal will allow for planting of a more suitable species.	Remove	Structural/Health	Heritage
297	Eucalyptus spp.	Gum	16	2	Removal recommended; poor structure; tree has very few branches due to overcrowding and is too close to building; removal will allow for planting of a more suitable species.	Remove	Structural/Health	Heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	DBH	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
298	Pinus radiata	Monterey Pine	28	2	Removal recommended; has a heavy lean over parking garage and is at risk of failure.	Remove	Structural/Health	Heritage
299	Pinus radiata	Monterey Pine	35	2	Removal recommended; has a bad lean and could fail; located far too close to drain and is causing damage to pipes and walkways. Mitigation: Significantly reduce branch end weight through pruning, take additional weight off of the West side and monitor.	Mitigation	Structural/Health	Heritage
300	Pinus radiata	Monterey Pine	22	2	Healthy tree, minor deadwood	Preserve		Heritage
301	Pinus radiata	Monterey Pine	26	2	Healthy tree, minor deadwood	Preserve		Heritage
302	Ulmus parvifolia	Chinese Elm	12	2	Removal recommended; healthy tree with a significant lean; showing signs of uprooting.  Mitigation: Prune to reduce end weight and monitor.	Mitigation	Structural/Health	Non-heritage
303	Ulmus parvifolia	Chinese Elm	14	3	Tree is healthy, but heavy ended	Preserve		Non-heritage
304	Betula pendula	White Birch	11	3	Healthy tree, a little overcrowded; needs structure	Preserve		Non-heritage
305	Betula pendula	White Birch	11	3	Healthy tree, a little overcrowded; needs structure	Preserve		Non-heritage
306	Betula pendula	White Birch	10	3	Healthy tree, a little overcrowded; needs structure	Preserve		Non-heritage
307	Betula pendula	White Birch	12	3	Healthy tree, a little overcrowded; needs structure	Preserve		Non-heritage
308	Platanus hispanica	Sycamore	18	3	Healthy tree; but overgrown on garage side	Preserve		Heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	DBH	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
309	Platanus hispanica	Sycamore	12	3	Healthy tree, but overgrown	Preserve		Non-heritage
310	Platanus hispanica	Sycamore	11	3	Healthy tree, but overgrown	Preserve		Non-heritage
311	Platanus hispanica	Sycamore	12	3	Healthy tree, but overgrown	Preserve		Non-heritage
312	Platanus hispanica	Sycamore	15	3	Healthy tree, but overgrown	Preserve		Heritage
313	Platanus hispanica	Sycamore	9	3	Healthy tree, but overgrown	Preserve		Non-heritage
314	Platanus hispanica	Sycamore	15	3	Healthy tree, but overgrown	Preserve		Heritage
315	Quercus douglassi	Blue Oak	27	2	Removal recommended; tree is overcrowded and growing into parking structure. Has large dead decaying limb.	Remove	Structural/Health	Heritage
316	Quercus douglassi	Blue Oak	33	2	Good health; but shows signs of trunk decay	Preserve		Heritage
317	Platanus hispanica	Sycamore	15	3	Large healthy tree, but overcrowded; ends of branches need reduction	Preserve		Heritage
318	Platanus hispanica	Sycomore	16	3	Large healthy tree, but overcrowded; ends of branches need reduction	Preserve		Heritage
319	Platanus hispanica	Sycamare	17	3	Large healthy tree, but overcrowded; ends of branches need reduction	Preserve		Heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	ОВН	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
320	Platanus hispanica	Sycamore	21	3	Large healthy tree, but overcrowded; ends of branches need reduction	Preserve		Heritage
321	Betula pendula	White Birch	5	2	Young tree, over crowded	Preserve		Non-heritage
322	Betula pendula	White Birch	10	3	Young tree, over crowded	Preserve		Non-heritage
323	Betula pendula	White Birch	6	3	Young tree, over crowded	Preserve		Non-heritage
324	E. polyanthemos	Silver Dollar Eucalyptus	20	2	Removal recommended; tree has been topped in the past, therefore attachments are poor; located over a walkway and is a danger to residents. Mitigation: Significantly reduce branch end weight through pruning and monitor.	Mitigation	Structural/Health	Heritage
325	E. polyanthemos	Silver Dollar Eucalyptus	22	2	Removal recommended; tree has been topped in the past, therefore attachments are poor; located over a walkway and is a danger to residents. Mitigation: Significantly reduce branch end weight through pruning and monitor.	Mitigation	Structural/Health	Heritage
326	Betula pendula	White Birch	9	3	Healthy tree, but overgrown	Preserve		Non-heritage
327	Betula pendula	White Birch	6	3	Healthy tree, but overgrown	Preserve		Non-heritage
328	Betula pendula	White Birch	6	3	Healthy tree, but overgrown	Preserve		Non-heritage
329	Betula pendula	White Birch	6	3	Healthy tree, but overgrown	Preserve		Non-heritage
330	Betula pendula	White Birch	7	3	Healthy tree; heavy ends	Preserve		Non-heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	рвн	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
331	Betula pendula	White Birch	10	3	Healthy tree; heavy ends	Preserve		Non-heritage
332	Betula pendula	White Birch	11	3	Healthy tree; heavy ends	Preserve		Non-heritage
333	Betula pendula	White Birch	12	3	Healthy tree; heavy ends	Remove	Construction	Non-heritage
334	E. polyanthemos	Silver Dollar Eucalyptus	10	2	Removal recommended; poorly structured tree, has been topped; recommend starting over with a new tree	Remove	Structural/Health	Non-heritage
335	Fraxinus uhdei	Shamel Ash	14	2	Thin tree due to building clearance	Preserve		Non-heritage
336	Fraxinus uhdei	Shomel Ash	12	1	Thin tree due to building clearance	Preserve		Non-heritage
337	Fraxinus uhdel	Shamel Ash	23	1	Thin tree due to building clearance	Preserve		Heritage
338	Fraxinus uhdei	Shamel Ash	20	1	Thin tree due to building clearance	Preserve		Heritage
339	Fraxinus uhdei	Shamel Ash	17	1	Thin tree due to building clearance	Preserve		Heritage
340	Fraxinus uhdei	Shamel Ash	17	1	Thin tree due to building clearance	Preserve		Heritage
341	Sequola sempervirens	Redwood	12	2	Young healthy tree	Preserve		Non-heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	D8H	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
342	Pinus radiata	Monterey Pine	42	2	Removal recommended; tree is in decline; too large for its location and is lifting sidewalk; falling cones pose a danger over the pool area. Broken branch resting on roof of bidg, Q	Remove	Structural/Health	Heritage
343	Pinus radiata	Monterey Pine	27	2	Removal recommended; tree is in decline; too large for its location and is lifting sidewalk; falling cones pose a danger over the pool area; too close to building and causing damage to foundation and pipes. Mitigation: Significantly reduce branch end	Mitigation	Structural/Health	Heritage
344	Pinus radiata	Monterey Pine	27	2	weight through reuning and monitor.  Removal recommended; tree is in decline; too large for its location and is lifting sidewalk; falling cones pose a danger over the pool area; too close to building and causing damage to foundation and pipes. Mitigation: Significantly reduce branch end weight through oruging and monitor.	Mitigation	Structural/Health	Heritage
345	Pyrus kawakamil	Evergreen Pear	7	3	Young healthy tree; needs end-weight reduction	Preserve		Non-heritage
346	Pyrus calleryana	Bradford Pear	8	3	Young healthy tree; needs end-weight reduction	Preserve		Non-heritage
347	Prunus cerasifera	Plum	4	3	Young healthy tree; needs end-weight reduction	Preserve		Non-heritage
348	Prunus cerasifera	Plum	4	3	Young healthy tree; needs end-weight reduction	Preserve		Non-heritage
349	Pyrus kawakamii	Evergreen Pear	9	3	Young healthy tree; needs end-weight reduction	Preserve		Non-heritage
350	Fraxinus uhdei	Shamel Ash	18	1	Removal recommended; Tree is heavy on the ends due to building clearance	Remove	Structural/Health	Heritage
351	Froxinus uhdei	Shamel Ash	28	1	Removal recommended; Tree is heavy on the ends due to building clearance	Remove	Structural/Health	Heritage
352	Fraxinus uhdel	Shamel Ash	15	1	Removal recommended; Tree is heavy on the ends due to building clearance	Remove	Structural/Health	Heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	DBH	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
353	Fraxinus uhdei	Shamel Ash	15	1	Removal recommended; Tree is heavy on the ends due to building clearance	Remove	Structural/Health	Heritage
354	Fraxinus uhdei	Shamel Ash	25	1	Removal recommended; Tree is heavy on the ends due to building clearance	Remove	Structural/Health	Heritage
355	Fraxinus uhdei	Shamel Ash	17	1	Removal recommended; Tree is heavy on the ends due to building clearance	Remove	Structural/Health	Heritage
356	Pinus radiata	Monterey Pine	35	2	Removal recommended; tree is much too large for its location and is damaging sidewalk, pipes, and garage; poses a danger to residents	Remove	Structural/Health	Heritage
357	Betula pendula	White Birch	7	3	Young healthy tree	Preserve		Non-heritage
358	Betula pendula	White Birch	10	3	Young healthy tree	Preserve		Non-heritage
359	Betula pendula	White Birch	9	3	Young healthy tree	Preserve		Non-heritage
360	Betula pendula	White Birch	11	3	Good health and vigor, however heavy on tops	Preserve		Non-heritage
361	Betula pendula	White Birch	11	3	Good health and vigor, however heavy on tops	Preserve	<del>-</del>	Non-heritage
362	Betula pendula	White Birch	9	3	Good health and vigor, however heavy on tops	Preserve		Non-heritage
363	Betula pendula	White Birch	6	3	Good health and vigor, however heavy on tops	Preserve		Non-heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	DBH	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
364	Betula pendula	White Birch	10	3	Good health and vigor, however heavy on tops	Preserve		Non-heritage
365	Quercus alba	White Oak	21	3	Healthy tree, however, looks thin	Preserve		Heritage
366	Quercus alba	White Oak	21	3	Removal recommended; healthy tree, however it is growing into the building and will soon damage it. Mitigation: Prune away from the building and monitor.	Mitigation	Structural/Health	Heritage
367	Betula pendula	White Birch	10	1	Removal recommended; Dead top, poor structure	Remove	Structural/Health	Non-heritage
368	Betula pendula	White Birch	9	3	Healthy tree, needs structure	Preserve		Non-heritage
369	Betula pendula	White Birch	6	2	Removal recommeded; Good health, but heavy competiton from stone pines, overcrowded.	Remove	Structural/Health	Non-heritage
370	Betula pendula	White Birch	9	2	Removal recommeded; Good health, but heavy competiton from stone pines, overcrowded.	Remove	Structural/Health	Non-heritage
371	Betula pendula	White Birch	8	2	Removal recommeded; Good health, but heavy competiton from stone pines, overcrowded.	Remove	Structural/Health	Non-heritage
372	E. polyanthemos	Silver Dollar Eucalyptus	14	2	Removal recommended; tree is a poor example of species, it has been topped in the past and is in a poor location; falling branches pose a danger to residents.	Remove	Structural/Health	Non-heritage
373	E. polyanthemos	Silver Dollar Eucalyptus	16	2	Removal recommended; tree is a poor example of species, it has been topped in the past and is in a poor location; falling branches pose a danger to residents.	Remove	Structural/Health	Heritage
374	Betula pendula	White Birch	5	2	Young tree in decline	Preserve		Non-heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	DBH	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
375	Betula pendula	White Birch	6	2	Removal recommended; Young tree in decline, very thin top	Remove	Structural/Health	Non-heritage
376	Betula pendula	White Birch	6		Tree died, removed summer of 2013			
377	Liriodendron tulipifera	Tulip Tree	10	3	Healthy tree with significant end-weight	Preserve		Non-heritage
378	Liriodendron tulipifera	Tulip Tree	11	3	Healthy tree with significant end-weight	Preserve		Non-heritage
379	Liriodendron tulipifera	Tulip Tree	10	3	Healthy tree with significant end-weight	Preserve		Non-heritage
380	Betula pendula	White Birch	12	3	Healthy tree with significant end-weight	Preserve		Non-heritage
381	Betula pendula	White Birch	6	3	Healthy tree with significant end-weight	Preserve		Non-heritage
382	Betula pendula	White Birch	5	3	Healthy tree with significant end-weight	Preserve		Non-heritage
383	Betula pendula	White Birch	9	3	Healthy tree with significant end-weight	Preserve		Non-heritage
384	Sequaia sempervirens	Redwood	31	4	Healthy, well-structured tree	Preserve		Heritage
385	Sequaia sempervirens	Redwood	21	4	Healthy, well-structured tree	Preserve		Heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	DBH	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
386	Sequoia sempervirens	Redwood	15	4	Healthy, well-structured tree	Preserve		Heritage
387	Sequola sempervirens	Redwood	28	4	Healthy, well-structured tree	Preserve		Heritage
388	Sequoia sempervirens	Redwood	15	4	Healthy, well-structured tree	Preserve		Heritage
389	Sequola sempervirens	Redwood	15	4	Healthy, well-structured tree	Preserve		Heritage
390	Betula pendula	White Birch	14	0	Removal recommended; tree is dead	Remove	Structural/Health	Non-heritage
391	Pinus radiata	Monterey Pine	32	2	Removal recommended, tree lost large leader and has a thin canopy	Remove	Structural/Health	Heritage
392	Platanus hispanica	Sycomore	10	3	Healthy tree, but overgrown and crowded	Preserve		Non-heritage
393	Platanus hispanica	Sycamore	9	3	Healthy tree, but overgrown and crowded	Preserve		Non-heritage
394	Platanus hispanica	Sycamore	9	3	Healthy tree, but overgrown and crowded	Preserve		Non-heritage
395	Platanus hispanica	Sycamore	14	3	Healthy tree, but overgrown and crowded	Preserve		Non-heritage
396	Platanus hispanica	Sycamore	13	3	Healthy tree, but overgrown and crowded	Preserve		Non-heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	DBH	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
397	Platanus hispanica	Sycamore	9	3	Healthy tree, but overgrown and crowded	Preserve		Non-heritage
398	Platanus hispanica	Sycamore	9	3	Healthy tree, but overgrown	Preserve		Non-heritage
399	Platanus hispanica	Sycamore	9	3	Healthy tree, but overgrown and crowded	Preserve		Non-heritage
400	Platanus hispanica	Sycamore	14	3	Healthy tree, but overgrown and crowded	Preserve		Non-heritage
401	Pittosporum eugenioides	Pittosporum	10	3	Good health; has good structure	Preserve		Non-heritage
402	E.sideroxylon	Red Ironbark	24	3	Removal recommended; much too large for its location; there is a risk of limb failure due to poor structure and is a danger to residents.	Remove	Structural/Health	Heritage
403	Ulmus parvifolia	Chinese Elm	13	3	Tree is overcrowded by the Euc. behind	Preserve		Non-heritage
404	Ulmus parvifolia	Chinese Elm	12	2	Removal recommended. Tree is overcrowded by adjacent Eucalyptus. Tree has a lean and poor structure	Remove	Structural/Health	Non-heritage
405	E. polyanthemos	Silver Dollar Eucalyptus	32	1	Removal recommended; much too large for its location; there is a risk of limb failure due to poor structure and is a danger to residents.	Remove	Structural/Health	Heritage
406	E. polyanthemos	Silver Dollar Eucalyptus	20	1	Removal recommended; overcrowded; tree has been topped therefore structure is poor and poses a danger to the patios below. Mitigation: Significantly reduce branch end weight through pruning and monitor.	Mitigation	Structural/Health	Heritage
407	E. polyanthemos	Silver Dollar Eucalyptus	16	1	Removal recommended; overcrowded; tree has been topped therefore structure is poor and poses a danger to the patios below. Mitigation: Significantly reduce branch end weight through pruning and monitor.	Mitigation	Structural/Health	Heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	ОВН	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
408	E. polyanthemos	Silver Dollar Eucalyptus	22	1	Removal recommended; overcrowded; tree has been topped therefore structure is poor and poses a danger to the patios below. Mitigation: Significantly reduce branch end weight through pruning and monitor.	Mitigation	Structural/Health	Heritage
409	E. polyanthemos	Silver Dollar Eucalyptus	17	1	Removal recommended; overcrowded; tree has been topped therefore structure is poor and poses a danger to the patios below. Mitigation: Significantly reduce branch end weight through pruning and monitor.	Mitigation	Structural/Health	Heritage
410	Pinus radiato	Monterey Pine	31	2	Removal recommended; tree appears to be in decline and is damaging walkway, creating a trip hazard.	Remove	Structural/Health	Heritage
411	E.sideroxylon	Red Ironbark	27	2	Removal recommended; much too large for its location; there is a risk of limb failure due to poor structure and is a danger to residents.	Remove	Structural/Health	Heritage
412	E.sideroxylon	Red Ironbark	31	2	Removal recommended; much too large for its location; there is a risk of limb failure due to poor structure and is a danger to residents.	Remove	Structural/Health	Heritage
413	Prunus cerasifera	Plum	9	3	Tree is healthy and young	Preserve		Non-heritage
414	Prunus cerasifera	Plum	10	3	Tree is healthy and young	Preserve		Non-heritage
415	Pittosporum eugeniaides	Pittosporum	10	3	Good health, but overgrown	Preserve		Non-heritage
416	Pittosporum eugenioides	Pittosporum	10	3	Good health, but overgrown	Preserve		Non-heritage
417	E. polyanthemas	Silver Dallar Eucalyptus	17	2	Removal recommended; tree is a poor example of species, it has been topped in the past and is in a poor location; falling branches pose a danger to residents.	Remove	Structural/Health	Heritage
418	Juniperus chinensis	Juniper	10	3	Good health and vigor, though it has a fair amount of deadwood	Remove	Construction	Non-heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	D8H	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
419	Quercus ilex	Hally Oak	11	4	Tree is one-sided due to overcrowding	Preserve		Non-heritage
420	Quercus agrifolia	Live Oak	19	2	Tree is overcrowded and thin	Preserve		Heritage
421	Quercus agrifolia	Live Oak	12	2	Tree is overcrowded and thin	Preserve		Heritage
422	Pinus radiota	Monterey Pine	33	2	Removal recommended; tree appears to be in decline and is damaging walkway, creating a trip hazard. Mitigation: Remove deadwood and monitor.	Mitigation	Structural/Health	Heritage
423	Pinus radiata	Monterey Pine	27	2	Tree is well pruned, but a little thin	Preserve		Heritage
424	Pinus radiata	Monterey Pine	29	2	Tree is well pruned, but a little thin	Preserve		Heritage
425	Platanus hispanica	Sycamore	10	3	Healthy tree, but branches too long	Preserve		Non-heritage
426	Platanus hispanica	Sycamore Sycamore	14	3	Healthy tree, but branches too long	Preserve		Non-heritage
427	Platanus hispanica	Sycamore	14	3	Healthy tree, but branches too long	Preserve		Non-heritage
428	Platanus hispanica	Sycamore	9	3	Healthy tree, but branches too long	Preserve		Non-heritage
429	Platanus hispanica	Sycamore	13	3	Healthy tree, but branches too long	Preserve		Non-heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	DBH	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
430	Platanus hispanica	Sycamore	11	3	Healthy tree, but branches too long	Preserve		Non-heritage
431	Platanus hispanica	Sycamore	9	3	Healthy tree, but branches too long	Preserve		Non-heritage
432	Platanus hispanica	Sycamore	14	3	Healthy tree, but branches too long	Preserve		Non-heritage
433	Platanus hispanica	Sycamore	18	3	Healthy tree, but branches too long	Preserve		Heritage
434	Platanus hispanica	Sycamore	16	3	Healthy tree, but branches too long	Preserve		Heritage
435	Platanus hispanica	Sycamore	14	3	Good health and vigor, in need of structure prune	Preserve		Non-heritage
436	Platanus hispanica	Sycamore	14	3	Good health and vigor, in need of structure prune	Preserve		Non-heritage
437	Platonus hispanica	Sycamare	12	3	Good health and vigor, in need of structure prune	Preserve		Non-heritage
438	Platanus hisponica	Sycamore	8	3	Good health and vigor, in need of structure prune	Preserve		Non-heritage
439	Populus tremula	Cottonwood Poplar	23	2	Removal reccommended; Large tree over park areas, heavy ends, large deadwood.  Mitigation: Remove deadwood and monitor.	Mitigation	Structural/Health	Heritage
440	Populus tremula	Cottonwood Poplar	26	2	Removal recommended; Large tree over park areas, heavy ends, large deadwood.  Mitigation: Remove deadwood and monitor.	Mitigation	Structural/Health	Heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	DBH	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
441	Populus tremula	Cottonwood Poplar	23	2	Removal recommended; Large tree over park areas, heavy ends, large deadwood.  Mitigation: Remove deadwood and monitor.	Mitigation	Structural/Health	Heritage
442	Malus floribunda	Crab Apple	8	3	Young, vigorous tree	Preserve		Non-heritage
443	Malus floribunda	Crab Apple	8	3	Young, vigorous tree	Preserve		Non-heritage
444	Malus floribunda	Crab Apple	6	3	Young, vigorous tree	Preserve		Non-heritage
445	Malus floribunda	Crab Apple	10	3	Young, vigorous tree	Remove	Construction	Non-heritage
446	Betula pendula	White Birch	6	3	Young, vigorous tree	Preserve		Non-heritage
447	Betula pendula	White Birch	6	3	Young, vigorous tree	Preserve		Non-heritage
448	Betula pendula	White Birch	10	3	Young, vigorous tree	Preserve		Non-heritage
449	Pinus radiata	Monterey Pine	31	3	Included bark, fair health	Preserve		Heritage
450	Pinus radiata	Monterey Pine	26	1	Removal recommended; tree is declining and has severely included bark on the limb over garage.	Remove	Structural/Health	Heritage
451	Platanus hispanica	Sycamore	12	3	Good health, but needs to be pruned for structure	Preserve		Non-heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	<b>DBH</b>	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
452	Platanus hispanica	Sycamore	11	3	Good health, but needs to be pruned for structure	Preserve		Non-heritage
453	Platanus hispanica	Sycamore	11	3	Good health, but needs to be pruned for structure	Preserve		Non-heritage
454	Platanus hispanica	Sycamore	10	3	Good health, but needs to be pruned for structure	Preserve		Non-heritage
455	Platanus hispanica	Sycamore	10	3	Good health, but needs to be pruned for structure	Preserve		Non-heritage
456	Platanus hispanica	Sycamare	11	3	Good health, but needs to be pruned for structure	Preserve		Non-heritage
457	Platanus hispanica	Sycamore	11	3	Good health, but needs to be pruned for structure	Preserve		Non-heritage
458	Platanus hispanica	Sycomore	13	3	Good health, but needs to be pruned for structure	Preserve		Non-heritage
459	Platanus hispanica	Sycamore	16	3	Good health, but needs to be pruned for structure	Preserve		Heritage
460	Pinus radiota	Manterey Pine	36	3	Good health and vigor, evidence of red turpetine beetle activity	Preserve		Heritage
461	Prunus caroliniana	Carolina Cherry	6	3	Good health and vigor; however, tree has lean	Preserve		Non-heritage
462	Quercus ilex	Holly Oak	10	3	Good health and vigor; however, tree has lean	Preserve		Non-heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	DBH	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
463	Quercus lobata	Valley Oak	33	3	Appears healthy, but is showing some trunk decay	Preserve		Heritage
464	Pinus radiata	Monterey Pine	27	2	Removal recommended; located much too close to building and is causing damage to foundation and pipes. Mitigation: Reduce end weight and monitor.	Mitigation	Structural/Health	Heritage



July 12, 2016

Mr. Christian Bonner, City Arborist City of Menlo Park Public Works Department 701 Laurel Street Menlo Park, CA 94025

Re: HTR2016-00137 – 350 Sharon Park Drive

Contract Arborist Review of Heritage Tree Removal Permit Application

Dear Mr. Bonner:

As requested, Fujiitrees Consulting, LLC (FTC) completed this review of the Heritage Tree Removal Permit Application and Arborist Report submitted on behalf of the Sharon Green Apartments located at 350 Sharon Park Drive in the City of Menlo Park.

This review would be equivalent to the work typically conducted by the City Arborist for development or similar projects.

Following is the FTC Assignment limited to the Heritage Tree Removal Permit Application HTR2016-00137 (See attached, Appendix 3):

- 1. Verify the locations of the 39 trees proposed for removal on the subject property.
- 2. Verify the tree species identified in the report with the corresponding tree tag number on the property.
- 3. Verify the condition of 39 trees described in the report with the existing trees on the property.
- 4. Confirm that sound reasons are stated in the Report for the removal of the 39 subject trees.
- 5. Recommend for the approval or the denial of the application to remove any one or all of the subject Heritage trees.

#### **Background**

In 2013, the Project Arborist for Sharon Green Apartments, Arborwell, completed a tree survey of 464 trees located on the property. The 39 trees that are the subjects of this Heritage Tree Removal Permit Application were part of that 2013 tree inventory.

Walt Fujii, RCA®
Consulting Arborist
415.699.6269

24701 Broadmore Ave Hayward, CA 94544

walt@fujiitrees.com fujiitrees.com

ASCA Registered Consulting Arborist® No. 402
ISA Certified Arborist No. WE2257A
ISA-TRAQ Tree Risk Assessment Qualification
CA DPR Qualified Applicator Certificate No. 82521
APA Certified Aesthetic Pruner No. 011





FTC conducted a peer review of that tree inventory and presented its findings in a report submitted to the Planning Department in October, 2013.

### Field Verification Methodology

On July 5, 2016, Fujiitrees Consulting, LLC (FTC) visited the Sharon Green Apartments property to complete a field verification of the 39 Heritage trees that are the subjects of Heritage Tree Removal Permit Application HTR2016-00137.

Two documents were recently provided to FTC for use in this peer review; the Arborist Report dated May 2016 (Appendix 4) and the Sharon Green Tree Inventory Dated May 2016 Draft (Appendix 5).

In addition, an electronic version of the tree inventory prepared by Arborwell dated September 4, 2013 was updated and modified for use in this report. (Table 1- Tree Status Chart) An electronic version of Sheet L0.01 - Heritage Tree Demolition Plan dated June, 2013, was also updated for use in this report as the Tree Location Map (Appendix 2).

To assist the Reader of this report, photographs of each subject tree were assembled in the Photograph Exhibit (Appendix 1). These photographs present a perspective of each tree; not all defects or conditions were readily visible.

Trunk diameters were for the most part visually verified. A diameter tape was used to measure a sampling of trunk diameters to calibrate visual approximations.

#### Assignment

- 1. Verify the locations of the 39 trees proposed for removal on the subject property.
  - 1.1. A total of 39 trees with tags were located by FTC.
  - 1.2. Each tree plotted in red on the Tree Location Map (Appendix 2) was field verified for approximate location.
- 2. Verify the tree species identified in the report with the corresponding tree tag number on the property.
  - The tree species identified in the Arborist Report and Tree Inventory were confirmed in the field by FTC.
- 3. Verify the condition of 39 trees described in the report with the existing trees on the property. The condition of trees described in the Arborist Report and the Tree Inventory were confirmed in the field by FTC.



- 4. Confirm that sound reasons were stated in the Report for the removal of 39 subject trees. The reasons for removing each subject tree as stated in the Arborist Report and the Tree Inventory were determined to be sound and to be in the best interest for residents, guests and staff of the Sharon Green Apartments.
- 5. Recommend for the approval or the denial of the application to remove any one or all of the subject Heritage trees.

It is the opinion of FTC that the Heritage tree removals are consistent with MPMC Section 13.24.040 Permits and recommends approval of HTR2016-00137.

These subsections of MPMC Section 13.24.040 Permits are germane to the application:

- The condition of the tree or trees with respect to disease, danger of falling, proximity to existing
  or proposed structures and interferences with utility services;
   The subject trees displayed poor structure, low vigor and/or presented a significant risk
  of harm to residents, guests and staff that cannot be reasonably mitigated.
- 2) The long-term value of the species under consideration, particularly lifespan and growth rate; Certain subject tree species such as the ash, Monterey pine, certain eucalypts spp. and black acacia are not considered suitable for use in the urban landscape or in highly confined spaces. The trees proposed for removal are mature or over mature. (Appendix 1- Photograph Exhibit)

society of Consulting

Consulting A

Submittal of this report completes the FTC peer review assignment

Respectfully,

FUJIITREES CONSULTING, LLC

Walt Fujii, RCA® Manager

Attachments: Table 1 – Tree Status Chart

Appendix 1 – Photograph Exhibit

Appendix 2 – Tree Location Map

Appendix 3 – HTR2016-0137\_350 Sharon Park Drive

Appendix 4 – Arborwell Arborist Report May 2016

Appendix 5 – Arborwell Sharon Green Tree Inventory Draft May 2016

Certificate of Performance

Terms and Conditions



**Table 1**Tree Status Chart <sup>1</sup> **Sharon Green Apartments**Menlo Park, California

TREE NO.	BOTANICAL NAME	COMMON NAME	DBH	COND	PROJECT ARBORIST'S COMMENTS AND RECOMMENDATIONS <sup>2</sup>	HERITAGE TREE	CONTRACT ARBORIST OBSERVATIONS <sup>3</sup>	CONTRACT ARBORIST RECOMMENDS APPROVAL <sup>3</sup>
33	Pinus radiata	Monterey Pine	24	2	Removal recommended; canopy looks thin; tree is in close proximity and leaning over building and may cause damage to foundation and pipes.	Yes	Very poor structure	Yes
34	Pinus radiata	Monterey Pine	25	2	Removal recommended; canopy looks thin; tree is in close proximity and leaning over building and may cause damage to foundation and pipes.	Yes	Very poor structure	Yes
35	Pinus radiata	Monterey Pine	23	2	Removal recommended; tree is in close proximity to building and may cause damage to foundation and pipes.	Yes	Very poor structure, wrong location.	Yes
36	Pinus radiata	Monterey Pine	26	2	Removal recommended; canopy looks thin; tree is in close proximity and leaning over building and may cause damage to foundation and pipes.	Yes	Very poor structure	Yes
47	Pyrus kawakamii	Evergreen Pear	20	3	Removal recommended; has developed a heavy lean due to overcrowding, structure is fair but will never develop correctly due to close proximity to the building and other trees.	Yes	Please replace flag. Very poor structure, removal is long overdue.	Yes
48	Pyrus kawakamii	Evergreen Pear	15	3	Removal recommended; has developed a heavy lean due to overcrowding, structure is fair but will never develop correctly due to close proximity to the building and other trees.	Yes	Please replace flag. Very poor structure.	Yes
75	Corymbia ficifolia	Red Gum	15	2	Removal recommended; Good health, poor structure	Yes	Trunk lean toward building.	Yes
87	Pinus radiata	Monterey Pine	42	2	Removal recommended; located very close to building and retaining wall and is causing damage to foundation and pipes. Canopy has dieback.	Yes	Very poor structure	Yes
88	Pinus radiata	Monterey Pine	42	2	Removal recommended; located very close to building and retaining wall and is causing damage to foundation and pipes.	Yes	Very poor structure, visible hardscape damage.	Yes

**Table 1**Tree Status Chart <sup>1</sup> **Sharon Green Apartments**Menlo Park, California

TREE NO.	BOTANICAL NAME	COMMON NAME	DBH	COND	PROJECT ARBORIST'S COMMENTS AND RECOMMENDATIONS <sup>2</sup>	HERITAGE TREE	CONTRACT ARBORIST OBSERVATIONS <sup>3</sup>	CONTRACT ARBORIST RECOMMENDS APPROVAL <sup>3</sup>
90	Liriodendron tulipifera	Tulip Tree	22	1	Removal recommended; included bark and poor health; severe trunk decay, potential failure.	Yes	Very poor structure.	Yes
95	Pinus radiata	Monterey Pine	30	2	Removal recommended; too close to building and causing damage to foundation and pipes.	Yes	Very poor structure, wrong location.	Yes
96	Pinus radiata	Monterey Pine	31	2	Removal recommended; too close to building and causing damage to foundation and pipes.	Yes	Very poor structure, wrong location.	Yes
177	Pinus radiata	Monterey Pine	30	2	Removal recommended; tree is growing directly against the building and is causing damage to foundation and pipes	Yes	Please replace flag. Poor structure, in contact with building.	Yes
206	E. sideroxylon	Red Ironbark	19	2	Removal recommended; high risk tree; significant lean, overgrown and may damage building; very poor structure and has had numerous limb failures; located near walkways and pose a danger to residents	Yes	Please replace flag. A large neglected tree with very poor structure	Yes
272	Platanus hispanica	Sycamore	15	3	Large tree with one sided canopy, is causing significant damage to hardscape.	Yes	Uplifted sidewalk created puddling, trip hazard.	Yes
285	Platanus hispanica	Sycamore	17	3	Tree health good, lifting & cracking sidewalk. Located to close to the hardscape for mitigation.	Yes	Walkway was observed to be displaced by roots.	Yes
294	Acacia melanoxylon	Acacia	17	1	Removal recommended; tree has lost large limbs in the past and structure shows it will lose many more in the future; is a danger to residents.	Yes	Very poor structure, wrong location.	Yes
295	Acacia melanoxylon	Acacia	21	1	Removal recommended; tree has lost large limbs in the past and structure shows it will lose many more in the future; is a danger to residents.	Yes	Very poor structure, wrong location.	Yes

**Table 1**Tree Status Chart <sup>1</sup> **Sharon Green Apartments**Menlo Park, California

TREE NO.	BOTANICAL NAME	COMMON NAME	DBH	COND	PROJECT ARBORIST'S COMMENTS AND RECOMMENDATIONS <sup>2</sup>	HERITAGE TREE	CONTRACT ARBORIST OBSERVATIONS <sup>3</sup>	CONTRACT ARBORIST RECOMMENDS APPROVAL <sup>3</sup>
296	Eucalyptus spp.	Red Flowering Gum	22	2	Removal recommended; poor structure; tree has very few branches due to overcrowding and is too close to building; removal will allow for planting of a more suitable species.	Yes	Very poor structure. Planting area is confined, possible room for a small tree.	Yes
297	Eucalyptus spp.	Red Flowering Gum	16	2	Removal recommended; poor structure; tree has very few branches due to overcrowding and is too close to building; removal will allow for planting of a more suitable species.	Yes	Very poor structure. Planting area is confined, possible room for a small tree.	Yes
298	Pinus radiata	Monterey Pine	28	2	Removal recommended; has a heavy lean over parking garage and is at risk of failure.	Yes	Severe lean over parking structure.	Yes
315	Quercus lobata	Valley Oak	27	2	Removal recommended; tree is overcrowded and growing into parking structure. Has large dead decaying limb.	Yes	Wrong location.	Yes
342	Pinus radiata	Monterey Pine	42	2	Removal recommended; tree is in decline; too large for its location and is lifting sidewalk; falling cones pose a danger over the pool area. Broken branch resting on roof of Bldg. Q.	Yes	Very poor structure and displaying low vigor.	Yes
350	Fraxinus uhdei	Shamel Ash	18	1	Removal recommended; Tree is heavy on the ends due to building clearance	Yes	Please replace flag. Very poor structure, wrong location.	Yes
351	Fraxinus uhdei	Shamel Ash	28	1	Removal recommended; Tree is heavy on the ends due to building clearance	Yes	Please replace flag. Very poor structure, wrong location.	Yes
352	Fraxinus uhdei	Shamel Ash	15	1	Removal recommended; Tree is heavy on the ends due to building clearance	Yes	Please replace flag. Very poor structure, wrong location.	Yes
353	Fraxinus uhdei	Shamel Ash	15	1	Removal recommended; Tree is heavy on the ends due to building clearance	Yes	Please replace flag. Very poor structure, wrong location.	Yes

**Table 1**Tree Status Chart <sup>1</sup> **Sharon Green Apartments**Menlo Park, California

TREE NO.	BOTANICAL NAME	COMMON NAME	DBH	COND	PROJECT ARBORIST'S COMMENTS AND RECOMMENDATIONS <sup>2</sup>	HERITAGE TREE	CONTRACT ARBORIST OBSERVATIONS <sup>3</sup>	CONTRACT ARBORIST RECOMMENDS APPROVAL <sup>3</sup>
354	Fraxinus uhdei	Shamel Ash	25	1	Removal recommended; Tree is heavy on the ends due to building clearance	Yes	Please replace flag. Very poor structure, wrong location.	Yes
355	Fraxinus uhdei	Shamel Ash	17	1	Removal recommended; Tree is heavy on the ends due to building clearance	Yes	Please replace flag. Very poor structure, wrong location.	Yes
356	Pinus radiata	Monterey Pine	35	2	Removal recommended; tree is much too large for its location and is damaging sidewalk, pipes, and garage; poses a danger to residents	Yes	Very poor structure and displaying low vigor.	Yes
373	E. polyanthemos	Silver Dollar Eucalyptus	16	2	Removal recommended; tree is a poor example of species, it has been topped in the past and is in a poor location; falling branches pose a danger to residents.	Yes	Very poor structure, phototropic trunk lean, wrong location.	Yes
391	Pinus radiata	Monterey Pine	32	2	Removal recommended, tree lost large leader and has thin canopy.	Yes	Low vigor displayed with a very poor structure.	Yes
402	E.sideroxylon	Red Ironbark	24	3	Removal recommended; much too large for its location; there is a risk of limb failure due to poor structure and is a danger to residents.	Yes	In overall poor condition, wrong location	Yes
405	E. polyanthemos	Silver Dollar Eucalyptus	32	1	Removal recommended; much too large for its location; there is a risk of limb failure due to poor structure and is a danger to residents.	Yes	Please replace flag. Trunk displays structural defects.	Yes
410	Pinus radiata	Monterey Pine	31	2	Removal recommended; tree appears to be in decline and is damaging walkway, creating a trip hazard.	Yes	Very poor structure, wrong location.	Yes
411	E.sideroxylon	Red Ironbark	27	2	Removal recommended; much too large for its location; there is a risk of limb failure due to poor structure and is a danger to residents.	Yes	Please replace flag. Very poor structure.	Yes
412	E.sideroxylon	Red Ironbark	31	2	Removal recommended; much too large for its location; there is a risk of limb failure due to poor structure and is a danger to residents.	Yes	Please replace flag. Very poor structure	Yes

**Table 1**Tree Status Chart <sup>1</sup> **Sharon Green Apartments**Menlo Park, California

TREE NO.	BOTANICAL NAME	COMMON NAME	DBH	COND	PROJECT ARBORIST'S COMMENTS AND RECOMMENDATIONS <sup>2</sup>	HERITAGE TREE	CONTRACT ARBORIST OBSERVATIONS <sup>3</sup>	CONTRACT ARBORIST RECOMMENDS APPROVAL 3
417	E. polyanthemos	Silver Dollar Eucalyptus	17	3	Removal recommended; tree is a poor example of species, it has been topped in the past and is in a poor location; falling branches pose a danger to residents.		Very poor structure, wrong location.	Yes
450	Pinus radiata	Monterey Pine	26	1	Removal recommended; tree is declining and has severely included bark on the limb over garage.	Yes	Please replace flag. Observed to be in steep decline.	Yes

<sup>1/</sup> Tree Status chart is modified from the 2013 Sharon Green Tree Inventory prepared by Arborwell.

<sup>2/</sup> Project Arborist's comments and recommendations from 2013 were updated based on 2016 Sharon Green Tree Inventory prepared by Arborwell.

<sup>3/</sup> Contract Arborist's observations and recommendations by Fujiitrees Consulting, LLC





Trees 33, 34, 35 and 36

Tree 47





Tree 48 Tree 75





Trees 87 and 88 Tree 90





Trees 95 and 96 Tree 177






Tree 206 Tree 272





Tree 285 Trees 294 and 295






Trees 296 and 297 Tree 298





Tree 315 Tree 342





Trees 350, 351 and 352

Trees 353 and 354





Tree 355 Tree 356





Tree 373 Tree 391





Tree 402 Tree 405





Tree 410 Tree 411






Tree 412 Tree 417



Tree 450



# **Heritage Tree Removal Permit Application**

This application must be submitted with the Arborist Report Form Please submit completed forms to: 701 Laurel St., Menlo Park, CA 94025

Application No. <u>H7R2016</u> — 00137 Purpose of application: Removal Pruning of more than 25% Permit Fee: \$135.00 (each tree, up to 3 trees); \$90 each additional tree (separate forms required for each tree) PLEASE PRINT CLEARLY Site Address: 350 Sharon Park Drive Name of Applicant: Dave Ruth of Maximus Real Estate Partners Phone 415 795 7052 FAX Mailing Address: 575 Florida Street, Suite 150 San Francisco, CA 94110 Email: druth@maximusrepartners.com Location on property: Throughout property Type of Tree: Various Reasons for Request: Subject trees are either too close to the structure, exhibiting poor health or are structurally unsound. Please see arborist report. IF TREE IS DEAD or DAMAGING STRUCTURE PLEASE ATTACH PHOTOS DEMONSTRATING CONDITION. ARE YOU CONSIDERING ANY CONSTRUCTION ON YOUR PROPERTY IN THE NEXT 12 MONTHS? Yes No □ If we please submit additional information describing what type of construction is planned and a site plan

	what type of constituction is planned and a site plan.							
from the City as indicated below.	ess and until the applicant has received final permission							
<ul> <li>The signed permit approval form must be on site and performed.</li> </ul>	•							
<ul> <li>A suitable replacement tree, 15 gallon size or larger with a mature height of 40 feet or more, is to be installed in the time frame indicated below.</li> </ul>								
I (we) hereby agree to hold the City harmless from all costs and expenses, including attorney's fees, incurred by the City, including but not limited to, all cost in the City's defense of its actions in any proceeding brought in any State or Federal Court challenging the City's actions with respect to the proposed tree removal.								
Incomplete applications will not be processed.								
Signature of property owner authorizing access and inspection of tree in his/her absence.  Date: 6/7/16								
PLEASE DO NOT WRITE BELOW THIS LINE								
PERMIT APPROVED	PERMIT DENIED							
TIMING OF REMOVAL  ☐ Upon receipt of this approved permit ☐ After applying for a Building Permit for associated construction	TIMING OF REPLANTING  ☐ Within 30 days of Heritage Tree removal ☐ Prior to final building inspection of associated construction							
Staff Signature:	Date:							
Print name and title:								
	FIC   18							

## **Arborist Form**

Please complete one form for each tree. Mark each tree with colored ribbon or tape prior to our inspection.

Site Address: 350 Sharon Park	( Drive						
ARBORIST INFORMATION: Name of Certified Arborist Jon	athan Cardenas	er >					
ISA or ASCA number: WC-4333	Menlo Park Busine	ess License number: 58352					
Company: Arborwell							
Address: 2337 American Ave. Hayward, CA 94545							
Phone: <u>888-969-8733</u>	FAX:	Email: jcardenas@arborwell.com					
TREE INFORMATION:							
Date of Inspection: 5/19/16	<u> </u>						
Common Name:	Botanical Na	ıme:					
Location of Tree:Height of Tree:							
Diameter of tree at 54 inches abo	ove natural grade:						
Circumference of tree at 54 inche							
Condition of Tree:  See attach	ed spreadsheet for reco	mmended removals					
	83						
		1 1999 300 300					
If recommending removal or p	runing, please list <u>all</u> r	easons:					
Suggested Replacement Tree:							
Signature of Arborist:	MM	Date:6/2/16					

### CITY OF MENLO PARK/FINANCE DEP 650-330-6704

# 117536 9:24 AM 06/09/16

EMP: MARY JANE

701

HERITAGE TREE PERMIT

3 @ 135.00 405.0M

701

HERITAGE TREE PERMIT 36 E 90.00

3.240.00

350 SHARON PARK

PO BY : SUTRO

MANAGEMENT GROUP LTD

SUB-TOTAL: \$3,645.00

SALES TAX :

. 09

TOTAL > \$3,645.00

PAY TYPE : CHECK

RECEIVED : 3,645.00

CHANGE :

. AA

701 LAUREL STREET MENLO PARK, CA. 94025 THANK YOU FOR YOUR BUSINESS





JUN 0 7 2016

CITY OF MENLO PARK PLANNING

May 24, 2016

Dave Ruth
Director of Capital Projects
Maximus Real Estate Partners
575 Florida Street, Suite 150
San Francisco, CA 94110

RE: Sharon Green Apartments, 350 Sharon Park Drive

### Assignment

It was requested that Arborwell re-evaluate the trees at Sharon Green Apartments and update the Tree Inventory report dated October 30, 2013.

The purpose of this re-evaluation is:

- To verify and update all data on the existing spreadsheet (See attached Tree Inventory Report dated 5/19/16)
- To re-evaluate trees previously recommended for removal and determine if any can be preserved.

## **Background**

The last Tree Inventory report was produced October 30, 2013. At that time, out of the 464 trees that were evaluated, 62 heritage trees were slated for removal. These trees were classified for removal due to health, structural, or location (proximity to structures and foundations) concerns. The majority of these trees were Monterey pine, Eucalyptus (various species) and Acacia and the inherent problems with these types of trees have been well documented.

The City's Arborist, Mr. Walt Fuji reviewed and supported all recommended removals and identified 12 additional trees that should be removed.

Soon thereafter, the prior property owner (BRE at that time) requested a re-evaluation of the recommended heritage removals, to see if there was any possibility to preserve some if extensive mitigation was performed. Each of the 62 proposed removals were re-evaluated and trees were identified that could be preserved if certain mitigation techniques were performed. At the end of this process of re-evaluation, 42 heritage trees were identified as requiring



removal. On February 10, 2014 the Planning Commission recommended the City Council adopt a resolution approving the removal permits for the 42 heritage trees.

For some unknown reasons, BRE did not pursue the tree removals further and the condition of the trees has continued to deteriorate. In late 2015, Sharon Green was acquired by a new ownership group and Maximus assumed management of the property. Maximus requested Arborwell develop a comprehensive tree maintenance program for the property. Pursuant to this request, all the trees were measured and their condition evaluated for changes from the 2013 survey. Care recommendations from the previous survey were revised accordingly on the Tree Inventory.

### Tree Inventory

The attached updated Tree Inventory shows all heritage and non-heritage removals as well as the reason for the removal. Additionally, it identifies other trees recommended for removal but at the request of ownership have been re-evaluated and classified as trees that can be considered for preservation with certain mitigation performed to lessen the risk of failure or other damage.

Please note that in some cases the required mitigation techniques may be detrimental to the health of the tree. For example, in most cases the trees are noted for their poor structure which poses a danger of limb failure. The necessary mitigation in this case would include pruning the tree significantly to reduce risk to a satisfactory level. The required pruning may be such that it strains the health of the subject tree and can lead to future failure.

### **Heritage Trees recommended for removal**

This section discusses heritage tree removals. These were recommended for removal for one or more of the following reasons: 1) Poor health: meaning the trees health was poor enough to call into question its viability and or it safety. 2) Poor structure: meaning the limbs and or leaders in the tree are poorly attached and pose a significant risk to structures and or pedestrians. Or 3) poor location, meaning the trees close proximity to a structure is actively causing damage or poses a significant risk to do damage to the structure to which it is adjacent.

<u>Tree # 33 - 36 Monterey pine - Average 24.5" dbh building I</u>. Comments: These trees are grouped close to each other and the building. The health of these trees is poor as is exhibited by their thin canopies. Trees 34 & 36 have a significant lean over building I. Trees 33 & 35 lean towards Sharon Road. Each of these trees represents a risk to residents and pedestrians. Due to the fact that these trees are clustered together these trees and their canopies have grown



somewhat reliant on each other. Therefore it is advisable that they are all removed at the same time. No amount of mitigation can reduce the risk that these trees represent.

<u>Tree # 47 Evergreen pear - 20" dbh building L.</u> Comments: Tree has significant lean due to overcrowding, structure is fair but will never develop correctly due to close proximity to building and other trees.

<u>Tree # 48 Evergreen pear - 15" dbh building L</u>. Comments: Tree has significant lean due to overcrowding, structure is fair but will never develop correctly due to close proximity to building and other trees.

<u>Tree # 75 Red gum – 15"dbh building N.</u> Comments: Tree is in good health, but the structure of this tree is very poor, imbalanced and weighted towards the building, limbs are poorly attached and pose a risk of limb failure. Its close proximity to the building makes preservation impractical.

<u>Tree #'s 87 & 88 Monterey pine - 42" dbh building L</u>. Comments: These very large trees are located between buildings M and L. The root systems are exerting pressure on the foundation of building M and a retaining wall associated with building L which is exhibiting signs of strain. These canopies have long and dangerously heavy branches that extend over the roof line that pose a risk to residents. Due to the close proximity to the structures and the impact on foundations, mitigating these risks is not possible.

<u>Tree # 90 Tulip – 22" dbh building N</u>. Comments: Health of this tree is very poor. Branches are weakly attached with included bark. The trunk has significant decay and the tree is at high risk of failure.

<u>Tree # 95 & 96 Monterey pine – Average 30.5" dbh building P.</u> Comments: These very large trees are located between buildings P and N. The root systems are exerting pressure on the foundations of both buildings. The canopies have long and dangerously heavy branches that extend over the roof lines that pose a risk to residents. Due to the close proximity to the structures, mitigating these risks is not possible.

<u>Tree #177 Monterey pine - 30"dbh building F.</u> Comments: Base of tree is in contact with the building. Tree is still actively growing and serious damage to structure is likely. Additionally, the canopy is very heavy over the structure and the walkway. Due to the close proximity to the structures, mitigating these risks is not possible.

<u>Tree #206 Red Ironbark – 19" dbh building H.</u> Comments: Tree is in good health, however, it is located very close to the structure and root system is actively lifting adjacent patio. Limbs are poorly attached and pose a risk of limb failure. Due to the close proximity to the structures, mitigating these risks is not possible.

2337 AMERICAN AVE, HAYWARD, CA 94545
2949 EDISON WAY, REDWOOD CITY, CA 94063
1592 LITTLE ORCHARD STREET, SAN JOSE, CA 95110
3207 FITZGERALD ROAD, RANCHO CORDOVA, CA 95742
5601 EASTGATE DRIVE, SAN DIEGO, CA 92121
24551 RAYMOND WAY, SUITE 151, LAKE FOREST, CA 92630

OFFICE: (888) 969-8733
MAIN FAX: (510) 881-5208
WWW.ARBORWELL.COM
FTC | 23



<u>Tree #272 Sycamore – 15" dbh building I.</u> Comments: The health of this tree is fair however its structure is poor. Due to competition from neighboring trees and its proximity to the structure the canopy in unbalanced. Additionally, it is too close to the sidewalk as it has caused the hardscape to lift and crack over the years. Due to its poor location, mitigation measures are not recommended.

<u>Tree #285 Sycamore - 17" dbh building J and Parking Structure.</u> Comments: The health of this tree is fair however its structure is poor. Due to competition from neighboring trees and its proximity to the parking structure the canopy in unbalanced. Additionally, the base of the tree is within a few inches of the sidewalk and is causing lifting and cracking. Due to its poor location, mitigation measures are not recommended.

<u>Tree #'s 294 & 295 Acacia – Average 19" dbh building T</u>. Comments: Trees have extremely poor structure. Both trees have had multiple limb failures in the past and future limb failure is likely. They are located in a tight space between building T and the parking structure. The canopies are currently growing over both the building and the parking garage. The potential of limb failure combined with many potential targets (cars & residents) makes preservation of these trees impractical.

<u>Tree # 296 & 297 Red flowering qum - Average 19" dbh building T.</u> Comments: Trees have extremely poor structure. They are located in a tight space between building T and the parking structure. The canopies are currently growing over both the building and the parking garage. The potential of limb failure combined with many potential targets (cars & residents) makes preservation of these trees impractical.

<u>Tree # 298 Monterey pine – 28"dbh building T.</u> Comments: Tree has significant lean over parking structure and poses a significant risk of failure. Due to the close proximity to the parking structure and the nature of its lean, mitigating these risks is not possible. The potential of limb failure combined with many potential targets (cars & residents) makes preservation of this tree impractical.

<u>Tree # 315 Blue Oak – 27"dbh building L and Parking Structure.</u> Comments: Tree is in fair health however, due to competition and age the canopy is in decline. Tree is overcrowded and is growing into the parking structure. Has large decaying limb that poses a danger if it were to fail. Mitigation does not seem practical in this case due to the reasons mentioned above.

<u>Tree # 342 Monterey pine - 42"dbh building Q.</u> Comments: Tree is in fair health but has poor structure. Many limbs are very long and heavy and some have failed. One limb is currently sagging and resting on the roof. This limb should be removed. Due to its poor location and large size it is causing damage to the surrounding hardscape. Additionally, falling pine cones pose a threat to individuals using the pool area.

2337 AMERICAN AVE, HAYWARD, CA 94545
2949 EDISON WAY, REDWOOD CITY, CA 94063
1592 LITTLE ORCHARD STREET, SAN JOSE, CA 95110
3207 FITZGERALD ROAD, RANCHO CORDOVA, CA 95742
5601 EASTGATE DRIVE, SAN DIEGO, CA 92121
24551 RAYMOND WAY, SUITE 151, LAKE FOREST, CA 92630



<u>Tree #'s 350 – 355 Shamel ash – Average 20" dbh building R.</u> Comments: This group of 6 trees is located between building R and the walk way. The collective root systems of these trees are exerting pressure on the walkways as well as the foundation of the building. These trees are still actively growing and will do further damage. Additionally, the canopies have weak branch attachments and long heavy limbs that extend over the roof line. Due to the close proximity to the structures, mitigating the risks in these trees is not possible.

<u>Tree # 356 Monterey pine -35'' dbh building S.</u> Comments: This tree is much too large for its location and is in poor health. Canopy has many long heavy branches extending over the tennis court and building S. The risk of failure of these limbs poses a significant threat to pedestrians and those that utilize the court. Root system is heaving the side walk and is near utilities that could also be damaged.

<u>Tree # 373 Silver dollar eucalyptus – 16" dbh building T.</u> Comments: Tree is located close to building and is structured very poorly. Due to topping many years ago, the resulting re-growth is poorly attached as is at risk of failure. No amount of mitigation pruning can fix these defects.

<u>Tree # 391 Monterey pine - 32" dbh building A.</u> Comments: This tree is much too large for its location and its health is in decline. Tree has a history of branch failures and has lost one large main leader. Canopy has many long heavy branches extending over the building. The risk of failure of these limbs poses a significant threat to the residents, pedestrians and cars utilizing the parking spaces nearby.

<u>Tree # 402 Red Ironbark – 24" dbh building B.</u> Comments: Tree is in good health, however, it is located very close to the structure and is exerting pressure on the foundation. Limbs are poorly attached and pose a risk of limb failure both over the building and over the pedestrian area. Due to the close proximity to the structures, mitigating these risks is not possible.

<u>Tree # 405 Silver dollar eucalyptus – 32" dbh building E.</u> Comments: Tree is much too large for its location. Canopy is comprised of 3 main leaders all of which are appear to be very heavy and poorly attached. These leaders (or trunks) extend over the building and the pedestrian area. Due to the close proximity to the structure, mitigating these risks through pruning is not possible.

<u>Tree # 410 Monterey pine - 31" dbh between buildings E and D.</u> Comments: Tree's health seems to be exhibiting signs of decline. Tree has long heavy limbs that pose a threat to pedestrians and residents. The trees close proximity to the surrounding hardscape is problematic and is causing significant damage which in turn is causing trip hazards for pedestrians.



<u>Tree # 411 Red ironbark - 27" dbh building C.</u> Comments: Tree is much too large for its location between buildings C and D and is very close to the structure. The canopy has 4 main leaders some of which are poorly attached and extend over the roof line of the adjacent structures. Additionally, many years ago the tree was topped and the resulting regrowth is also poorly attached and at risk of failure. Due to the close proximity to the structure, mitigating these risks through pruning is not possible.

<u>Tree # 412 Red ironbark – 31" dbh building C and laundry.</u> Comments: The structure of this tree is very poor in part due to the nature of the species and due to the fact that years ago the tree was topped and the resulting regrowth is poorly attached and poses a risk of failure. Despite a regular maintenance program, this tree has had multiple limb failures in the past 5 years.

<u>Tree #417 Silver dollar eucalyptus – 17" dbh building B.</u> Comments: Tree has very poor structure and an imbalanced canopy. Additionally, it is located too close to the building.

<u>Tree # 450 Monterey pine - 26" dbh building C.</u> Comments: This tree is located between building C and the parking garage. It has two main leaders that are attached at approximately 3' above grade. This branch attachment is severely included. With this condition, the leader that is growing over the parking garage is at significant risk of failure.

### Construction

It should be noted that this re-evaluation was done concurrently with preliminary design of a proposed renovation to all existing buildings on the property and installation of a new fire sprinkler system. Arborwell coordinated with the design team to ensure the fire sprinkler main line was routed so as to minimize the need for any tree removals

As a result of this close coordination, only three trees (all non-heritage) require removal to facilitate installation of the new fire sprinkler lines. These trees are identified as #'s 333, 418 and 445 on the attached Tree Inventory

### Conclusion

As a result of this re-evaluation and a reduction in the scope of the construction project, the number of trees being recommended for removal has been reduced from the 42 (proposed in 2013) to 39 now recommended for removal.



Sharon Green has many mature trees that truly add value to the community of Menlo Park. Unfortunately, there are also a number of large trees that were unwisely planted too close to buildings many years ago that now are causing significant problems to the community and are threatening the safety of its residents. Over the last few years since the time of the last evaluation, there have been a number of limb failures due the poor condition and structure of many of the trees. One of the fundamental principles of arboriculture is having the right tree in the right location. Moving forward with the proposed removals and their replacements will help this site to have many more trees that are placed in such a way so that the community can truly benefit from them.

Respectfully submitted,

Jonathan Cardenas

Certified Arborist WC #4333A

925-260-3186



JUN 0 7 2016

### Sharon Green Tree Inventory May 2016 Draft



CITY OF MENLO PARK TREE 2=Fair Removal Reason **BOTANICAL NAME COMMON NAME DBH** COMMENTS NO. 3=Good Recommendation (Structural/Health, Heritage Tree? 4=Very Good Construction) 5=Excellent Liquidambar 1 **Liquidambar** 12 3 Young tree; excellent health styraciflua Preserve Non-heritage Liquidambar 2 Liquidambar 17 3 Healthy tree; heavy on the ends styraciflua Preserve Hentage Liquidambar 3 Liquidambar 13 Tree falled; was removed 10/29/13 styraciflua 4 Prunus cerasifera Plum 8 Tree damaged by the failure of tree #3; was removed on 10/29/13 Liquidambar 5 Liquidambar 19 3 Good health and vigor styraciflua Preserve Heritage Removal recommended; tree has very poor structure and is a poor specimen. It is 6 Prunus cerasifera Plum 10 1 Remove showing signs of trunk and root decay. Recently lost major limb. Structural/Health Non-heritage **Liquidombar** 7 **Liquidambar** 14 3 Good health and vigor styraciflua Preserve Non-heritage Removal recommended; heavily weighted on one side, showing signs of uprooting and is 8 Pinus radiata Monterey Pine 24 2 causing damage to patio. Mitigation: If tree is to be retained, significantly reduce branch Mitigation Structural/Health Heritage end weight through pruning and monitor. Liquidambar 9 Liquidambar 14 3 Good health and vigor styraciflua Preserve Non-heritage Removal recommended; poor structure at very top and could lose large limbs at any Liquidombar 10 Liquidombar 15 time, is located near a walkway. Mitigation: If tree is retained, prune to reduce branch 2 styrociflua Mitigation Heritage Structural/Health end weight and monitor. Liquidambar 11 Liquidambar 14 3 Healthy tree; many water sprouts Preserve styraciflua Non-heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	DBH	CONDITION  1=Poor  2=Fair  3=Good  4=Very Good  5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
12	Prunus cerasifera	Plum	7	1	Removal recommended; this tree has very poor structure and is a poor specimen. It is showing signs of trunk and root decay.	Remove	Structural/Health	Non-heritage
13	Liquidambar styraciflua	Liquidambar	17	3	Heavy on the ends; good health	Preserve		Heritage
14	Liquidambar styraciflua	Liquidambor	12	3	Healthy with good structure	Preserve		Non-heritage
15	Liquidambar styraciflua	Liquidambar	11	3	Healthy young tree	Preserve		Non-heritage
16	Liquidambar styraciflua	Liquidambar	8	1	Removal recommended; overcrowded with severe trunk decay. If tree is retained, prune to reduce branch end weight and monitor. Mitigation: If tree is retained, prune to reduce branch end weight and monitor.	Mitigation	Structural/Health	Non-heritage
17	Quercus ilex	Holly Oak	13	2	Good health; thin canopy	Preserve		Non-heritage
18	Liquidambar styraciflua	Liquidambar	13		This tree was removed.			Non-heritage
19	Liquidambar styraciflua	Liquidambar	7	1	Removal recommended; overcrowded with severe root decay. Mitigation: If tree is retained, prune to reduce branch end weight and monitor.	Mitigation	Structural/Health	Non-heritage
20	Liquidombar styraciflua	Liquidambar	12	3	Poor structure; good health	Preserve		Non-heritage
21	Liquidambar styraciflua	Liquidambar	8	2	Removal recommended; may have root decay; poor structure and will be growing over the building in the future. Mitigation: If tree is retained, prune to reduce branch end weight and monitor.	Mitigation	Structural/Health	Non-heritage
22	Liquidambar styrociflua	Liquidambar	10	3	Heavy on one side - slightly imbalanced	Preserve		Non-heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	DBH	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
23	Sequoia sempervirens	Redwood	40	4	Good health	Preserve		Heritage
24	Sequoia sempervirens	Redwood	19	4	Good health	Preserve		Heritage
25	Prunus cerasifera	Plum	13	2	Removal recommended; poor structure, losing branching	Remove	Structural/Health	Non-heritage
26	Sequola sempervirens	Redwood	26	4	Good health	Preserve		Heritage
27	Sequola sempervirens	Redwood	27	4	Good health	Preserve		Heritage
28	Sequoia sempervirens	Redwood	26	4	Good health	Preserve		Heritage
29	Sequola sempervirens	Redwood	25	4	Good health	Preserve		Hentage
30	Sequoia sempervirens	Redwood	20	4	Good health	Preserve		Heritage
31	Sequoia sempervirens	Redwood	15	4	Excellent health	Preserve		Heritage
32	Sequola sempervirens	Redwood	19	4	Excellent health	Preserve		Heritage
33	Pinus radiata	Monterey Pine	24	2	Removal recommended; canopy looks thin; tree is in close proximity and leaning over building and may cause damage to foundation and pipes.	Remove	Structural/Health	Heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	DBH	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
34	Pinus radiata	Monterey Pine	25	2	Removal recommended; canopy looks thin; tree is in close proximity and leaning over building and may cause damage to foundation and pipes.	Remove	Structural/Health	Heritage
35	Pinus radiata	Monterey Pine	23	2	Removal recommended; tree is in close proximity to building and may cause damage to foundation and pipes.	Remove	Structural/Health	Heritage
36	Pinus radiata	Monterey Pine	26	2	Removal recommended; canopy looks thin; tree is in close proximity and leaning over building and may cause damage to foundation and pipes.	Remove	Structural/Health	Heritage
37	Pinus radiata	Monterey Pine	30	2	Removal recommended; tree is in close proximity to building and may cause damage to foundation and pipes. Mitigation: If tree is retained, prune to reduce branch end weight and monitor.	Mitigation	Structural/Health	Heritage
38	Ulmus parvifolia	Chinese Elm	18	3	Good health and vigor	Preserve		Heritage
39	Liriodendron tulipifera	Tulip Tree	9	3	Good health and vigor; heavy ended	Preserve		Non-heritage
40	Liriodendron tulipifera	Tulip Tree	18	3	Good health and vigor; heavy ended	Preserve		Heritage
41	Uriodendron tulipifera	Tulip Tree	11	3	Good health and vigor; heavy ended	Preserve	_	Non-heritage
42	Liriodendron tulipifera	Tulip Tree	13	3	Good health and vigor; heavy ended	Preserve		Non-heritage
43	Liriodendron tulipifera	Tulip Tree	15	3	Good health and vigor; heavy ended	Preserve		Heritage
44	Liriodendron tulipifera	Tulip Tree	14	3	Good health and vigor; heavy ended	Preserve		Non-heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	DBH	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
45	Urlodendron tulipifera	Tulip Tree	14	3	Good health and vigor; heavy ended	Preserve		Non-heritage
46	Urlodendron tulipifera	Tulip Tree	15	3	Good health, heavy ended	Preserve		Heritage
47	Pyrus kawakamii	Evergreen Pear	20	3	Removal recommended; has developed a heavy lean due to overcrowding, structure is fair but will never develop correctly due to close proximity to the building and other trees.	Remove	Structural/Health	Heritage
48	Pyrus kawakamil	Evergreen Pear	15	3	Removal recommended; has developed a heavy lean due to overcrowding, structure is fair but will never develop correctly due to close proximity to the building and other trees.	Remove	Structural/Health	Heritage
49	Pyrus kawakamii	Evergreen Pear	9	3	Removal recommended; has developed a heavy lean due to overcrowding, structure is fair but will never develop correctly due to close proximity to the building and other trees.	Remove	Structural/Health	Non-heritage
50	Pinus radiata	Monterey Pine	58	2	Deadwood	Preserve		Heritage
51	Uriodendron tulipifera	Tulip Tree	25	3	Good health, heavy ended	Preserve		Heritage
52	Liriodendron tulipifera	Tulip Tree	23	3	Good health, heavy ended	Preserve		Heritage
53	Quercus lobata	Valley Oak	13	1	Removal recommended; tree is in decline, has minimal branches and is overcrowded; removal will allow others to grow. Mitigation: If tree is retained, prune to to remove dead wood and monitor.	Mitigation	Structural/Health	Heritage
54	Quercus lobata	Valley Oak	42	3	Some branches have decay	Preserve		Heritage
55	Betula pendula	White Birch	8	5	Young tree; excellent health	Preserve		Non-heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	DBH	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
56	Betula pendula	White Birch	8	5	Young tree; excellent health	Preserve		Non-heritage
57	Lagerstroemia	Crape Myrtle	4.5	5	Young tree; excellent health	Preserve		Non-heritage
58	Lagerstroemia	Crape Myrtle	4.5	5	Young tree; excellent health	Preserve		Non-heritage
59	Sequola sempervirens	Redwood	17	5	Healthy tree	Preserve		Heritage
60	Sequoia sempervirens	Redwood	57	5	Low Branches	Preserve		Heritage
61	Sequola sempervirens	Redwood	41	2	Removal recommended; tree has a hard lean and is showing signs of uprooting; is located near a walkway. Mitigation: If tree is retained, prune to reduce branch end weight, crown thin and monitor.	Mitigation	Structural/Health	Heritage
62	Malus floribunda	Crab Apple	4	3	Good health, poor structure	Preserve		Non-heritage
63	Alnus rhombifolia	Alder	22	3	Good health; heavy ended	Preserve		Heritage
64	Quercus labata	Valley Oak	19	3	Canopy looks thin	Preserve		Heritage
65	Quercus lobata	Valley Oak	27	3	Good health; heavy ended	Preserve		Heritage
66	Liriodendron tulipifera	Tulip Tree	13	3	Good health and vigor	Preserve		Non-heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	DBH	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
67	Liriodendron tulipifera	Tulip Tree	29	3	Good health and vigor	Preserve		Heritage
68	Liriodendron tulipifera	Tulip Tree	17	3	Good health and vigor	Preserve		Heritage
69	Liriodendron tulipifera	Tulip Tree	20	3	Good health and vigor	Preserve		Heritage
70	Malus floribunda	Crab Apple	10	3	Overgrown	Preserve		Non-heritage
71	Quercus lobata	Valley Oak	35	3	Good health	Preserve		Heritage
72	Quercus labata	Valley Oak	33	3	Good health	Preserve		Heritage
73	Quercus lobata	Valley Oak	24	3	Good health	Preserve		Heritage
74	Corymbia ficifolia	Red Gum	20	2	Removal recommended; good health, poor structure. Mitigation: Significantly reduce branch end weight through pruning and monitor.	Mitigation	Structural/Health	Heritage
75	Corymbia ficifolia	Red Gum	15	2	Removal recommended; good health, poor structure	Remove	Structural/Health	Heritage
76	Sequoia sempervirens	Redwood	32	4	Good health and structure	Preserve		Heritage
77	Sequoia sempervirens	Redwood	38	4	Good health and structure	Preserve		Heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	DBH	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
78	Sequoia sempervirens	Redwood	39	4	Good health and structure	Preserve		Heritage
79	Sequola sempervirens	Redwood	32	4	Good health and structure	Preserve		Heritage
80	Sequola sempervirens	Redwood	41	4	Good health and structure	Preserve		Heritage
81	Sequala sempervirens	Redwood	40	4	Good health and structure	Preserve		Heritage
82	Malus floribunda	Crab Apple	7	3	Poor structure	Preserve		Non-heritage
83	Malus floribunda	Crab Apple	6	3	Poor structure	Preserve		Non-heritage
84	. Sequaia sempervirens	Redwood	23	3	Good health and structure, but thin canopy	Preserve		Heritage
85	Sequola sempervirens	Redwood	25	3	Good health and structure, but thin canopy	Preserve		Heritage
86	Sequoia sempervirens	Redwood	25	3	Good health and structure, but thin canopy	Preserve		Heritage
87	Pinus radiata	Monterey Pine	42	2	Removal recommended; located very close to building and retaining wall and is causing damage to foundation and pipes. Canopy has dieback.	Remove	Structural/Health	Heritage
88	Pinus radiota	Monterey Pine	42	2	Removal recommended; located very close to building and retaining wall and is causing damage to foundation and pipes.	Remove	Structural/Health	Heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	DBH	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
89	Liriodendran tulipifera	Tulip Tree	17	3	Good health	Preserve		Heritage
90	Uriodendron tulipifera	Tulip Tree	22	1	Removal recommended; included bark and poor health; severe trunk decay, potential failure.	Remove	Structural/Health	Heritage
91	Liriodendron tulipifera	Tulip Tree	16	3	Good health; poor structure	Preserve		Heritage
92	Liriodendron tulipifera	Tulip Tree	21	3	Good health; poor structure	Preserve		Heritage
93	Liriodendron tulipifera	Tulip Tree	19	3	Good health; poor structure	Preserve		Heritage
94	Liriodendron tulipifera	Tulip Tree	17	3	Good health; poor structure	Preserve		Heritage
95	Pinus radiata	Monterey Pine	30	2	Removal recommended; too close to building and causing damage to foundation and pipes.	Remove	Structural/Health	Heritage
96	Pinus radiata	Monterey Pine	31	2	Removal recommended; too close to building and causing damage to foundation and pipes.	Remove	Structural/Health	Heritage
97	Eucalyptus spp.	Gum	25	1	Removal recommended; overgrown and poorly structured; limbs break often and is a danger to residents. Mitigation: Significantly reduce branch end weight through pruning and monitor.	Mitigation	Structural/Health	Heritage
98	Juniperus chinensis	Juniper	19	3	Good Health; canopy is dense	Preserve		Heritage
99	Liriodendron tulipifera	Tulip Tree	19	3	End weight is a problem, but otherwise healthy	Preserve		Heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	DBH	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
100	Liriodendron tulipifero	Tulip Tree	19	. 3	End weight is a problem, but otherwise healthy	Preserve		Heritage
101	Liriodendron tulipijera	Tulip Tree	22	3	End weight is a problem, but otherwise healthy	Preserve		Heritage
102	Liriodendron tulipifera	Tulip Tree	20	3	End weight is a problem, but otherwise healthy	Preserve		Heritage
103	Quercus lobata	Valley Oak	38	3	Good health and structure	Preserve		Heritage
104	Quercus lobata	Valley Oak	46	3	Good health and structure	Preserve		Heritage
105	Sequola sempervirens	Redwood	31	3	Good health	Preserve		Heritage
106	Sequoia sempervirens	Redwood	28	4	Overcrowded	Preserve		Heritage
107	Sequoia sempervirens	Redwood	18	4	Overcrowded, multiple broken branches, cause unknown	Preserve		Heritage
108	Sequola sempervirens	Redwood	14	3	Canopy looks thin and the trunk has a gash	Preserve		Non-heritage
109	Arbutus marina	Arbutus	11	3	Healthy young tree, poor structure	Preserve		Non-heritage
110	Sequoia sempervirens	Redwood	11	3	Very thin canopy	Preserve		Non-heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	DBH	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
111	Pinus radiata	Monterey Pine	39	2	Poor vigor and lot of deadwood	Preserve		Heritage
112	Quercus alba	White Oak	26	3	Young tree; excellent health	Preserve		Heritage
113	Liriodendron tulipifera	Tulip Tree	19	2	Under stress	Preserve		Heritage
114	Sequola sempervirens	Redwood	12	3	Young healthy tree; potentially over watered	Preserve		Non-heritage
115	Sequola sempervirens	Redwood	18	3	Young healthy tree; potentially over watered	Preserve		Heritage
116	Liriodendron tulipifera	Tulip Tree	15	3	Stressed; potentially over watered	Preserve		Heritage
117	Malus floribunda	Crab Apple	6	3	Young tree; excellent health	Preserve		Non-heritage
118	Betula pendula	White Birch	9	3	Healthy vigor and structure	Preserve		Non-heritage
119	Betula pendula	White Birch	10	3	Heavy on the ends; good health	Preserve		Non-heritage
120	Pinus radiata	Monterey Pine	52	2	Removal recommended; very large tree close to parking garage; poor structure and potentially presents a risk of failure. Has lost large limbs. Mitigation: Significantly reduce branch end weight through pruning and monitor.	Mitigation	Structural/Health	Heritage
121	Pinus radiata	Monterey Pine	36	2	Canopy thinning	Preserve		Heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	DBH	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
122	Pinus radiata	Monterey Pine	30	3	Healthy tree. Leaning significantly towards the street.	Preserve		Heritage
123	Pinus rodiata	Monterey Pine	30	2	Canopy thinning, with a large amount of deadwood.	Preserve		Heritage
124	E. sideroxylon	Red Ironbark	29	2	Removal recommended; very large tree close to buildings; poor structure and presents a risk of failure. Mitigation: Significantly reduce branch end weight through pruning and monitor.	Mitigation	Structural/Health	Heritage
125	Urlodendron tulipijera	Tulip Tree	20	3	Large healthy tree, heavy ended	Preserve		Heritage
126	Liriodendron tulipifera	Tulip Tree	17	3	Large healthy tree, heavy ended	Preserve		Heritage
127	Liriodendron tulipifera	Tulip Tree	19	3	Large healthy tree, heavy ended	Preserve		Heritage
128	Liriodendron tulipifera	Tulip Tree	14	2	Removal recommended; young tree; may be receiving to much water	Remove	Structural/Health	Non-heritage
129	Sequoia sempervirens	Redwood	17	4	Healthy trees, lots of crossing branches	Preserve		Heritage
130	Sequola sempervirens	Redwood	23	4	Healthy trees, lots of crossing branches	Preserve		Heritage
131	Sequola sempervirens	Redwood	13	4	Healthy trees, lots of crossing branches	Preserve		Non-heritage
132	Sequola sempervirens	Redwood	18	4	Healthy trees, lots of crossing branches	Preserve		Heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	DBH	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
133	Sequola sempervirens	Redwood	19	4	Healthy trees, lots of crossing branches	Preserve		Heritage
134	Sequoia sempervirens	Redwood	39	4	Healthy trees, lots of crossing branches	Preserve		Heritage
135	Sequoia sempervirens	Redwood	34	3	Healthy trees, being over watered	Preserve		Heritage
136	Sequola sempervirens	Redwood	41	3	Healthy trees, being over watered	Preserve		Heritage
137	Cinnamomum camphora	Camphor	16	3	Young healthy tree	Preserve		Heritage
138	Sequola sempervirens	Redwood	37	3	Large healthy tree, good vigor and structure	Preserve		Heritage
139	Sequola sempervirens	Redwood	27	3	Large healthy tree, good vigor and structure	Preserve		Heritage
140	Betula pendulo	White Birch	12	3	Healthy tree, overcrowded by Redwood	Preserve		Non-heritage
141	Betula pendulo	White Birch	11	3	Healthy tree, overcrowded by Redwood	Preserve		Non-heritage
142	Betula pendula	White Birch	13	3	Healthy tree, overcrowded by Redwood	Preserve		Non-heritage
143	Sequola sempervirens	Redwood	15	3	Young tree, seems to be browning due to overcrowding and possibly too much water	Preserve		Heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	DBH	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
144	Sequoia sempervirens	Redwood	15	3	Young tree, seems to be browning due to overcrowding and possibly too much water	Preserve		Heritage
145	Sequola sempervirens	Redwood	14	3	Young tree, seems to be browning due to overcrowding and possibly too much water	Preserve		Non-heritage
146	Sequoia sempervirens	Redwood	14	3	Young tree, seems to be browning due to overcrowding and possibly too much water	Preserve		Non-heritage
147	Sequola sempervirens	Redwood	19	3	Young tree, seems to be browning due to overcrowding and possibly too much water	Preserve		Heritage
148	Sequola sempervirens	Redwood	30	3	Young tree, seems to be browning due to overcrowding and possibly too much water	Preserve		Heritage
149	Sequola sempervirens	Redwood	6	2	Removal recommended; small; overcrowded and declining; should be removed to allow others to grow. Mitigation: Remove deadwood and monitor	Mitigation	Structural/Health	Non-heritage
150	Sequola sempervirens	Redwood	15	3	Good Health and vigor	Preserve		Heritage
151	Betula pendula	White Birch	10	3	Good Health and vigor	Preserve		Non-heritage
152	Betula pendula	White Birch	9	3	Overcrowded and poor structure	Preserve		Non-heritage
153	Betula pendula	White Birch	14	3	Overcrowded and poor structure	Preserve		Non-heritage
154	Sequala sempervirens	Redwood	14	3	Good health, vigor and structure	Preserve		Non-heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	DBH	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
155	Sequola sempervirens	Redwood	19	3	Good health, vigor and structure	Preserve		Heritage
156	Sequola sempervirens	Redwood	18	3	Good health, vigor and structure	Preserve		Heritage
157	Sequola sempervirens	Redwood	16	3	Good health, vigor and structure	Preserve		Heritage
158	Pinus radiata	Monterey Pine	24	2	Trees in decline; thin and heavy on ends	Preserve		Heritage
159	Pinus radiata	Monterey Pine	39	2	Trees in decline; thin and heavy on ends	Preserve		Heritage
160	Quercus ilex	Holly Oak	11	3	Canopy seems thin	Preserve		Non-heritage
161	Sequoia sempervirens	Redwood	24	2	Has included bark but good health	Preserve		Heritage
162	Sequola sempervirens	Redwood	12	2	Tree is in decline	Preserve	-	Non-heritage
163	Sequoia sempervirens	Redwood	10	2	Tree is in decline	Preserve		Non-heritage
164	Quercus ilex	Hally Oak	9	2	Tree has lots of water spots, and is stressed	Preserve		Non-heritage
165	Pinus radiata	Monterey Pine	39	2	Removal recommended; tree has potential for failure and has lost large limbs in the past, poor structure indicates it will lose more. Mitigation: Significantly reduce branch end weight through pruning, remove large limb over Eastridge Ave. and monitor.	Mitigation	Structural/Health	Heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	рвн	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
166	Pinus radiata	Monterey Pine	36	2	Removal recommended; tree has large potential for failure and has lost large limbs in the past, poor structure indicates it will lose more. Mitigation: Significantly reduce branch end weight through pruning install cable and monitor.	Mitigation	Structural/Health	Heritage
167	Betula pendula	White Birch	6	3	Healthy young trees	Preserve		Non-heritage
168	Juniperus chinensis	Juniper	9	3	Healthy young trees	Preserve		Non-heritage
169	Uquidambar styraciflua	Liquidambar	10	3	Healthy young trees	Preserve		Non-heritage
170	Platanus hispanica	Sycamore	12	2	Removal recommended; health is fair, but overcrowded and one-sided. Poor structure dominated by neighboring pine.	Remove	Structural/Health	Non-heritage
171	Platanus hispanica	Sycamore	8	2	Healthy vigor and structure, but overcrowded and one-sided	Preserve		Non-heritage
172	Platanus hispanica	Sycamore	9	2	Healthy vigor and structure, but overcrowded and one-sided	Preserve		Non-heritage
173	Platanus hispanica	Sycamore	8	2	Healthy vigor and structure, but overcrowded and one-sided	Preserve		Non-heritage
174	Platanus hispanica	Sycamore	10	2	Healthy vigor and structure, but overcrowded and one-sided	Preserve		Non-heritage
175	Platanus hispanica	Sycamore	10	2	Healthy vigor and structure, but overcrowded and one-sided	Preserve		Non-heritage
176	Prunus cerasifera	Plum	6	3	Good health, but poor structure	Preserve		Non-heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	ОВН	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
177	Pinus radiata	' Monterey Pine	30	2	Removal recommended; tree is growing directly against the building and is causing damage to foundation and pipes	Remove	Structural/Health	Heritage
178	Prunus cerasifera	Plum	6	3	Good health, but poor structure	Preserve		Non-heritage
179	Platanus hispanica	Sycamore	10	3	Very thin due to overcrowding	Preserve		Non-heritage
180	Platanus hispanica	Sycamare	12	3	Tree is overgrown due to crowding	Preserve		Non-heritage
181	Platanus hispanica	Sycamore	12	3	Tree is overgrown due to crowding	Preserve		Non-heritage
182	Platanus hispanica	Sycamore	12	3	Tree is overgrown due to crowding	Preserve		Non-heritage
183	Platanus hispanica	Sycamare	12	3	Tree is overgrown due to crowding	Preserve		Non-heritage
184	Platanus hispanica	Sycomore	10	3	Tree is overgrown due to crowding	Preserve		Non-heritage
185	Platanus hispanica	Sycamore	12	3	Tree is overgrown due to crowding	Preserve		Non-heritage
186	Cinnamomum camphora	Camphor	10	2.5	Fair health; canopy is thin	Preserve		Non-heritage
187	Cinnamomum comphora	Camphor	11	2.5	Fair health; canopy is thin	Preserve		Non-heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	DBH	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
188	Cinnamomum comphora	Camphor	12	2.5	Fair health; canopy is thin	Preserve		Non-heritage
189	Cinnamomum camphora	Camphor	13	2.5	Fair health; canopy is thin	Preserve		Non-heritage
190	Cinnamomum camphora	Camphor	12	2.5	Fair health; canopy is thin	Preserve		Non-heritage
191	Cinnamomum camphora	Camphor	11	2.5	Fair health; canopy is thin	Preserve		Non-heritage
192	Pinus radiata	Monterey Pine	32	2	Removal recommended; showing potential for failure; causing damage to walkways and posing a danger to residents. Mitigation: Significantly reduce branch end weight through pruning and monitor.	Mitigation	Structural/Health	Heritage
193	Pinus radiata	Monterey Pine	34	2	Removal recommended; showing potential for failure; causing damage to walkways and posing a danger to residents. Mitigation: Significantly reduce branch end weight through pruning and monitor.	Mitigation	Structural/Health	Heritage
194	Platanus hispanica	Sycamore	15	3	Healthy tree, but overcrowded	Preserve		Heritage
195	Platanus hispanica	Sycamore	15	3	Tree is overgrown and very one-sided	Preserve		Heritage
196	Platanus hispanica	Sycamare	13	3	Tree is overgrown and very one-sided	Preserve		Non-heritage
197	Platanus hispanica	Sycamore	15	3	Tree is overgrown and very one-sided	Preserve		Heritage
198	Platanus hispanica	Sycamore	16	3	Tree is overgrown and very one-sided	Preserve		Heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	DBH	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
199	Platanus hispanica	Sycamore	17	3	Tree is overgrown and very one-sided	Preserve		Heritage
200	Platanus hispanica	Sycamore	17	3	Tree is overgrown and very one-sided	Preserve		Heritage
201	Pittosporum eugenioides	Pittosporum	10	3	Lots of crossing and dead branches	Preserve		Non-heritage
202	Pittasporum eugenioides	Pittosporum	10	3	Lots of crossing and dead branches	Preserve		Non-heritage
203	Platanus hispanica	Sycamore	19	3	Removal recommended; high potential risk tree; significant lean, overgrown and is causing damage to pipes and foundation; very poor structure, with pruning risk can be somewhat mitigated	Mitigation	Structural/Health	Heritage
204	Platanus hispanica	Sycamore	18	3	Removal recommended; high potential risk tree; significant lean, overgrown and is causing damage to pipes and foundation; very poor structure, with pruning risk can be somewhat mitigated	Mitigation	Structural/Health	Heritage
205	E. sideroxylon	Red Ironbark	18	2	Removal recommended; high risk tree; significant lean, overgrown and may damage building; very poor structure and has had numerous limb failures; located near walkways and poses a danger to residents. Mitigation: Significantly reduce branch end	Mitigation	Structural/Health	Heritage
206	E. sideroxylon	Red Ironbark	19	2	Removal recommended; high risk tree; significant lean, overgrown and may damage building; very poor structure and has had numerous limb failures; located near walkways and poses a danger to residents	Remove	Structural/Health	Heritage
207	Prunus caroliniana	Carolina Cherry	9	3	Healthy tree, but heavy ended	Preserve		Non-heritage
208	Cinnamomum comphora	Comphor	15	3	Healthy tree, but heavy ended	Preserve	SI .	Heritage
209	Magnolia grandiflora	Magnolia	14	3	Good health, vigor and structure	Preserve		Non-heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	D8H	CONDITION  1=Poor  2=Fair  3=Good  4=Very Good  5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
210	Prunus cerosifera	Plum	10	3	Good health, very poor structure	Preserve		Non-heritage
211	Magnolia grandiflora	Magnolia	9	1	Removal recommended; dead nearly dead	Remove	Structural/Health	Non-heritage
212	Magnolla grandiflora	Magnalia	10	1	Removal recommended; tree shows large amounts of die back; declining due to lack of light and overcrowding	Remove	Structural/Health	Non-heritage
213	Prunus cerasifera	Plum	10	3	Good health; but overcrowded and overgrown	Preserve		Non-heritage
214	Platanus hispanica	Sycamore	18	2	Removal recommended; tree is one-sided; overgrown and lifting the sidewalk; located too close to building and will soon cause damage to foundation. Mitigation: Prune away from building and monitor.	Mitigation	Structural/Health	Heritage
215	Platanus hispanica	Sycamore	14	2	Removal recommended; tree is one-sided; overgrown and lifting the sidewalk; located too close to building and will soon cause damage to foundation. Mitigation: Prune away from building and monitor.	Mitigation	Structural/Health	Non-heritage
216	Platanus hispanica	Sycomore	15	2	Removal recommended; tree is one-sided; overgrown and lifting the sidewalk; located too close to building and will soon cause damage to foundation. Mitigation: Prune away from building and monitor.	Mitigation	Structural/Health	Heritage
217	Platanus hispanica	Sycamore	11	2	Removal recommended; tree is one-sided; overgrown and lifting the sidewalk; located too close to building and will soon cause damage to foundation. Mitigation: Prune away from building and monitor.	Mitigation	Structural/Health	Non-heritage
218	Platanus hispanica	Sycamore	20	2	Removal recommended; tree is one-sided; overgrown and lifting the sidewalk; located too close to building and will soon cause damage to foundation. Mitigation: Prune away from building and monitor.	Mitigation	Structural/Health	Heritage
219	Prunus cerasifera	Plum	6	1	Removal recommended; poor structure, canopy looks poor; not aesthetically pleasing.	Remove	Structural/Health	Non-heritage
220	Prunus cerasifera	Plum	12	2	Healthy and vigorous; fair structure	Preserve		Non-heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	DBH	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
221	Ulmus parvifolia	Chinese Elm	10	3	Healthy and vigorous; but very heavy ends	Preserve		Non-heritage
222	Ulmus parvifolia	Chinese Elm	15	3	Health and vigorous; but very heavy ends	Preserve		Heritage
223	Ulmus parvifolia	Chinese Elm	11	3	Healthy and vigorous; but very heavy ends	Preserve		Non-heritage
224	Ulmus parvifolia	Chinese Elm	11	3	Healthy and vigorous; but very heavy ends	Preserve		Non-heritage
225	Platanus hispanica	Sycamare	21	3	Tree is healthy; but overgrown	Preserve		Heritage
226	Platanus hispanica	Sycamore	17	3	Tree is healthy; but overgrown	Preserve		Heritage
227	Platanus hispanica	Sycamore	8	1	Removal recommended; overcrowded, and poor structure; should be removed so others can grow. Mitigation: Prune and monitor,	Mitigation	Structural/Health	Non-heritage
228	Platanus hispanica	Sycamore	22	3	Healthy tree with long heavy branches	Preserve		Heritage
229	Platanus hispanica	Sycamore	21	3	Healthy tree with long heavy branches	Preserve		Heritage
230	Platanus hispanica	Sycamore	10	1	Removal recommended; overcrowded, and poor structure; should be removed so others can grow. Mitigation: Prune and monitor.	Mitigation	Structural/Health	Non-heritage
231	Platanus hispanica	Sycamore	16	3	Large healthy tree	Preserve		Heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	DBH	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
232	Platanus hispanica	Sycamore	19	3	Large healthy tree	Preserve		Heritage
233	Quercus lobata	Valley Oak	11	3	Young healthy tree; one-sided, due to overcrowding	Preserve		Heritage
234	Quercus lobata	Valley Oak	10	3	Young healthy tree; one-sided, due to overcrowding	Preserve		Heritage
235	Quercus lobata	Valley Oak	10	3	Young healthy tree; one-sided, due to overcrowding	Preserve		Heritage
236	Prunus caroliniana	Carolina Cherry	9	2	Removal recommended; overcrowded, and poor structure; should be removed so others can grow. Mitigation: Prune and monitor.	Mitigation	Structural/Health	Non-heritage
237	Liriodendron tulipifera	Tulip Tree	19	3	Healthy tree, but has heavy ends	Preserve		Heritage
238	Liriodendron tulipifera	Tulip Tree	15	3	Healthy tree, but has heavy ends	Preserve		Heritage
239	Liriodendron tulipifera	Tulip Tree	13	3	Healthy tree, but has heavy ends	Preserve		Non-heritage
240	Liriodendron tulipifera	Tulip Tree	13	2	Removal recommended; bad case of included bark; located too close to drain and is causing damage to pipes.	Remove	Structural/Health	Non-heritage
241	Betula pendula	White Birch	8		Tree died, remaved summer of 2013			
242	Betula pendula	White Birch	6		Tree died, removed summer of 2013			



TREE NO.	BOTANICAL NAME	COMMON NAME	DBH	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
243	Pyrus kawakamii	Evergreen Pear	9	3	Healthy, but overgrown	Preserve		Non-heritage
244	Pyrus kawakamii	Evergreen Pear	10	3	Healthy, but overgrowл	Preserve		Non-heritage
245	Pyrus kawakamii	Evergreen Pear	8	3	Healthy, but overgrown	Preserve		Non-heritage
246	Ulmus parvifolia	Chinese Elm	17	3	Healthy tree, poor structure	Preserve		Heritage
247	Pyrus kawakamii	Evergreen Pear	10	3	Good health and vigor, poor structure	Preserve		Non-heritage
248	Pinus pinea	Stone Pine	32	4	Healthy tree, but heavy on ends	Preserve		Heritage
249	Pinus pinea	Stone Pine	29	4	Healthy tree, but heavy on ends	Preserve		Heritage
250	Liriodendron tulipifera	Tulip Tree	15	3	Healthy tree; good structure, ends are weighted	Preserve		Heritage
251	Liriodendron tulipifera	Tulip Tree	9	3	Healthy tree, good structure, ends are weighted	Preserve		Non-heritage
252	Liriodendron tulipifera	Tulip Tree	12	3	Healthy tree, good structure, ends are weighted	Preserve		Non-heritage
253	Uriodendron tulipifera	Tulip Tree	11	3	Healthy tree, good structure, ends are weighted	Preserve		Non-heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	D8H	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
254	Liriodendron tulipifera	Tulip Tree	10	2	Tree looks better since last evaluation, continue to monitor	Preserve		Non-heritage
255	Quercus lobata	Valley Oak	36	3	Old healthy tree; heavy on one side	Preserve		Heritage
256	Platanus hispanica	Sycamore	18	3	Large healthy tree; good structure	Preserve		Heritage
257	Platanus hispanica	Sycamore	9	2	Removal recommended; small overcrowded tree with poor structure; should be removed to allow others to grow. Mitigation: Prune and monitor.	Mitigation	Structural/Health	Non-heritage
258	Platanus hispanica	Sycamore	14	3	Healthy tree with long ends	Preserve		Non-heritage
259	Platanus hispanica	Sycamore	15	3	Healthy tree with long ends	Preserve		Heritage
260	Platanus hispanica	Sycamore	10	2	Removal recommended; small overcrowded tree with poor structure; should be removed to allow others to grow. Mitigation: Prune and monitor.	Mitigation	Structural/Health	Non-heritage
261	Platanus hispanica	Sycamore	7	2	Removal recommended; small overcrowded tree with poor structure; should be removed to allow others to grow. Mitigation: Prune and monitor.	Mitigation	Structural/Health	Non-heritage
262	Platanus hispanica	Sycamore	15	3	Healthy tree overcrowding others	Preserve		Heritage
263	Platanus hispanica	Sycamore	8	2	Removal recommended; small overcrowded tree with poor structure; should be removed to allow others to grow. Mitigation: Prune and monitor.	Mitigation	Structural/Health	Non-heritage
264	Pinus radiata	Monterey Pine	28	3	Removal recommended; located too close to building and is causing damage to the foundation, pipes, and walkways. Mitigation: Prune away from building and monitor.	Mitigation	Structural/Health	Heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	DBH	CONDITION  1=Poor  2=Fair  3=Good  4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
265	Platanus hispanica	Sycamore	20	3	Healthy tree one-sided due to crowding	Preserve		Heritage
266	Platanus hispanica	Sycamore	15	3	Healthy tree one-sided due to crowding	Preserve		Heritage
267	Platanus hispanica	Sycamore	15	3	Healthy tree one-sided due to crowding	Preserve		Heritage
268	Prunus cerasifera	Plum	8	3	Healthy tree one-sided due to crowding	Preserve		Non-heritage
269	Platanus hispanica	Sycamore	18	3	Removal recommended; showing signs of trunk decay; lifting sidewalk. Mitigation: Prune and monitor.	Mitigation	Structural/Health	Heritage
270	Platanus hispanica	Sycamore	14	3	Some trunk decay	Preserve		Non-heritage
271	Platanus hispanica	Sycamore	14	3	Large tree one-sided	Preserve		Non-heritage
272	Platanus hispanica	Sycamore	15	3	Large tree with one sided canopy. Is causing significant damage to hardscape.	Remove	Structural/Health	Heritage
273	Prunus cerasifera	Plum	8	3	Healthy tree, but overcrowded with poor structure	Preserve		Non-heritage
274	Platanus hispanica	Sycomore	15	3	Healthy tree, but overgrown	Preserve		Heritage
275	Platanus hispanica	Sycamore	13	3	Healthy tree, but overgrown	Preserve		Non-heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	DBH	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
276	Platanus hispanica	Sycamore	14	3	Healthy tree, but overgrown	Preserve		Non-heritage
277	Pinus radiata	Monterey Pine	31	2	Showing signs of decline	Preserve		Heritage
278	Sequoia sempervirens	Redwood	25	3	Young healthy tree; a little overcrowded	Preserve		Heritage
279	Sequoia sempervirens	Redwood	25	3	Young healthy tree; a little overcrowded	Preserve		Heritage
280	Sequola sempervirens	Redwood	22	3	Young healthy tree, a little overcrowded	Preserve		Heritage
281	Sequola sempervirens	Redwood	19	3	Young healthy tree, a little overcrowded	Preserve		Heritage
282	Sequola sempervirens	Redwood	20	3	Young healthy tree, a little overcrowded	Preserve		Heritage
283	Sequola sempervirens	Redwood	18	3	Young healthy tree, a little overcrowded	Preserve		Heritage
284	Sequola sempervirens	Redwood	7	1	Removal recommended; small overcrowded tree; should be removed to allow others to grow. Mitigation: Purne and monitor.	Mitigation	Structural/Health	Non-heritage
285	Platanus hispanica	Sycamore	17	3	Tree health good, lifting & cracking sidewalk. Located too close to the hardscape for mitigation	Remove	Structural/Health	Heritage
286	Platanus hispanica	Sycamore	14	3	Healthy tree with good structure, but lifting sidewalk	Preserve		Non-heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	DBH	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
287	Platanus hispanica	Sycamore	15	3	Healthy tree with good structure, but lifting sidewalk	Preserve		Heritage
288	Platanus hisponico	Sycamore	11	3	Healthy tree with good structure, but lifting sidewalk	Preserve		Non-heritage
289	Platanus hispanica	Sycamore	15	3	Healthy tree with good structure, but lifting sidewalk	Preserve		Heritage
290	Prunus cerasifera	Plum	6	3	Young healthy tree, but overcrowded	Preserve		Non-heritage
291	Prunus cerasifera	Plum	10	3	Young healthy tree, but overcrowded	Preserve		Non-heritage
292	Quercus lobata	Valley Oak	29	3	Removal recommended; growing into parking garage and could cause damage to the structure. Mitigation: Prune away from structure to extent possible and monitor,	Mitigation	Structural/Health	Heritage
293	Platanus hispanica	Sycamore	13	2	Showing signs of die back	Preserve		Non-heritage
294	Acacia melanoxylon	Acacia	17	1	Removal recommended; tree has lost large limbs in the past and structure shows it will lose many more in the future; is a danger to residents.	Remove	Structural/Health	Heritage
295	Acacia melanoxylon	Acacia	21	1	Removal recommended; tree has lost large limbs in the past and structure shows it will lose many more in the future; is a danger to residents.	Remove	Structural/Health	Heritage
296	Eucalyptus spp.	Gum	22	2	Removal recommended; poor structure; tree has very few branches due to overcrowding and is too close to building; removal will allow for planting of a more suitable species.	Remove	Structural/Health	Heritage
297	Eucalyptus spp.	Gum	16	2	Removal recommended; poor structure; tree has very few branches due to overcrowding and is too close to building; removal will allow for planting of a more suitable species.	Remove	Structural/Health	Hentage



TREE NO.	BOTANICAL NAME	COMMON NAME	DBH	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
298	Pinus radiata	Monterey Pine	28	2	Removal recommended; has a heavy lean over parking garage and is at risk of failure.	Remove	Structural/Health	Heritage
299	Pinus radiata	Monterey Pine	35	2	Removal recommended; has a bad lean and could fail; located far too close to drain and is causing damage to pipes and walkways. Mitigation: Significantly reduce branch end weight through pruning, take additional weight off of the West side and monitor.	Mitigation	Structural/Health	Heritage
300	Pinus radiata	Monterey Pine	22	2	Healthy tree, minor deadwood	Preserve		Heritage
301	Pinus radiata	Monterey Pine	26	2	Healthy tree, minor deadwood	Preserve		Heritage
302	Ulmus parvifalia	Chinese Elm	12	2	Removal recommended; healthy tree with a significant lean; showing signs of uprooting.  Mitigation: Prune to reduce end weight and monitor.	Mitigation	Structural/Health	Non-heritage
303	Ulmus parvifolia	Chinese Elm	14	3	Tree is healthy, but heavy ended	Preserve		Non-heritage
304	Betula pendula	White Birch	11	3	Healthy tree, a little overcrowded; needs structure	Preserve		Non-heritage
305	Betula pendula	White Birch	11	3	Healthy tree, a little overcrowded; needs structure	Preserve		Non-heritage
306	Betula pendula	White Birch	10	3	Healthy tree, a little overcrowded; needs structure	Preserve		Non-heritage
307	Betula pendula	White Birch	12	3	Healthy tree, a little overcrowded; needs structure	Preserve		Non-heritage
308	Platanus hispanica	Sycamore	18	3	Healthy tree; but overgrown on garage side	Preserve		Heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	DBH	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
309	Platanus hispanica	Sycamore	12	3	Healthy tree, but overgrown	Preserve		Non-heritage
310	Platanus hispanica	Sycamore	11	3	Healthy tree, but overgrown	Preserve		Non-heritage
311	Platanus hispanica	Sycamore	12	3	Healthy tree, but overgrown	Preserve		Non-heritage
312	Piatanus hispanica	Sycamore	15	3	Healthy tree, but overgrown	Preserve		Heritage
313	Platanus hispanica	Sycamore	9	3	Healthy tree, but overgrown	Preserve		Non-heritage
314	Platonus hispanica	Sycamore	15	3	Healthy tree, but overgrown	Preserve		Heritage
315	Quercus douglassi	Blue Oak	27	2	Removal recommended; tree is overcrowded and growing into parking structure. Has large dead decaying limb.	Remove	Structural/Health	Heritage
316	Quercus douglassi	Blue Oak	33	2	Good health; but shows signs of trunk decay	Preserve		Heritage
317	Platanus hispanica	Sycamore	15	3	Large healthy tree, but overcrowded; ends of branches need reduction	Preserve		Heritage
318	Platanus hispanica	Sycomore	16	3	targe healthy tree, but overcrowded; ends of branches need reduction	Preserve		Heritage
319	Platanus hispanica	Sycamare	17	3	Large healthy tree, but overcrowded; ends of branches need reduction	Preserve		Heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	OBH	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
320	Platanus hispanica	Sycamore	21	3	Large healthy tree, but overcrowded; ends of branches need reduction	Preserve		Heritage
321	Betula pendula	White Birch	5	2	Young tree, over crowded	Preserve		Non-heritage
322	Betula pendula	White Birch	10	3	Young tree, over crowded	Preserve		Non-heritage
323	Betula pendula	White Birch	6	3	Young tree, over crowded	Preserve		Non-heritage
324	E. polyanthemos	Silver Dollar Eucalyptus	20	2	Removal recommended; tree has been topped in the past, therefore attachments are poor; located over a walkway and is a danger to residents. Mitigation: Significantly reduce branch end weight through pruning and monitor.	Mitigation	Structural/Health	Heritage
325	E. polyanthemos	Silver Dollar Eucalyptus	22	2	Removal recommended; tree has been topped in the past, therefore attachments are poor; located over a walkway and is a danger to residents. Mitigation: Significantly reduce branch end weight through pruning and monitor.	Mitigation	Structural/Health	Heritage
326	Betula pendula	White Birch	9	3	Healthy tree, but overgrown	Preserve		Non-heritage
327	Betula pendula	White Birch	6	3	Healthy tree, but overgrown	Preserve		Non-heritage
328	Betula pendula	White Birch	6	3	Healthy tree, but overgrown	Preserve		Non-heritage
329	Betula pendula	White Birch	6	3	Healthy tree, but overgrown	Preserve		Non-heritage
330	Betula pendula	White Birch	7	3	Healthy tree; heavy ends	Preserve		Non-heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	ОВН	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
331	Betula pendula	White Birch	10	3	Healthy tree; heavy ends	Preserve		Non-heritage
332	Betula pendula	White Birch	11	3	Healthy tree; heavy ends	Preserve		Non-heritage
333	Betula pendula	White Birch	12	3	Healthy tree; heavy ends	Remove	Construction	Non-heritage
334	E. polyanthemos	Silver Dollar Eucalyptus	10	2	Removal recommended; poorly structured tree, has been topped; recommend starting over with a new tree	Remove	Structural/Health	Non-heritage
335	Fraxinus uhdei	Shamel Ash	14	2	Thin tree due to building clearance	Preserve		Non-heritage
336	Fraxinus uhdei	Shomel Ash	12	1	Thin tree due to building clearance	Preserve		Non-heritage
337	Fraxinus uhdel	Shamel Ash	23	1	Thin tree due to building clearance	Preserve		Heritage
338	Fraxinus uhdei	Shamel Ash	20	1	Thin tree due to building clearance	Preserve		Heritage
339	Fraxinus uhdei	Shamei Ash	17	1	Thin tree due to building clearance	Preserve		Heritage
340	Fraxinus uhdei	Shamel Ash	17	1	Thin tree due to building clearance	Preserve		Heritage
341	Sequola sempervirens	Redwood	12	2	Young healthy tree	Preserve		Non-heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	D8H	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
342	Pinus radiata	Monterey Pine	42	2	Removal recommended; tree is in decline; too large for its location and is lifting sidewalk; falling cones pose a danger over the pool area. Broken branch resting on roof of bidg, Q	Remove	Structural/Health	Heritage
343	Pinus radiata	Monterey Pine	27	2	Removal recommended; tree is in decline; too large for its location and is lifting sidewalk; falling cones pose a danger over the pool area; too close to building and causing damage to foundation and pipes. Mitigation: Significantly reduce branch end	Mitigation	Structural/Health	Heritage
344	Pinus radiata	Monterey Pine	27	2	weight through reuning and monitor.  Removal recommended; tree is in decline; too large for its location and is lifting sidewalk; falling cones pose a danger over the pool area; too close to building and causing damage to foundation and pipes. Mitigation: Significantly reduce branch end weight through oruging and monitor.	Mitigation	Structural/Health	Heritage
345	Pyrus kawakamil	Evergreen Pear	7	3	Young healthy tree; needs end-weight reduction	Preserve		Non-heritage
346	Pyrus calleryana	Bradford Pear	8	3	Young healthy tree; needs end-weight reduction	Preserve		Non-heritage
347	Prunus cerasifera	Plum	4	3	Young healthy tree; needs end-weight reduction	Preserve		Non-heritage
348	Prunus cerasifera	Plum	4	3	Young healthy tree; needs end-weight reduction	Preserve		Non-heritage
349	Pyrus kawakamii	Evergreen Pear	9	3	Young healthy tree; needs end-weight reduction	Preserve		Non-heritage
350	Fraxinus uhdei	Shamel Ash	18	1	Removal recommended; Tree is heavy on the ends due to building clearance	Remove	Structural/Health	Heritage
351	Froxinus uhdei	Shamel Ash	28	1	Removal recommended; Tree is heavy on the ends due to building clearance	Remove	Structural/Health	Heritage
352	Fraxinus uhdel	Shamel Ash	15	1	Removal recommended; Tree is heavy on the ends due to building clearance	Remove	Structural/Health	Heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	DBH	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
353	Fraxinus uhdei	Shamel Ash	15	1	Removal recommended; Tree is heavy on the ends due to building clearance	Remove	Structural/Health	Heritage
354	Fraxinus uhdei	Shamel Ash	25	1	Removal recommended; Tree is heavy on the ends due to building clearance	Remove	Structural/Health	Heritage
355	Fraxinus uhdei	Shamel Ash	17	1	Removal recommended; Tree is heavy on the ends due to building clearance	Remove	Structural/Health	Heritage
356	Pinus radiata	Monterey Pine	35	2	Removal recommended; tree is much too large for its location and is damaging sidewalk, pipes, and garage; poses a danger to residents	Remove	Structural/Health	Heritage
357	Betula pendula	White Birch	7	3	Young healthy tree	Preserve		Non-heritage
358	Betula pendula	White Birch	10	3	Young healthy tree	Preserve		Non-heritage
359	Betula pendula	White Birch	9	3	Young healthy tree	Preserve		Non-heritage
360	Betula pendula	White Birch	11	3	Good health and vigor, however heavy on tops	Preserve		Non-heritage
361	Betula pendula	White Birch	11	3	Good health and vigor, however heavy on tops	Preserve		Non-heritage
362	Betula pendula	White Birch	9	3	Good health and vigor, however heavy on tops	Preserve		Non-heritage
363	Betula pendula	White Birch	6	3	Good health and vigor, however heavy on tops	Preserve		Non-heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	DBH	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
364	Betula pendula	White Birch	10	3	Good health and vigor, however heavy on tops	Preserve		Non-heritage
365	Quercus alba	White Oak	21	3	Healthy tree, however, looks thin	Preserve		Heritage
366	Quercus alba	White Oak	21	3	Removal recommended; healthy tree, however it is growing into the building and will soon damage it. Mitigation: Prune away from the building and monitor.	Mitigation	Structural/Heaith	Heritage
367	Betula pendula	White Birch	10	1	Removal recommended; Dead top, poor structure	Remove	Structural/Health	Non-heritage
368	Betula pendula	White Birch	9	3	Healthy tree, needs structure	Preserve		Non-heritage
369	Betula pendula	White Birch	6	2	Removal recommeded; Good health, but heavy competiton from stone pines, overcrowded.	Remove	Structural/Health	Non-hentage
370	Betula pendula	White Birch	9	2	Removal recommeded; Good health, but heavy competiton from stone pines, overcrowded.	Remove	Structural/Health	Non-heritage
371	Betula pendula	White Birch	8	2	Removal recommeded; Good health, but heavy competiton from stone pines, overcrowded.	Remove	Structural/Health	Non-heritage
372	E. palyanthemos	Silver Dollar Eucalyptus	14	2	Removal recommended; tree is a poor example of species, it has been topped in the past and is in a poor location; falling branches pose a danger to residents.	Remove	Structural/Health	Non-heritage
373	E. polyanthemos	Silver Dollar Eucalyptus	16	2	Removal recommended; tree is a poor example of species, it has been topped in the past and is in a poor location; falling branches pose a danger to residents.	Remove	Structural/Health	Heritage
374	Betula pendula	White Birch	5	2	Young tree in decline	Preserve		Non-heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	DBH	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
375	Betula pendula	White Birch	6	2	Removal recommended; Young tree in decline, very thin top	Remove	Structural/Health	Non-heritage
376	Betula pendula	White Birch	6		Tree died, removed summer of 2013			
377	Liriodendron tulipifera	Tulip Tree	10	3	Healthy tree with significant end-weight	Preserve		Non-heritage
378	Liriodendron tulipifera	Tulip Tree	11	3	Healthy tree with significant end-weight	Preserve		Non-heritage
379	Liriodendron tulipifera	Tulip Tree	10	3	Healthy tree with significant end-weight	Preserve	,	Non-heritage
380	Betula pendula	White Birch	12	3	Healthy tree with significant end-weight	Preserve		Non-heritage
381	Betula pendula	White Birch	6	3	Healthy tree with significant end-weight	Preserve		Non-heritage
382	Betula pendula	White Birch	5	3	Healthy tree with significant end-weight	Preserve		Non-heritage
383	Betula pendula	White Birch	9	3	Healthy tree with significant end-weight	Preserve		Non-heritage
384	Sequaia sempervirens	Redwood	31	4	Healthy, well-structured tree	Preserve		Heritage
385	Sequoia sempervirens	Redwood	21	4	Healthy, well-structured tree	Preserve		Heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	DBH	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
386	Sequoia sempervirens	Redwood	15	4	Healthy, well-structured tree	Preserve		Heritage
387	Sequola sempervirens	Redwood	28	4	Healthy, well-structured tree	Preserve		Heritage
388	Sequaia sempervirens	Redwood	15	4	Healthy, well-structured tree	Preserve		Heritage
389	Sequala sempervirens	Redwood	15	4	Healthy, well-structured tree	Preserve		Heritage
390	Betula pendula	White Birch	14	0	Removal recommended; tree is dead	Remove	Structurel/Health	Non-heritage
391	Pinus radiata	Monterey Pine	32	2	Removal recommended, tree lost large leader and has a thin canopy	Remove	Structural/Health	Heritage
392	Platanus hispanica	Sycomore	10	3	Healthy tree, but overgrown and crowded	Preserve		Non-heritage
393	Platanus hispanica	Sycamore	9	3	Healthy tree, but overgrown and crowded	Preserve		Non-heritage
394	Platanus hispanica	Sycamore	9	3	Healthy tree, but overgrown and crowded	Preserve		Non-heritage
395	Platanus hispanica	Sycamore	14	3	Healthy tree, but overgrown and crowded	Preserve		Non-heritage
396	Platanus hispanica	Sycamore	13	3	Healthy tree, but overgrown and crowded	Preserve		Non-heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	DВН	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
397	Platanus hispanica	Sycamore	9	3	Healthy tree, but overgrown and crowded	Preserve		Non-heritage
398	Platanus hispanica	Sycamore	9	3	Healthy tree, but overgrown	Preserve		Non-heritage
399	Platanus hispanica	Sycamore	9	3	Healthy tree, but overgrown and crowded	Preserve		Non-heritage
400	Platanus hispanica	Sycamore	14	3	Healthy tree, but overgrown and crowded	Preserve		Non-heritage
401	Pittosporum eugenioides	Pittosporum	10	3	Good health; has good structure	Preserve		Non-heritage
402	E.sideroxylon	Red Ironbark	24	3	Removal recommended; much too large for its location; there is a risk of limb failure due to poor structure and is a danger to residents.	Remove	Structural/Health	Heritage
403	Ulmus parvifolia	Chinese Elm	13	3	Tree is overcrowded by the Euc. behind	Preserve		Non-heritage
404	Ulmus parvifolia	Chinese Elm	12	2	Removal recommended. Tree is overcrowded by adjacent Eucalyptus. Tree has a lean and poor structure	Remove	Structural/Health	Non-heritage
405	E. polyanthemos	Silver Dollar Eucalyptus	32	1	Removal recommended; much too large for its location; there is a risk of limb failure due to poor structure and is a danger to residents.	Remove	Structural/Health	Heritage
406	E. polyanthemos	Silver Dollar Eucalyptus	20	1	Removal recommended; overcrowded; tree has been topped therefore structure is poor and poses a danger to the patios below. Mitigation: Significantly reduce branch end weight through pruning and monitor.	Mitigation	Structural/Health	Heritage
407	E. polyanthemos	Silver Dollar Eucalyptus	16	1	Removal recommended; overcrowded; tree has been topped therefore structure is poor and poses a danger to the patios below. Mitigation: Significantly reduce branch end weight through pruning and monitor.	Mitigation	Structurat/Health	Heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	рвн	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
408	E. polyanthemos	Silver Dollar Eucalyptus	22	1	Removal recommended; overcrowded; tree has been topped therefore structure is poor and poses a danger to the patios below. Mitigation: Significantly reduce branch end weight through pruning and monitor.	Mitigation	Structural/Health	Heritage
409	E. polyanthemos	Silver Dollar Eucalyptus	17	1	Removal recommended; overcrowded; tree has been topped therefore structure is poor and poses a danger to the patios below. Mitigation: Significantly reduce branch end weight through pruning and monitor.	Mitigation	Structural/Health	Heritage
410	Pinus radiata	Monterey Pine	31	2	Removal recommended; tree appears to be in decline and is damaging walkway, creating a trip hazard.	Remove	Structural/Health	Heritage
411	E.sideroxylon	Red Ironbark	27	2	Removal recommended; much too large for its location; there is a risk of limb failure due to poor structure and is a danger to residents.	Remove	Structural/Health	Heritage
412	E.sideroxylon	Red Ironbark	31	2	Removal recommended; much too large for its location; there is a risk of limb failure due to poor structure and is a danger to residents.		Structural/Health	Heritage
413	Prunus cerasifera	Plum	9	3	Tree is healthy and young	Preserve		Non-heritage
414	Prunus cerasifera	Plum	10	3	Tree is healthy and young	Preserve		Non-heritage
415	Pittosporum eugeniaides	Pittosporum	10	3	Good health, but overgrown	Preserve		Non-heritage
416	Pittosporum eugenioides	Pittosporum	10	3	Good health, but overgrown Preserve			Non-heritage
417	E. polyanthemas	Silver Dallar Eucalyptus	17	2	Removal recommended; tree is a poor example of species, it has been topped in the past and is in a poor location; falling branches pose a danger to residents.	Remove	Structural/Health	Heritage
418	Juniperus chinensis	Juniper	10	3	Good health and vigor, though it has a fair amount of deadwood	Remove	Construction	Non-heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	D8H	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Heaith, Construction)	Heritage Tree?
419	Quercus ilex	Holly Oak	11	4	Tree is one-sided due to overcrowding	Preserve		Non-heritage
420	Quercus agrifolia	Live Oak	19	2	Tree is overcrowded and thin	Preserve		Heritage
421	Quercus agrifolia	Live Oak	12	2	Tree is overcrowded and thin	Preserve	_	Heritage
422	Pinus radiota	Monterey Pine	33	2	Removal recommended; tree appears to be in decline and is damaging walkway, creating a trip hazard. Mitigation: Remove deadwood and monitor.	Mitigation	Structural/Health	Heritage
423	Pinus radiata	Monterey Pine	27	2	Tree is well pruned, but a little thin	Preserve		Heritage
424	Pinus radiata	Monterey Pine	29	2	Tree is well pruned, but a little thin	Preserve		Heritage
425	Platanus hispanica	Sycamore	10	3	Healthy tree, but branches too long	Preserve		Non-heritage
426	Platanus hispanica	Sycamore	14	3	Healthy tree, but branches too long	Preserve		Non-heritage
427	Platanus hispanica	Sycamore	14	3	Healthy tree, but branches too long	Preserve		Non-heritage
428	Platanus hispanica	Sycamore	9	3	Healthy tree, but branches too long	Preserve		Non-heritage
429	Platanus hispanica	Sycomore	13	3	Healthy tree, but branches too long	Preserve		Non-heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	DBH	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
430	Platanus hispanica	Sycamore	11	3	Healthy tree, but branches too long	Preserve		Non-heritage
431	Platanus hispanica	Sycamore .	9	3	Healthy tree, but branches too long	Preserve		Non-heritage
432	Platanus hispanica	Sycamore	14	3	Healthy tree, but branches too long	Preserve		Non-heritage
433	Platanus hispanica	Sycamore	18	3	Healthy tree, but branches too long	Preserve		Heritage
434	Platanus hispanica	Sycamore	16	3	Healthy tree, but branches too long	Preserve		Heritage
435	Platanus hispanica	Sycamore	14	3	Good health and vigor, in need of structure prune	Preserve		Non-heritage
436	Platanus hispanica	Sycamore	14	3	Good health and vigor, in need of structure prune	Preserve		Non-heritage
437	Platanus hispanica	Sycamore	12	3	Good health and vigor, in need of structure prune	Preserve		Non-heritage
438	Platanus hispanica	Sycamore	8	3	Good health and vigor, in need of structure prune	Preserve		Non-heritage
439	Populus tremula	Cottonwood Poplar	23	2	Removal reccommended; Large tree over park areas, heavy ends, large deadwood.  Mitigation: Remove deadwood and monitor.	Mitigation	Structural/Health	Heritage
440	Populus tremula	Cottonwood Poplar	26	2	Removal recommended; Large tree over park areas, heavy ends, large deadwood. Mitigation: Remove deadwood and monitor.	Mitigation	Structural/Health	Heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	DBH	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
441	Populus tremula	Cottonwood Poplar	23	2	Removal recommended; Large tree over park areas, heavy ends, large deadwood.  Mitigation: Remove deadwood and monitor.	Mitigation	Structural/Health	Heritage
442	Malus floribunda	Crab Apple	8	3	Young, vigorous tree	Preserve		Non-heritage
443	Malus floribunda	Crab Apple	8	3	Young, vigorous tree	Preserve		Non-heritage
444	Malus floribunda	Crab Apple	6	3	Young, vigorous tree	Preserve		Non-heritage
445	Malus floribunda	Crab Apple	10	3	Young, vigorous tree	Remove	Construction	Noл-heritage
446	Betula pendula	White Birch	6	3	Young, vigorous tree	Preserve		Non-heritage
447	Betula pendula	White Birch	6	3	Young, vigorous tree	Preserve		Non-heritage
448	Betula pendula	White Birch	10	3	Young, vigorous tree	Preserve		Non-heritage
449	Pinus radiata	Monterey Pine	31	3	Included bark, fair health	Preserve		Heritage
450	Pinus radiata	Monterey Pine	26	1	Removal recommended; tree is declining and has severely included bark on the limb over garage.	Remove	Structural/Health	Heritage
451	Platanus hispanica	Sycamore	12	3	Good health, but needs to be pruned for structure	Preserve		Noл-heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	DBH	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
452	Platanus hispanica	Sycamore	11	3	Good health, but needs to be pruned for structure	Preserve 		Non-heritage
453	Platanus hispanica	Sycamore	11	3	Good health, but needs to be pruned for structure	Preserve		Non-heritage
454	Platanus hispanica	Sycamore	10	3	Good health, but needs to be pruned for structure	Preserve		Non-heritage
455	Platanus hispanica	Sycamore	10	3	Good health, but needs to be pruned for structure	Preserve		Non-heritage
456	Platanus hispanica	Sycamare	11	3	Good health, but needs to be pruned for structure	Preserve		Non-heritage
457	Platanus hispanica	Sycamore	11	3	Good health, but needs to be pruned for structure	Preserve		Non-heritage
458	Platanus hispanica	Sycomore	13	3	Good health, but needs to be pruned for structure	Preserve		Non-heritage
459	Platanus hispanica	Sycamore	16	3	Good health, but needs to be pruned for structure	Preserve		Heritage
460	Pinus radiota	Manterey Pine	36	3	Good health and vigor, evidence of red turpetine beetle activity	Preserve		Heritage
461	Prunus caroliniana	Carolina Cherry	6	3	Good health and vigor; however, tree has lean	Preserve		Non-heritage
462	Quercus ilex	Hally Oak	10	3	Good health and vigor; however, tree has lean	Preserve		Non-heritage



TREE NO.	BOTANICAL NAME	COMMON NAME	DBH	CONDITION 1=Poor 2=Fair 3=Good 4=Very Good 5=Excellent	COMMENTS	Recommendation	Removal Reason (Structural/Health, Construction)	Heritage Tree?
463	Quercus lobata	Valley Oak	33	3	Appears healthy, but is showing some trunk decay	Preserve		Heritage
464	Pinus radiata	Monterey Pine	27	2	Removal recommended; located much too close to building and is causing damage to foundation and pipes. Mitigation: Reduce end weight and monitor.	Mitigation	Structural/Health	Heritage

#### **Certification of Performance**

That I have personally inspected the tree(s) and /or property referred to in this report and have stated my findings accurately. The extent of the evaluation and appraisal is stated in the attached report and the Terms and Conditions;

That I have no current or prospective interest in the vegetation or the property that is the subject of this report and I have no personal interest or bias with respect to the parties involved:

That the analysis opinions and conclusions stated herein are my own and are based on current scientific procedures and facts;

That my compensation is not contingent upon the reporting of a predetermined conclusion that favors the cause of the client or any other party nor upon the results of the assessment the attainment of stipulated results or the occurrence of any subsequent events;

That my analysis opinions and conclusion were developed and this report has been prepared according to commonly accepted Arboricultural practices;

I further certify that I am a Registered Consulting Arborist® by the American Society of Consulting Arborists (ASCA) and a Certified Arborist by the International Society of Arboriculture (ISA).

#### **Disclosure Statement**

Arborists are tree specialists who use their education, knowledge, training and experience to examine trees and recommend measures to enhance the beauty and health of trees and attempt to reduce the risk of living near trees. Clients may choose to accept or disregard the recommendations of the arborist or to seek additional advice.

Arborists cannot detect every condition that could possibly lead to the structural failure of a tree. Trees are living organisms that fail in ways we do not fully understand. Certain conditions are often hidden within trees or below the ground. Arborists cannot guarantee that a tree will be healthy or safe under all circumstances or for a specific period of time. Likewise remedial treatments cannot be guaranteed.

Trees can be managed but they cannot be controlled. To live near trees is to accept some degree of risk.

FUJIITREES CONSULTING, LLC

Walter Fujii, RCA®

Manager and Consulting Arborist

Date: July 12

Consulting

## Fujiitrees Consulting TERMS AND CONDITIONS

The following terms and conditions apply to all oral and written reports and correspondence pertaining to the consultations, inspections and activities of Fujiitrees Consulting hereinafter referred to as "Consultant".

- 1. Any legal description provided to the Consultant is assumed to be correct. No responsibility is assumed for matters legal in character nor is any opinion rendered as to the quality of any title.
- 2. It is assumed that any property referred to in any report or in conjunction with any services performed by the Consultant, is not in violation of any applicable codes, ordinances, statutes, or other governmental regulations, and that any titles and ownership to any property are assumed to be good and marketable. Any existing liens and encumbrances have been disregarded.
- 3. Possession of this report or a copy thereof does not imply any right of publication or use for any purpose, without the express permission of the Consultant and the Client to whom the report was issued. Loss, removal or alteration of any part of a report invalidates the entire appraisal/evaluation.
- 4. The scope of any report or other correspondence is limited to the trees and conditions specifically mentioned in those reports and correspondence. The Consultant assumes no liability for the failure of trees or parts of trees, either inspected or otherwise. The Consultant assumes no responsibility to report on the condition of any tree or landscape feature not specifically requested by the named client.
- 5. No tree described in this report was climbed, unless otherwise stated. The Consultant cannot take responsibility for any defects, which could only have been discovered by climbing. A full root crown examination (RCX), consisting of excavating the soil around the tree to uncover the root crown and major buttress roots was not performed unless otherwise stated. We cannot take responsibility for any root defects, which could only have been discovered by such an inspection.
- 6. The Consultant shall not be required to provide further documentation, give testimony, be deposed, or attend court by reason of this appraisal/report unless subsequent contractual arrangements are made, including payment of additional fees for such services as described by the consultant or in the fee schedules or contract.
- 7. The Consultant offers no guarantees or warrantees, either expressed or implied, as to the suitability of the information contained in the reports for any purpose. It remains the responsibility of the client to determine applicability to his/her particular case.
- 8. Any report and the values, observations, and recommendations expressed therein represent the professional opinion of the Consultant, and the fee for services is in no manner contingent upon the reporting of a specified value nor upon any particular finding to be reported.
- 9. Any photographs, diagrams, graphs, sketches, or other graphic material included in any report, being intended solely as visual aids, are not necessarily to scale and should not be construed as engineering reports or surveys, unless otherwise noted in the report. Any reproductions of graphs material or the work produce of any other persons is intended solely for the purpose of clarification and ease of reference. Inclusion of said information does not constitute a representation by the Consultant as to the sufficiency or accuracy of that information.
- 10. Trees can be managed, but they cannot be controlled. To live near trees is to accept some degree of risk. The only way to eliminate all risk associated with trees is to eliminate all trees.
- 11. Payment terms are net payable upon receipt of invoice. All balances due beyond 30 days of invoice date will be charged a service fee of 1.5 percent per month (18.0% APR). All checks returned for insufficient funds or any other reason will be subject to a \$25.00 service fee. Advance payment of fees may be required in some cases.



## Meador, Kaitlin M

From: Andrew Steven Kennard <akennard@stanford.edu>

**Sent:** Thursday, July 21, 2016 4:40 PM

**To:** Meador, Kaitlin M

**Subject:** Comment on proposed modifications at 350 Sharon Park Drive (Maximus Real Estate

Partners)

Follow Up Flag: Follow up Flag Status: Follow up

Dear Katie Meador,

I am a researcher at Stanford and a resident of Sharon Green Apartments (350 Sharon Park Drive), and I am writing to submit a comment on the proposed landscaping modifications in this complex. I received a notice about the proposed work which mentioned the possible removal of 39 heritage trees across the site.

I am dismayed to hear that the intended landscaping will remove any of these trees, which are one of the most valuable and cherished components of the Sharon Green grounds. These trees were the first thing that drew me into the Sharon Green site, and they left a strong impression on me as I was deciding to move into the complex. Sharon Green is distinguished from nearby apartment complexes by its large number and variety of trees. I've noticed pink ribbons wrapped around many of the trees in one area of the complex, and it appears that the proposed tree removal is concentrated in one particular area, so certain parts of the complex will lose all of the trees that are critical for the sense of space in Sharon Green.

These trees are not just nice to look at; they have also played a valuable role in generating community in our complex. At a recent resident barbeque, I got to know a family with two bright children by marveling with them at a leaf from one of these trees under my field microscope. It was wonderful to be able to excite the children with the love of nature in their own backyard, and the tree was central to our coming together as neighbors.

I appreciate that Maximus Real Estate wants to modernize the grounds of Sharon Green for a new generation, and I support this overall goal. But I urge them to reconsider the proposed landscaping changes to keep the existing trees, many of which are quite old and would take decades to replace with saplings. As a resident of the complex, I ask that in your review of this proposal you consider the important value of these heritage trees to our complex, and I hope you will recommend that Maximus include them in their plans for the renovated Sharon Green Apartments.

Thank you very much for your time.

Sincerely, Andrew Kennard Doctoral Candidate in Biophysics Stanford University

## THIS PAGE INTENTIONALLY LEFT BLANK

## AGENDA ITEM D-3 Community Development



#### **STAFF REPORT**

Environmental Quality Commission
Meeting Date: 8/31/2016
Staff Report Number: 16-007-EQC

Regular Business: Heritage Tree Removal Permits/Greenheart Land

Company/Station 1300 Project

#### Recommendation

Staff recommends that the Environmental Quality Commission (EQC) review and provide a recommendation to the Planning Commission and City Council on 59 Heritage Tree Removal Permits associated with the proposal by Greenheart Land Company to develop a mixed-use (residential, office, and community-serving uses) project on a 6.4-acre site at 1258-1300 El Camino Real, 550-580 Oak Grove Avenue, and 540-570 Derry Lane. The project is known as "Station 1300" or "1300 El Camino Real".

## **Policy Issues**

Each heritage tree permit request is considered individually with regard to the Heritage Tree Ordinance requirements.

## **Background**

Greenheart Land Company ("Greenheart") is proposing to redevelop a multi-acre site on El Camino Real and Oak Grove Avenue with up to 217,000 square feet of non-residential uses and approximately 183 dwelling units. A location map is included as Attachment A. The project would demolish all existing structures on the site and construct approximately 420,000 square feet of mixed uses. In total, the project would include three mixed-use buildings, a surface parking lot, an underground parking garage, onsite linkages, and landscaping. The uses at the project site would include approximately 188,900 to 199,300 square feet of non-medical office space in two buildings, approximately 202,100 square feet of residential space in one building, and up to 29,000 square feet of community-serving space throughout the proposed office and residential buildings. The project would provide approximately 1,000 parking spaces within an underground parking garage and a small surface parking lot. The project includes the abandonment of the dead-end, L-shaped Derry Lane and the dedication of a new Garwood Way extension, which would connect Oak Grove and Glenwood Avenues. Excerpts of the project plans are included for reference as Attachment B. The project requires Planning Commission review/recommendation and City Council action. The development would conform to the El Camino Real/Downtown Specific Plan.

## **Analysis**

The Environmental Quality Commission (EQC) is being asked to provide a recommendation on the proposed heritage tree removals, for the consideration of the Planning Commission and City Council. The City Council will consider and make all discretionary actions associated with the project, including the proposed heritage tree removals.

The applicant has submitted an arborist report prepared by SBCA Tree Consulting (Attachment C),

evaluating all trees on and near the subject property, including 59 heritage trees. The arborist report reflects updates and clarifications that were requested by the City's independent arborist peer review (described in a following section).

All of the on-site trees are proposed for removal due to the comprehensive nature of the development, with an underground parking garage that spans most of the project site. In addition, trees along the existing portion of Garwood Way and the street extension are proposed for removal, in order to build this new transportation connection, which would include a bicycle route and stormwater treatment area. Likewise, some trees on the El Camino Real and Oak Grove Avenue frontages are proposed for removal for new driveway and curb improvements, as well as to create a new comprehensive landscaping aesthetic. Separately from the Station 1300 project, the pending Caltrain electrification project is known to be affecting (either significant pruning or full removal) a number of trees near the rail corridor, so the Commission should keep in mind that some trees in this area may be removed or pruned, regardless of the Station 1300 actions.

### Municipal Code requirements

Section 13.24.040 of Menlo Park's Heritage Tree Ordinance, requires consideration of the following eight factors when determining whether there is good cause for permitting removal of a heritage tree:

- (1) The condition of the tree or trees with respect to disease, danger of falling, proximity to existing or proposed structures and interference with utility services;
- (2) The necessity to remove the tree or trees in order to construct proposed improvements to the property;
- (3) The topography of the land and the effect of the removal of the tree on erosion, soil retention and diversion or increased flow of surface waters:
- (4) The long-term value of the species under consideration, particularly lifespan and growth rate;
- (5) The ecological value of the tree or group of trees, such as food, nesting, habitat, protection and shade for wildlife or other plant species;
- (6) The number, size, species, age distribution and location of existing trees in the area and the effect the removal would have upon shade, privacy impact and scenic beauty;
- (7) The number of trees the particular parcel can adequately support according to good arboricultural practices;
- (8) The availability of reasonable and feasible alternatives that would allow for the preservation of the tree(s).

#### City Arborist review

The City Arborist has coordinated for an independent consulting arborist, Fujitrees Consulting, to review the applicant's arborist report, conduct a site visit to independently evaluate the health and condition of the heritage trees proposed for removal, and provide recommendations. This independent evaluation, which has been reviewed and approved by the City Arborist, is included as Attachment D.

The consulting arborist recommends approval of the requested removals in recognition of factors #1 (tree condition/health), #2 (construction conflicts), and #4 (long-term species value). In particular, the majority of

the heritage tree removals (59 percent) would be Chinese trees of heaven, which are multi-stem trees that were not deliberately planted and which have limited long-term value. In addition, as previously noted, the heritage trees conflict with the proposed comprehensive redevelopment of this site, which includes the construction of a new street that would serve in part as a bicycle connection, as well as a stormwater treatment area to filter the runoff from this roadway.

The consulting arborist made comments regarding a few specific trees, as follows:

## Tree #12 (Redwood)

The consulting arborist states that the large redwood tree at the front-left portion of the El Camino Real frontage is a high risk, as it exhibits "significant branch dieback with a slight trunk lean toward the roadway". Given its location near a major thoroughfare, the consulting arborist designates it "a tree of great concern that should not be ignored". The City Arborist has concurred that the tree (which had already been proposed for removal with the development project) should be removed as soon as possible, and has issued an immediate removal authorization. Although the City's typical process for Heritage Tree Removal Permits associated with development proposals involves waiting to issue such permits until the overall project has been acted on (so that the proposal can be considered comprehensively), the City Arborist can issue such permits immediately if a heritage tree is "imminently hazardous or dangerous to life or property," as is the case here. Such immediate removal authorizations cannot be appealed. The tree is scheduled for removal in early September.

## Tree #13.1 (Holly oak)

The consulting arborist requested that the applicant consider the potential to retain a non-heritage holly oak tree located near the front-right corner of the El Camino Real frontage. The applicant confirmed that this tree would conflict with the proposed El Camino Real sidewalk, which is proposed to be widened substantially to address Specific Plan requirements regarding enhanced pedestrian connectivity. The applicant also confirmed that relocation is not feasible given the comprehensive nature of the site redevelopment (i.e., this tree couldn't be moved to another part of the site, since the entire parcel is proposed to be affected by construction). In addition, while this tree is attractive and in good condition, holly oaks are not native to California, and as such are not protected by the Heritage Tree Ordinance's provisions regarding native oaks.

#### Tree #36 (Canary Island palm)

The consulting arborist also requested that the applicant consider the potential to retain a heritage Canary Island palm tree located near the left-rear property line, along Garwood Way. The applicant confirmed that this tree would conflict with the proposed new sidewalk along this improved/extended street. However, such palms are generally good candidates for transplanting, and, while there is not an on-site option for moving this specimen, the applicant is coordinating with J Arnaz Tree Movers to move it to an off-site location.

## Heritage tree replacements

The City has a heritage tree replacement guideline for commercial/mixed-use projects to replace trees at a 2:1 level. The replacements have to be of a type that can grow to heritage-size. The applicant is proposing to provide 120 heritage tree replacements to compensate for the loss of the 59 heritage trees, which would exceed the replacement requirement (118). The proposed replacements include 20 Chinese pistaches or Chinese elms, 21 date palms, 54 Lombary poplars or European hornbeams, 19 Armstrong gold maples or Dawyck beeches, and 6 Mexican fan palms. The City Arborist has identified that the poplars and beech trees are not ideal, as they can be short-lived and use high levels of water, respectively. In addition, the City Arborist recommends not considering the palms as heritage replacements, as they provide comparatively modest benefits in mitigating canopy loss. Staff will work with the project applicant to refine the planting plan

Staff Report #: 16-007-EQC

accordingly prior to Planning Commission and City Council consideration of the project.

Additional trees and landscaping would be planted throughout the site. The project would be required to comply with the Water Efficient Landscaping Ordinance (WELO).

#### Conclusion

Staff believes that the proposed removals would meet the Heritage Tree Ordinance's factors #1 (tree condition/health), #2 (construction conflicts), and #4 (long-term species value). Replacement trees would be planted at the 2:1 ratio for projects of this type, and additional water-efficient landscaping would added. Staff recommends that the Environmental Quality Commission recommend to the Planning Commission and City Council that the proposed heritage tree removals be approved in association with the proposed mixed-use project.

## **Impact on City Resources**

The project sponsor is required to pay Planning, Building and Public Works permit fees, based on the City's Master Fee Schedule, to fully cover the cost of staff time spent on the review of the project.

#### **Environmental Review**

A Draft Infill Environmental Impact Report (EIR) has been prepared for the project, and the required review period took place in February-April 2016. Comments received on the Draft Infill EIR will be responded to as part of the Final Infill EIR, which will be considered by the Planning Commission and City Council as part of the final project actions.

#### **Public Notice**


Public Notification was achieved by posting the agenda, with the agenda items being listed, at least 72 hours prior to the meeting. Public notification also consisted of notification by mail of owners and occupants within a 300-foot radius of the subject property.

#### **Attachments**

- A. Location Map
- B. Project Plan Excerpts
- C. Arborist Report, SBCA Tree Consulting
- D. Consulting Arborist Review, Fujitrees Consulting

Report prepared by:

Thomas Rogers, Principal Planner





## **CITY OF MENLO PARK**

LOCATION MAP STATION 1300

DRAWN: THR CHECKED: THR DATE: 08/31/16 SCALE: 1" = 300' SHEET: 1



## THIS PAGE INTENTIONALLY LEFT BLANK

Total Building

53,705

203,764

## PERSPECTIVE VIEW OF RESIDENTIAL BUILDING

# STATION 1300


## **DEVELOPMENT PERMIT APPLICATION AT ECR NE-R ZONING DISTRICT**

## **PROJECT DESCRIPTION**

ONE FOUR-STORY MULTI-FAMILY RESIDENTIAL BUILDING AND TWO THREE-STORY OFFICE BUILDINGS, ALL WITH NEIGHBORHOOD SERVING RETAIL. BUILDINGS SHARE AMENITIES, OPEN SPACES, AND ARE LOCATED OVER A TWO-LEVEL SUBTERRANEAN PARKING GARAGE.

## **AREA SUMMARY**

## **VICINITY MAP**



<b>ZONING KEY</b>	
-------------------	--



Υ	A0.0	Cover Sheet
Χ	A1.1	Area Plan - 1300 El Camino Real
Χ	A1.2	Site Plan - 1300 El Camino Real
X	A1.3	Address Plan - Station 1300
X	A2.B1	Parking Floor Plan - Level B1
Χ	A2.B2	Parking Floor Plan - Level B2
Χ	A2.C01	Office Floor Plan - Ground Floor
X	A2.C02	Office Floor Plan - Level 2
Χ	A2.C03	Office Floor Plan - Level 3
Χ	A2.C04	Office Floor Plan - Roof Plan
X	A2.R01	Residential Floor Plan - Level 1
Χ	A2.R02	Residential Floor Plan - Level 2
X	A2.R03	Residential Floor Plan - Level 3
X	A2.R04	Residential Floor Plan - Level 4
X	A2.R05	Residential Floor Plan - Roof Level
х Х	A2.R10	Enlarged Unit Plans - 1 Bedroom, Typical
х Х	A2.R11	Enlarged Unit Plans - 1 Bedroom, Typical
х Х	A2.R12	Enlarged Unit Plans - 2 Bedroom, Typical
х Х	A2.R13	Enlarged Unit Plans - 2 Bedroom, Typical
х Х	A2.R14	Enlarged Unit Plans - 2 Bedroom, Typical
X	A2.R15	Enlarged Unit Plans - 2 Bedroom, Typical
х Х	A2.R16	Enlarged Unit Plans - 3 Bedroom, Typical
х Х	A3.01	Level 1 Area Diagram
х Х	A3.02	Level 2 Area Diagram
л Х	A3.03	Level 3 Area Diagram
л Х	A3.04	Level 4 Area Diagram
^ Х	A3.B1	Parking Level B1 Area Diagram
^X	A3.B2	Parking Level B2 Area Diagram
^X	A4.01	Specific Plan Standards Compliance Diagram - ECR
^ X	A4.01	Exterior Elevations - North Office Building
^ X	A4.02A	Commercial Frontage and Ground Floor Transparency
^ X	A4.02A	Commercial Frontage and Ground Floor Transparency
^ X	A4.02b	Exterior Elevations - South Office Building
	A4.04	Specific Plan Standards Compliance Diagram - OakGrove
X X	A4.04	Specific Plan Standards Compliance Diagram - Garwood
х Х	A4.05	Exterior Elevations - Residential at Public R.O.W.s
	A4.00	Exterior Elevations - Residential at Courtyard
X v	A4.07	Exterior Elevations - Residential Rear
X 	A4.08	Existing Exterior Building Elevations (Oakgrove Ave.)
X 	A4.10	
X 	A5.01	Existing Exterior Building Elevations (ECR & Darry Ln.)  Streetscape at El Camino Boal
X 	A5.01	Streetscape at El Camino Real
X 		Streetscape at Oak Grove
X	A5.03	Streetscape at Garwood
X	A6.01	Building Cross Sections Site Sections
X 	A6.01a	Site Sections  Duilding Sections Office North Building FCB
X 	A6.10	Building Sections - Office - North Building - ECR
Χ	A6.11	Building Sections - Office - South Building -ECR
Χ	A6.12	Building Sections - Residential - Oak Grove
Χ	A6.13	Building Sections - South Residential @ Garwood
Χ	A6.14	Conceptual Details Office

Χ	A6.16	Conceptual Details Residential
Χ	A6.17	Conceptual Details Residential
Χ	A6.18	Conceptual Details Residential
Χ	A7.01	Color and Materials Board
Χ	A8.01	LEED Checklist
Χ	A8.02	Construction Phasing Plan
Χ	A8.03	Construction Phasing Plan
Χ	A9.01	Perspective Rendering - ECR Office View
Χ	A9.02	Perspective Rendering - Office Plaza View
Χ	A9.03	Perspective Rendering - Residential Entry at Oak Grove Ave
	•	

# 03 - LANDSCAPE x L-1.0 Landscape Site Plan x L-2.1 Landscape Enlargement Plan x L-2.2 Landscape Enlargement Plan x L-3.0 Proposed Tree Palette

Tree Removal Plan

		11.22.1.21.1.21.1.1.21.1.
02	CIVIII	
UZ -	CIVIL	
Χ	TM-1	Title Sheet
Χ	TM-2	Notes, Legends and Abbreviations
Χ	TM-3	Existing Conditions Plan
Χ	TM-4	Existing Parcelization Plan
Х	TM-5	Proposed Parcelization Plan
Χ	TM-6	Horizontal Control and Site Plan
Х	TM-7	Preliminary Grading Plan
Χ	TM-8	Preliminary Utility Plan
Х	TM-9	Preliminary Stormwater Control Plan
Х	TM-10	Preliminary Erosion Control Plan and Details
Х	TM-11	Best Management Practices
Х	TM-12	Fire Access Plan
Χ	TM-13	Fire Access Sections
Х	TM-14	Vehicular Circulation Plan
Х	TM-15	Details
Χ	TM-16	Details
Grar	nd total: 82	

	Included Floor A	Area (sf)			Excluded Floor	Area (sf)		9	¥
	Residential Units	Semi Enclosed Decks	Circulation	Amenity	Mechanical	Trash / Recycle	In Unit Shafts	Total Residential	Community Serving Use
L4	37,167	167	6,658	0	494	125	400	43,498	0
L3	45,949	228	8,044	0	553	125	500	53,668	0
L2	45,857	228	8,173	0	553	125	500	53,705	0
L1	34,508	161	7,932	3,491	545	125	350	45,547	7,346
Subtotal	163,481	784	30,807	3,491	2,145	500	1,750	196,418	7,346

	1 BDR	2 BDR	3 BDR	Total Level
L4	22	18	2	42
L3	28	21	2	51
L2	26	23	2	51
L1	22	15	2	39
Total	98	77	8	183
%	54%	42%	4%	100%

	Included Floor A	rea (sf)	_	Excluded Floor Ar	ea (sf)			Total Building (sf)
	N Office	S Office	Residential	Mechanical	Shafts	Total Office	Community Serving Uses	
L3	39,068	30,250	0	856	216	69,318	0	69,318
L2	40,512	34,906	0	856	216	75,418	0	75,418
L1	26,896	22,409	1,236	391	216	50,541	20,754	71,295
Subtotal	106,476	87,565	1,236	2,103	648	195,277	20,754	216,031

	Included Floor Area (sf) Excluded Floor Area (sf)										
	Parking Circulation		Bicycle Parking	Tenant Storage	Mechanical Residential	Mechanical Office	Total Garage (sf)				
B1	215,558	3,118	2,858	1,139	2,871	3,902	222,673				
B2	162,009	2,209	0	1,083	523	1,078	165,301				
Subtotal	377 567	5 327	2.858	2 222	3 394	4 980	387 974				

3% FAR	12,612
1% FAR	4,204
T Allowed Exclusion	16,816

3% Exclu	usion
Mech - Res	2,645
Mech - Office	2,103
Mech - Garage	5,999
T Mech Area Excluded	10,747
1% Exclu	
Central Plant	2.376

Total mechanical area is less than 3% FAR, so all mechanical area is excluded from gross square footage calculation. 16.04.325 C1

Total mechanical area (central plant) is less than 1% FAR, so all mechanical area is excluded from gross square footage calculation. 16.04.325 C2

Total Floor Area Permitted (sf)						
Site Area	280,269					
FAR	1.5					
Max Allowed Floor Area	420,404					
Max Allowed Office @ 50%	210,202					

Î.	Formula	Total OS (sf)
Common OS Required	183units x 100sf	18,300
Common OS Proposed		14,982
Mix Private, Common Required	(18,300-14,982)x1.25	4,148
Private OS Proposed		10,258
Total OS Mix Required	14,982 + 4,148	19,130
Total OS Mix Proposed	14982 + 10,258	25,240

CMP compliance standards requires 100sf of Open Space per Unit. In case of a Mix of Private and Common Open Space such Common OS shall be provided at a ratio equal to 1.25 square feet for each one sf of Private OS that is not provided.

	Resi.	Office	CSU	Total (sf)
Proposed (sf)	196,418	195,277	28,100	419,795
Max Allowed	NA	210,202	NA	420,404
Max Less Proposed		14,924.75		608.50

## **PROJECT TEAM**

GREENHEART LAND COMPANY BOB BURKE, STEVE PIERCE 621 HIGH STREET PALO ALTO, CA 94301 650.681.9334

12060

ARCHITECT:

BAR ARCHITECTS

STEPHEN HEGEDUS

901 BATTERY ST. #300

SAN FRANCISCO, CA 94111

415.293.5700

LANDSCAPE ARCHITECT:
JETT LANDSCAPE + DESIGN
BRUCE JETT
2 THEATRE SQUARE
ORINDA, CA 94563
925.4254.5422


CIVIL ENGINEER: BKF ENGINEERS TOM MORSE 150 CALIFORNIA ST. #650 SAN FRANCISCO, CA 94111 415.930.7900 STRUCTURAL ENGINEER: HOHBACH-LEWIN INC KEVIN MORTON 545 SANSOME ST. #850 SAN FRANCISCO, CA 94111 415.318.8520 SUSTAINABILITY CONSULTANT INTEGRAL GROUP INC STET SANBORN 427 13TH STREET OAKLAND, CA 94612 510.663.2070

MEP ENGINEER: TAYLOR ENGINEERING LLC STEVEN TAYLOR 1080 MARINA PARKWAY #501 ALAMEDA, CA 94501 510.263.1540

STATION 1300

1300 EL CAMINO REAL


**Cover Sheet** 



1300 EL CAMINO REAL

**Area Plan - 1300 El Camino Real** 


**BAR** architects





1300 EL CAMINO REAL

Site Plan - 1300 El Camino Real

**BAR** architects











1300 EL CAMINO REAL

Perspective Rendering - ECR Office View

**BAR** architects

08/11/2016







1300 EL CAMINO REAL


Perspective Rendering - Office Plaza View

7




1300 EL CAMINO REAPerspective Rendering - Residential Entry at Oak Grove Ave.


**BAR** architects



7.8/2016 A:21:31 PM C\0 REVITStation 1300 (Sarans -

CRLA #3335 · 2 Theatre Square #218 · Orinda CA · 94563








1300 EL CAMINO REAL


# Landscape Enlargement Plans















1300 EL CAMINO REAL

# Landscape Enlargement Plan










TYPE A TREE QTY: 5




BOTANICAL NAME: PLATANUS X HISPANICA COMMON NAME: LONDON PLANE TREE INSTALLATION SIZE: 24" BOX MATURE SIZE: 50'H X 40'W NOTE: SPECIES TO MATCH EXISTING ADJACENT STREET TREES



BOTANICAL NAME: PISTACIA CHINENSE COMMON NAME: CHINESE PISTACHE INSTALLATION SIZE: 24" BOX MATURE SIZE: 40'H X 30'W




BOTANICAL NAME: ULMUS PARVIFOLIA COMMON NAME: CHINESE ELM INSTALLATION SIZE: 24" BOX MATURE SIZE: 50'H X 30'W



BOTANICAL NAME: KOELREUTERIA BIPINNATA COMMON NAME: CHINESE FLAME TREE INSTALLATION SIZE: 24" BOX MATURE SIZE: 40'H X 30'W



BOTANICAL NAME: ULMUS 'EMERALD COMMON NAME: EMERALD SUNSHINE ELM INSTALLATION SIZE: 24" BOX MATURE SIZE: 35'H X 25'W





BOTANICAL NAME: ARBUTUS 'MARINA' COMMON NAME: MARINA STRAWBERRY TREE INSTALLATION SIZE: 24" BOX MATURE SIZE: 30'H X 20'W




BOTANICAL NAME: MAGNOLIA VIRGINIANA COMMON NAME: MOONGLOW SWEET BAY INSTALLATION SIZE: 24" BOX
MATURE SIZE: 35'H X 20'W






BOTANICAL NAME: PHOENIX DACTYLIFERA COMMON NAME: DATE PALM INSTALLATION SIZE: 16' BTF MATURE SIZE: 80'H X 20'W







INSTALLATION SIZE: 24" BOX MATURE SIZE: 35'H X 25'W




\*TYPE G TREE



BOTANICAL NAME: POPULUS NIGRA 'ITALICA' COMMON NAME: LOMBARDY POPLAR INSTALLATION SIZE: 15 GALLON MATURE SIZE: 60'H X 15'W




BOTANICAL NAME: CARPINUS BETULUS 'FASTIGIATA' COMMON NAME: EUROPEAN HORNBEAM INSTALLATION SIZE: 15 GALLON MATURE SIZE: 50'H X 25'W





BOTANICAL NAME: LAGERSTROEMIA INDICA X FAURIEI 'ZUNI' COMMON NAME: ZUNI CRAPE MYRTLE INSTALLATION SIZE: 15 GALLON MATURE SIZE: 12'H X 10'W






BOTANICAL NAME: ACER RUBRUM 'ARMSTRONG GOLD'
COMMON NAME: ARMSTRONG GOLD MAPLE INSTALLATION SIZE: 24" BOX MATURE SIZE: 50'H X 12'W




BOTANICAL NAME: FAGUS SYLVATICA 'DAWYCK' COMMON NAME: DAWYCK BEECH INSTALLATION SIZE: 24" BOX MATURE SIZE: 50'H X 12'W



QTY: 12



BOTANICAL NAME: LAGERSTROEMIA 'NATCHEZ' COMMON NAME: FLOWERING WHITE CRAPE MYRTLE INSTALLATION SIZE: 24" BOX MATURE SIZE: 25'H X 12'W




QTY: 1



BOTANICAL NAME: HALESIA CAROLINA 'WEDDING BELLS' INSTALLATION SIZE: 24" BOX




BOTANICAL NAME: ACER PALMATUM VAR. ATROPURPUREUM 'BLOODGOOD'
COMMON NAME: BLOODGOOD JAPANESE MAPLE INSTALLATION SIZE: 24" BOX MATURE SIZE: 20'H X 15'W



TYPE F TREE QTY: 26



BOTANICAL NAME: LOPHOSTEMON CONFERTUS COMMON NAME: BRISBANE BOX INSTALLATION SIZE: 24" BOX MATURE SIZE: 40'H X 25'W



BOTANICAL NAME: GEIJERA PARVIFOLIA COMMON NAME: AUSTRALIAN WILLOW



INSTALLATION SIZE: 20' BTF MATURE SIZE: 100'H X 10'W


TREE REPLACEMENT: THE TOTAL HERITAGE TREES REMOVAL: 59 REQUIRED REPLACEMENT TREES (2:1 RATIO): 118 TOTAL PROPOSED TREES: 270 (15 GALLON MINIMUM, 40' MIN. \*DESIGNATED HÉRITAGE REPLACEMENT TREE: 120 PROVIDED



1300 EL CAMINO REAL

**Proposed Tree Palette** 







7/6/2016 4:21:31 PM C:\0 REVIT\Station 130

CRLA #3335 · 2 Theatre Square #218 · Orinda CA · 94563

925.254.5422 · www.jett.land





## THIS PAGE INTENTIONALLY LEFT BLANK

## SBCA TREE CONSULTING

Steve Batchelder, Consulting Arborist 1534 Rose Street, Crockett, CA 94525 WC ISA Certified Arborist #228 CUFC Certified Urban Forester #134 Calif. Contractor Lic. (C-27) 533675 Phone (510) 787-3075, Fax (510) 787-3065

E-mail: steve@sbcatree.com

Date: Amendment 5- August 10, 2016

To: Bob Burke, Greenheart Land Company

Box 22263321 621 High Street Palo Alto, CA 94301

Subject: Tree Survey

Location: 1300 El Camino Real & Derry, Menlo Park

Scope: Survey includes all Heritage Trees on or directly adjacent to parcels at 1300 El Camino

Real and Derry Lane and includes all adjacent City Street Trees which may or may not be of Heritage size. *Tree tagging numbering system is from 1-100 and 201-212. Trees* 

added by Fugiitrees Consulting are numbered with decimals.

## Introduction

Arborist submitted initial tree survey report on 11-7-13. We returned to the site two additional times to survey all adjacent street trees and any additional trees that may have attained "Heritage" status. Two Canary Island Date Palms (*Phoenix canariensis*) have since been removed subsequent to the 11-7-13 survey.

Amendment 4 included additional 38 trees surveyed by Fugiitrees, three of which are Heritage. Amendment 5 includes 5 additional City street trees to be removed.

Appendices are as follows.

- Appendix 1 Tree Survey Data
- Appendix 2 Tree Location Map
- Appendix 3 Tree Protection Guidelines

## City of Menlo Park Ordinance, Chapter 13.24

A permit is required to remove or heavily prune trees of heritage size. Any development related work performed within an area 10 times the diameter of a Heritage Tree requires the submittal of tree protection plan.

#### Heritage Trees are defined as:

- An oak tree (*Quercus*) which is native to California and has a trunk with a circumference of 31.4 inches (diameter of 10 inches) or more, measured 54 inches above natural grade.
- All trees other than oaks which have a trunk with a circumference of 47.1 inches (diameter of 15 inches), measured 54 inches above natural grade.
- Trees with more than one trunk shall be measured at the point where the trunks divide. Heritage trees must be greater than 12 feet tall.

## **Summary**

- Arborist survey identifies one-hundred forty-eight (148) trees located on the parcels or immediately adjacent. Two palms that were previously surveyed in 2013 have since been removed. All trees located within the parcels designated for development are proposed for removal.
- Eighteen (18) tree species were identified.
- Fifty-nine (59) trees are of Heritage size.
- Sixty-five (65) City Street Trees were identified. Many are seedling Coast Live Oaks (*Quercus agrifolia*) located along Garwood Way.
- The most numerous species was the Chinese Tree of Heaven (Ailanthus altissima) with fortyeight (48) specimens identified. Most of the Ailanthus trees are multi-stemmed with numerous root sprouts. Flagging tape marks the surveyed Heritage specimens which are located in large stands.
- The Coast Live Oak was the second most numerous species identified, with thirty-four (34) specimens. Flagging tape marks the smaller specimens identified as Street Trees along Garwood Way.
- Coast Redwood #12 (Sequoia sempervirens) is a large tree, almost dead, and is not considered to be structurally sound. It would be best to remove this tree as soon as it is possible due to the potential "target" should it fail.
- One-hundred thirty-eight (138) trees are proposed for removal. These include forty-seven (47) trees within the parcels and fifty-three (53) City Street Trees.

## **Survey Procedure**

<u>Trees Tagged</u> – Each tree was tagged with a metal number tag corresponding with the number used on the tree location map. Aluminum tags were attached to trees with an aluminum nail; a wire was used for the smaller seedling oaks. Tree tagging numbering is from #1-100 and #201-212. Fugiitrees Consulting surveyed an additional 38 trees, and utilized numbers with decimal points (e.g. 5.1. 5.2).



<u>Data Recorded</u> – Arborists recorded data on tree species, diameter (DBH¹), tree crown spread, structural safety condition, tree health. Notes were recorded to provide commentary on general conditions.

<u>Measuring Ailanthus Suckers</u> –As per directions from City Arborist, "If Ailanthus have stand-alone stems of the same tree in a clonal type of clumping, the measurements can be taken individually (not a combined measurement). If the stems are visibly joined at grade, the measurement is taken at the base of the union."

<u>City Street Trees</u> –There is no minimum diameter for Street Trees. All street trees received metal number tags as well. The City right of way at on Oak Grove Ave is 11' from edge of gutter. The right of way on Derry Ln. is 4'. All trees located on Garwood Way are considered have street tree status.

- 65 Identified City street trees include the following:
  - 41 Trees on Garwood Way (#33-39, #64, #65, and #76-100, #201-207)
  - > 5 Trees on Oak Grove (#41-45)
  - 4 Trees on Derry Lane (#27, 30, 30.1 and 30.2)
  - > 15 London Plane trees in sidewalk along El Camino Real (#47-61)

<u>Table 1</u> – The table below provides a breakdown of numbers of each of 18 tree species surveyed.

Species	Common Name	Total Amoun t	Heritag e Tree	Street Tree	Proposed Removals	Comments
Acacia melanoxylon	Blackwood Acacia	3	1	2	3	
Acer palmatum	Japanese Maple	2	0	0	2	
Afrocarpus gracilior	African Fern Pine	7	3	0	7	5 w Poor structures
Ailanthus altissima	Chinese Tree of Heaven	48	35	6	48	Naturalized, Most trees are spreading through root sucker growth.
Cupressus sempervirens	Italian Cypress	9	2	0	9	2nd in a line of 7 cypress; Only this one cypress has reached Heritage size
Jacaranda mimosifolia	Jacaranda	4	4	0	4	Healthy, 3 are multi-stemmed
Malus sp.	Apple	1	0	1	1	
Phoenix canariensis	Canary Island Date Palm	1	1	1	1	2 have been cut down since initial survey
Platanus x hispanica	London Plane Tree	18	0	18	8	3 trees on Oak Grove are in poor condition; 15 along El Camino Real are nice trees
Prunus caroliniana	Carolina Laurel Cherry	10	0	0	10	

<sup>&</sup>lt;sup>1</sup> DBH is tree diameter measured at 54 inches above soil grade.

SBCA Tree Consulting 1534 Rose St. Crockett, CA 94525



Species	Common Name	Total Amoun t	Heritag e Tree	Street Tree	Proposed Removals	Comments
Pyrus kawakamii	Evergreen Pear	1	0	1	1	
Quercus agrifolia	Coast Live Oak	34	5	31	34	2 large specimens, A number of seedlings on Garwood
Quercus ilex	Holly Oak	1	0	0	1	
Quercus Iobata	Valley Oak	2	2	2	2	Health mitigation required
Quercus rubra	Red Oak	1	0	1	1	
Robinia pseudoacacia	Black Locust	1	1	1	1	Growing in fence
Sequoia sempervirens	Coast Redwood	4	4	1	4	#12 is hazardous; all others are in good condition
Washingtonia robusta	Mexican Fan Palm	1	1	0	1	Volunteer
	Totals	148	59	65	138	

## **End Report**

Appendices are as follows.

- Appendix 1 Tree Survey Data
- Appendix 2 Tree Location Map
- Appendix 3 Tree Protection Guidelines

Report Submitted By:

Store Botch

Steve Batchelder, Consulting Arborist ISA Certified Arborist WE 228A CaUFC Certified Urban Forester #138 Calif. Contractor Lic. (C-27) 533675



## 1300 El Camino Real and Derry Lane Heritage Tree Survey

#### COLUMN HEADING DESCRIPTIONS

Tag# - Indicates the number tag attached to tree

Species - Scientific name

Common Name - Vernacular name

DBH - Diameter measured in inches at 4.5 feet above soil grade; For multiple stemmed trees, measurements were taken at the point where the

trunks divide; For palms, measurements are made from the tree base to the point where fonds emanate

Spread- In feet

Structure- Tree Structural Safety: E is Excellent, G is Good, F is Fair, P is Poor, H is Hazardous

Health -Tree Health: E is Excellent, G is Good, F is Fair, P is Poor, D is Dead or Dying

City Street Tree - Y is Yes, N is No Heritage Tree - Y is Yes, N is No Proposed Removal - Y is Yes, N is No

Notes - See below

#### ABBREVIATIONS AND DEFINITIONS

Embedded Bark (EB) - AKA Included Bark, this is a structural defect where bark is included between the branch attachment so that the wood cannot join. Such defects have a higher propensity for failure.

Codominant (CD) - A situation where a tree has two or more stems which are of equal diameter and relative amounts of leaf area. Trees with codominant primary scaffolding stems are inherently weaker than stems, which are of unequal diameter and size.

Notes

Codominant w/ Embedded Bark (CDEB) - When bark is embedded between codominant stems, failure potential is very high and pruning to mitigate the defect is recommended.

Poor Pruning (PP)- Past pruning practices considered unacceptable according to ANSI A300 Best Management Practices, Tree Pruning

Headed (H) - Generally considered poor pruning practice which removes the central leader and the internode.

Tag	; #	Species	Common Name	DBH	Spread	Structure	Health	City Street Tree	Heritage Tree?	Proposed Removal	Notes
1	•	Sequoia sempervirens	Coast Redwood	28	25	O	F	Z	Υ	Υ	Off color, Signs of stress, Botryosphaeria?
2		Ailanthus altissima	Chinese Tree of Heaven	28 @ base	36	F - P	F	N	Υ	Υ	Multi
3		Ailanthus altissima	Chinese Tree of Heaven	24 @ base	30	F - P	F	N	Υ	Υ	Multi

Tag #	Species	Common Name	DBH	Spread	Structure	Health	City Street Tree	Heritage Tree?	Proposed Removal	Notes
4	Ailanthus altissima	Chinese Tree of Heaven	24 @ base	15	F - P	F	N	Υ	Υ	Multi, Clump of 4 stems
5	Ailanthus altissima	Chinese Tree of Heaven	15 @ base	20	F-P	F	N	Υ	Υ	Multi, Clump of 3 stems
6	Ailanthus altissima	Chinese Tree of Heaven	18 @ base	30	F - P	F	N	Υ	Y	Multi, Clump of 3 stems
7	Ailanthus altissima	Chinese Tree of Heaven	30 @ base	45	Р	F	N	Υ	Y	Multi, EB
8	Ailanthus altissima	Chinese Tree of Heaven	28 @ base	35	Р	F	N	Υ	Υ	Multi
9	Ailanthus altissima	Chinese Tree of Heaven	40 @ base	30	F-P	F	N	Υ	Y	Multi
10	Acacia melanoxylon	Blackwood Acacia	24	35	Р	G	N	Υ	Υ	CDEB
11	Cupressus sempervirens	Italian Cypress	15 @ base	10	F	F	N	Υ	Υ	CD, 2nd in a line of 7 cypress
12	Sequoia sempervirens	Coast Redwood	54	40	P - H	P - D	N	Υ	Y	Significant tip dieback, Dead CD top, 27" x 10' (rotting) wound on side facing street, Slight lean to street
13	Jacaranda mimosifolia	Jacaranda	27 @ base	25	F	G	N	Υ	Υ	Multi
14	Jacaranda mimosifolia	Jacaranda	28 @ base	30	Р	G	N	Υ	Υ	EB, Multi
15	Jacaranda mimosifolia	Jacaranda	26 @ base	25	F	G	N	Υ	Y	Multi, PP
16	Jacaranda mimosifolia	Jacaranda	15	25	F	G	N	Υ	Υ	CD
17	Ailanthus altissima	Chinese Tree of Heaven	32 @ base	40	Р	F	N	Υ	Y	Multi, CDEB, EB
18	Ailanthus altissima	Chinese Tree of Heaven	22 @ base	35	F-P	F	N	Υ	Y	Multi, Basal damage, Metal in tree
19	Ailanthus altissima	Chinese Tree of Heaven	20 @ base	20	Р	F	N	Υ	Υ	Multi, Clump of 6 stems, CDEB

Tag #	Species	Common Name	DBH	Spread	Structure	Health	City Street Tree	Heritage Tree?	Proposed Removal	Notes
20	Ailanthus altissima	Chinese Tree of Heaven	30 @ base	30	Р	F	N	Υ	Υ	Multi
21	Quercus agrifolia	Coast Live Oak	20 @ base	20	Р	F	N	Υ	Υ	Multi, EB
22	Ailanthus altissima	Chinese Tree of Heaven	48 @ base	70	Р	G	N	Υ	Υ	Multi, multi, EB, EB branch breakout
23	Ailanthus altissima	Chinese Tree of Heaven	72 @ base	50	Р	F-G	N	Y	Υ	Multi, Clump of 9 stems, EB
24	Afrocarpus gracilior	African Fern Pine	15	25	G	G	N	Υ	Υ	CD
25	Afrocarpus gracilior	African Fern Pine	15 @ base	20	Р	F	N	Υ	Υ	CDEB
26	Afrocarpus gracilior	African Fern Pine	15 @ base	15	Р	G	N	Υ	Υ	CDEB
27	Ailanthus altissima	Chinese Tree of Heaven	17 @ base	20	Р	F	Y	Υ	Υ	CDEB, PP, H
28	Quercus agrifolia	Coast Live Oak	23	50	F	F	N	Υ	Υ	PP, Wound at base, 20' from curb
29	Sequoia sempervirens	Coast Redwood	103 @ base	50	F	F	N	Υ	Υ	Multi, Off color, Signs of stress, 20' from curb
30	Sequoia sempervirens	Coast Redwood	32.5 @ base	30	G	G	Y	Y	Y	Hardscape displacement
31	Phoenix canariensis	Canary Island Date Palm								Gone
32	Phoenix canariensis	Canary Island Date Palm								Gone
33	Quercus agrifolia	Coast Live Oak	40.5	60	Р	G	Y	Y	Υ	Off site, 13' from property line, CD, Trunk rotted out on north side
34	Robinia pseudoacacia	Black Locust	30 @ base	25	Р	F	Y	Υ	Υ	On property line, Clump of 7 stems, Growing in fence
35	Ailanthus altissima	Chinese Tree of Heaven	24 @ base	40	Р	F	Y	Y	Υ	Multi, On property line, Clump of 10 stems, 5' from street
36	Phoenix canariensis	Canary Island Date Palm	20' of Clear Trunk	n/a	G	G	Y	Υ	Υ	Off site , 4' from street

Tag #	Species	Common Name	DBH	Spread	Structure	Health	City Street Tree	Heritage Tree?	Proposed Removal	Notes
37	Quercus lobata	Valley Oak	32	65	F	F	Y	Υ	Y	Off site, 7' from property line, 2' from curb, Previous #53, Large (rotting) pruning wound, PP
38	Quercus agrifolia	Coast Live Oak	10	20	F	G	Υ	Υ	Υ	Large breakouts, Pruning wounds, Lean for light
39	Quercus lobata	Valley Oak	23.5	40	F	Р	Υ	Υ	Υ	8' from curb
40	Ailanthus altissima	Chinese Tree of Heaven	20 @ base	20	F	F	N	Υ	Υ	Multi, Part of a large 70' long stand
41	Platanus x hispanica	London Plane Tree	12.5	20	Р	Р	Υ	N	Υ	Street tree, Pruning wounds, ID, Previously headed
42	Platanus x hispanica	London Plane Tree	12.5	30	Р	F	Υ	N	Υ	Street tree, Pruning wounds, ID, Previously headed
43	Platanus x hispanica	London Plane Tree	12.5	30	Р	F	Υ	N	Υ	Street tree, ID, Previously headed
44	Quercus agrifolia	Coast Live Oak	1	5	F	F	Υ	N	Υ	Good push of new growth
45	Pyrus kawakamii	Evergreen Pear	13	30	F	G	Υ	N	Υ	Large pruning wounds, CD
46	Washingtonia robusta	Mexican Fan Palm	7' of Clear Trunk	15	G	G	N	Y	Y	Close to building, Volunteer?
47	Platanus x hispanica	London Plane Tree	11	25	F	F-G	Υ	N	N	Street tree, Lean, CD
48	Platanus x hispanica	London Plane Tree	11	25	G	F-G	Υ	N	N	Lean
49	Platanus x hispanica	London Plane Tree	9	25	G	F-G	Υ	N	N	Lean
50	Platanus x hispanica	London Plane Tree	11.5	30	G	F-G	Υ	N	N	CD, Touching metal grate
51	Platanus x hispanica	London Plane Tree	11	30	G	G	Y	N	N	CD, Touching metal grate
52	Platanus x hispanica	London Plane Tree	10.5	30	G	G	Y	N	N	CD, Touching metal grate
53	Platanus x hispanica	London Plane Tree	11.5	30	G	G	Υ	N	Υ	CD, Touching metal grate

Tag #	Species	Common Name	DBH	Spread	Structure	Health	City Street Tree	Heritage Tree?	Proposed Removal	Notes
54	Platanus x hispanica	London Plane Tree	10	30	G	F-G	Υ	N	Υ	Large pruning wounds, CD, touching metal grate
55	Platanus x hispanica	London Plane Tree	10	30	G	F-G	Y	N	Υ	No grate
56	Platanus x hispanica	London Plane Tree	8.5	30	G	F-G	Y	N	Υ	
57	Platanus x hispanica	London Plane Tree	10	30	G	F-G	Y	N	N	Touching metal grate
58	Platanus x hispanica	London Plane Tree	11	30	G	G	Y	N	N	Lean
59	Platanus x hispanica	London Plane Tree	10	30	G	G	Y	N	N	
60	Platanus x hispanica	London Plane Tree	6	20	G	F	Y	N	Υ	Smaller than others, likely shaded by adjacent redwood
61	Platanus x hispanica	London Plane Tree	7.5	20	G	F	Y	N	N	
62	Ailanthus altissima	Chinese Tree of Heaven	18 @ base	45	Р	G	N	Y	Υ	CDEB, Multi
63	Quercus agrifolia	Coast Live Oak	10.5 @ base	20	F-P	G	N	Υ	Υ	3 stems
64	Acacia melanoxylon	Blackwood Acacia	12.5	25	F	G	Y	N	Υ	Lean, Trunk damage, 2-3' from curb
65	Acacia melanoxylon	Blackwood Acacia	8.5	25	G	G	Y	N	Υ	Slight lean, 5' from end of pavement
66	Ailanthus altissima	Chinese Tree of Heaven	34.5 @ base	20	Р	G	N	Y	Υ	Multi, Part of a large 70' long stand
67	Ailanthus altissima	Chinese Tree of Heaven	21 @ base	15	Р	G	N	Υ	Υ	Multi, Part of a large 70' long stand
68	Ailanthus altissima	Chinese Tree of Heaven	20 @ base	20	Р	G	N	Y	Υ	Multi, Part of a large 70' long stand
69	Ailanthus altissima	Chinese Tree of Heaven	18 @ base	25	Р	G	N	Υ	Υ	Multi, Part of a large 70' long stand
70	Ailanthus altissima	Chinese Tree of Heaven	19 @ base	20	Р	G	N	Υ	Υ	Multi, Part of a large 70' long stand
71	Ailanthus altissima	Chinese Tree of Heaven	16 @ base	25	Р	G	N	Υ	Υ	Multi, Part of a large 70' long stand

Tag #	Species	Common Name	DBH	Spread	Structure	Health	City Street Tree	Heritage Tree?	Proposed Removal	Notes
72	Ailanthus altissima	Chinese Tree of Heaven	15 @ base	25	Р	G	N	Υ	Y	Multi, Part of a large 70' long stand
73	Ailanthus altissima	Chinese Tree of Heaven	21 @ base	20	Р	G	N	Υ	Υ	Multi, Part of a large 70' long stand
74	Ailanthus altissima	Chinese Tree of Heaven	16 @ base	15	Р	G	N	Υ	Υ	Multi, Part of a large 70' long stand
75	Ailanthus altissima	Chinese Tree of Heaven	22 @ base	20	Р	G	N	Y	Υ	Multi, Pruning left larger stumps
76	Quercus agrifolia	Coast Live Oak	1 3/4	5	G	G	Y	N	Υ	Diameter taken below first branching
77	Quercus agrifolia	Coast Live Oak	1	5	G	F	Y	N	Y	Diameter taken below first branching
78	Quercus agrifolia	Coast Live Oak	3 3/4	10	G	G	Y	N	Y	Diameter taken below first branching
79	Quercus agrifolia	Coast Live Oak	4	10	F	G	Y	N	Y	CD
80	Quercus agrifolia	Coast Live Oak	4.5	20	F	G	Y	N	Y	Pruning wounds
81	Quercus agrifolia	Coast Live Oak	6	25	F	G	Y	N	Y	Large pruning wounds, CD
82	Malus sp.	Apple	3	5	G	G	Y	N	Y	
83	Quercus agrifolia	Coast Live Oak	3	10	G	G	Y	N	Y	Diameter taken below first branching. CD
84	Quercus agrifolia	Coast Live Oak	3	20	F	G	Y	N	Y	Diameter taken below first branching
85	Quercus agrifolia	Coast Live Oak	1	5	G	G	Y	N	Υ	Diameter taken below first branching
86	Quercus agrifolia	Coast Live Oak	5 3/4	20	G	G	Y	N	Y	Diameter taken below first branching
87	Quercus agrifolia	Coast Live Oak	0.5	3	G	G	Y	N	Υ	Diameter taken below first branching
88	Quercus agrifolia	Coast Live Oak	1	3	G	G	Y	N	Υ	Diameter taken below first branching
89	Quercus agrifolia	Coast Live Oak	3/4	3	G	G	Υ	N	Υ	Diameter taken below first branching

Tag #	Species	Common Name	DBH	Spread	Structure	Health	City Street Tree	Heritage Tree?	Proposed Removal	Notes
90	Quercus agrifolia	Coast Live Oak	0.5	3	G	G	Y	N	Υ	Diameter taken below first branching
91	Quercus agrifolia	Coast Live Oak	1.5	3	G	G	Υ	N	Υ	Diameter taken below first branching
92	Quercus agrifolia	Coast Live Oak	1	3	G	G	Υ	N	Υ	Diameter taken below first branching
93	Quercus agrifolia	Coast Live Oak	3.5	15	G	G	Υ	N	Υ	Diameter taken below first branching
94	Quercus agrifolia	Coast Live Oak	2	15	G	G	Υ	N	Υ	Diameter taken below first branching
95	Quercus agrifolia	Coast Live Oak	0.5	5	G	G	Υ	N	Υ	Diameter taken below first branching
96	Quercus agrifolia	Coast Live Oak	1.5	5	G	G	Υ	N	Υ	Diameter taken below first branching
97	Quercus agrifolia	Coast Live Oak	1.5	10	G	G	Υ	N	Υ	Diameter taken below first branching
98	Ailanthus altissima	Chinese Tree of Heaven	4	20	G	F	Υ	N	Υ	
99	Ailanthus altissima	Chinese Tree of Heaven	3.5	20	F	F	Υ	N	Υ	
100	Ailanthus altissima	Chinese Tree of Heaven	7.5	25	G	Р	Υ	N	Υ	
201	Quercus agrifolia	Coast Live Oak	1.5	5	G	G	Υ	N	Υ	Diameter taken below first branching
202	Quercus agrifolia	Coast Live Oak	1	5	G	G	Υ	N	Υ	Diameter taken below first branching
203	Quercus agrifolia	Coast Live Oak	1.5	5	G	G	Y	N	Υ	Diameter taken below first branching
204	Quercus agrifolia	Coast Live Oak	2.5	10	G	G	Υ	N	Υ	Diameter taken below first branching
205	Quercus agrifolia	Coast Live Oak	2	5	G	G	Υ	N	Υ	Diameter taken below first branching
206	Quercus agrifolia	Coast Live Oak	2.5	5	G	G	Υ	N	Υ	Diameter taken below first branching
207	Quercus agrifolia	Coast Live Oak	1	5	G	G	Y	N	Υ	Diameter taken below first branching

Tag #	Species	Common Name	DBH	Spread	Structure	Health	City Street Tree	Heritage Tree?	Proposed Removal	Notes
208	Ailanthus altissima	Chinese Tree of Heaven	18 @ base	20	Р	G	N	Υ	Υ	Multi
209	Ailanthus altissima	Chinese Tree of Heaven	15 @ base	20	Р	G	N	Υ	Υ	Multi
210	Ailanthus altissima	Chinese Tree of Heaven	16 @ base	25	Р	G	N	Υ	Υ	Multi
211	Ailanthus altissima	Chinese Tree of Heaven	40 @ base	25	Р	G	N	Y	Υ	Multi
212	Ailanthus altissima	Chinese Tree of Heaven	22 @ base	25	Р	G	N	Y	Υ	Multi
1.1	Ailanthus altissima	Chinese Tree of Heaven	13 @ base	14	F-G	G	N	N	Y	
5.1	Ailanthus altissima	Chinese Tree of Heaven	5.8	30	Р	G	N	N	Y	
5.2	Ailanthus altissima	Chinese Tree of Heaven	9.8	30	Р	G	N	N	Y	
11.1	Cupressus sempervirens	Italian Cypress	9.5 @ base	Shared Canopy 25 feet long	F	F	N	N	Y	
11.2	Cupressus sempervirens	Italian Cypress	11	Shared Canopy 25 feet long	F	G	N	N	Y	
11.3	Cupressus sempervirens	Italian Cypress	15.2	Shared Canopy 25 feet long	F	G	N	Y	Y	Heritage tree
11.4	Cupressus sempervirens	Italian Cypress	7	Shared Canopy 25 feet long	F	G	N	N	Y	
11.5	Cupressus sempervirens	Italian Cypress	11.7	Shared Canopy 25 feet long	F	G	N	N	Y	
11.6	Cupressus sempervirens	Italian Cypress	11.8	Shared Canopy 25 feet long	F	G	N	N	Y	


Tag #	Species	Common Name	DBH	Spread	Structure	Health	City Street Tree	Heritage Tree?	Proposed Removal	Notes
11.7	Cupressus sempervirens	Italian Cypress	13	Shared Canopy 25 feet long	F	G	N	N	Y	
11.8	Cupressus sempervirens	Italian Cypress	~6 stake	8	Р	G	N	N	Y	
13.1	Quercus ilex	Holly Oak	8.5	10	F	G	N	N	Υ	Possible tree to relocate
16.01	Ailanthus altissima	Chinese Tree of Heaven	6.5	16	F	F	N	N	Υ	
16.1	Acer palmatum	Japanese Maple	9.8 @ base	10	Р	G	N	N	Υ	
16.2	Acer palmatum	Japanese Maple	9.5 @ base	14	Р	G	N	N	Υ	
16.3	Prunus caroliniana	Carolina Laurel Cherry	10 @ base	Shared Canopy 25 feet long	F	G	N	N	Y	
16.4	Prunus caroliniana	Carolina Laurel Cherry	11.5 @ base	Shared Canopy 25 feet long	Р	G	N	N	Y	
16.5	Prunus caroliniana	Carolina Laurel Cherry	8 @ base	Shared Canopy 25 feet long	Р	G	N	N	Y	
16.6	Prunus caroliniana	Carolina Laurel Cherry	7.5 @ base	Shared Canopy 25 feet long	Р	G	N	N	Y	
16.7	Prunus caroliniana	Carolina Laurel Cherry	9.5 @ base	Shared Canopy 25 feet long	Р	G	N	Z	Y	

Tag #	Species	Common Name	DBH	Spread	Structure	Health	City Street Tree	Heritage Tree?	Proposed Removal	Notes
16.8	Prunus caroliniana	Carolina Laurel Cherry	7.7 @ base	Shared Canopy 25 feet long	Р	G	N	N	Y	
16.9	Prunus caroliniana	Carolina Laurel Cherry	7.3 @ base	8	Р	F	N	N	Υ	
17.1	Ailanthus altissima	Chinese Tree of Heaven	9.5	30	Р	F	N	N	Υ	
17.2	Ailanthus altissima	Chinese Tree of Heaven	6.4	18	Р	G	N	N	Y	
24.1	Ailanthus altissima	Chinese Tree of Heaven	18.4	15	Р	G	N	Υ	Υ	
24.2	Ailanthus altissima	Chinese Tree of Heaven	16.5	20	Р	G	N	Υ	Υ	
24.3	Ailanthus altissima	Chinese Tree of Heaven	7.3	18	Р	G	N	N	Υ	
24.4	Ailanthus altissima	Chinese Tree of Heaven	8	20	Р	G	N	N	Υ	
26.1	Afrocarpus gracilior	African Fern Pine	11.2 @ base	28	Р	F	N	N	Υ	
26.2	Afrocarpus gracilior	African Fern Pine	9.7	15	Р	F	N	N	Υ	
26.3	Afrocarpus gracilior	African Fern Pine	13.6	15	Р	F	N	N	Υ	
26.4	Afrocarpus gracilior	African Fern Pine	base	12	F	G	N	N	Υ	
26.5	Prunus caroliniana	Carolina Laurel Cherry	6.4 @ base	5	Р	F	N	N	Υ	
26.5	Prunus caroliniana	Carolina Laurel Cherry	8.8 @ base	8	Р	F	N	N	Υ	
26.7	Ailanthus altissima	Chinese Tree of Heaven	6 @ base	10	Р	G	N	N	Y	
26.8	Prunus caroliniana	Carolina Laurel Cherry	6.5 @ base	1.5	Р	Р	N	N	Υ	
30.1	Ailanthus altissima	Chinese Tree of Heaven	7.5 @ base	8	F	G	Υ	N	Υ	

1300 El Camino Real and Derry Lane, Menlo Park Real Social Good Investments Appendix 1 Survey Data

mendment 5, 8-10-16	
11 of 11	

Tag #	Species	Common Name	DBH	Spread	Structure	Health	City Street Tree	Heritage Tree?	Proposed Removal	Notes
30.2	Quercus rubra	Red Oak	2.5	7	F	G	Y	N	Y	





## **Tree Preservation Guidelines**

The project site is at 1300 El Camino Real in Menlo Park, CA. The guidelines pertain to the protection of all trees designated as City of Menlo Park Street Trees. None of the trees located within the proposed development site will be retained. Tree protection entails observation of the City Guidelines provided below as well as all procedures and treatments noted in this report.

Prior to the beginning of work activities, project arborist will meet with contractor to review rules for construction activities and to inspect and approve tree protection measures. No activities, demolition or otherwise are to begin until tree protection measures have been inspected and approved of

#### CITY OF MENLO PARK TREE PROTECTION SPECIFICATIONS

- 1. A 6" layer of coarse mulch or woodchips is to be placed beneath the dripline of the protected trees. Mulch is to be kept 12" from the trunk.
- 2. A protective barrier of 6' chain link fencing shall be installed around the dripline of protected tree(s). The fencing can be moved within the dripline if authorized by the Project Arborist or City Arborist but not closer than 2' from the trunk of any tree. Fence posts shall be 1.5" in diameter and are to be driven 2' into the ground. The distance between posts shall not be more than 10'. This enclosed area is the Tree Protection Zone (TPZ).
- 3. Movable barriers of chain link fencing secured to cement blocks can be substituted for "fixed" fencing if the Project Arborist and City Arborist agree that the fencing will have to be moved to accommodate certain phases of construction. The builder may not move the fence without authorization form the Project Arborist or City Arborist.
- 4. Where the City Arborist or Project Arborist has determined that tree protection fencing will interfere with the safety of work crews, Tree Wrap may be used as an alternative form of tree protection. Wooden slats at least one inch thick are to be bound securely, edge to edge, around the trunk. A single layer or more of orange plastic construction fencing is to be wrapped and secured around the outside of the wooden slats. Major scaffold limbs may require protection as determined by the City Arborist or Project Arborist. Straw waddle may also be used as a trunk wrap by coiling the waddle around the trunk up to a minimum height of six feet from grade. A single layer or more of orange plastic construction fencing is to be wrapped and secured around the straw waddle.

#### 5. Avoid the following conditions.

#### DO NOT:

- a. Allow run off of spillage of damaging materials into the area below any tree canopy.
- b. Store materials, stockpile soil, or park or drive vehicles within the TPZ.
- c. Cut, break, skin, or bruise roots, branches, or trunks without first obtaining authorization from the City Arborist.
- d. Allow fires under and adjacent to trees.
- e. Discharge exhaust into foliage.
- f. Secure cable, chain, or rope to trees or shrubs.
- g. Trench, dig, or otherwise excavate within the dripline or TPZ of the tree(s) without first obtaining authorization from the City Arborist.



- h. Apply soil sterilants under pavement near existing trees.
- 6. Only excavation by hand or compressed air shall be allowed within the dripline of trees. Machine trenching shall not be allowed.
- 7. Avoid injury to tree roots. When a ditching machine, which is being used outside of the dripline of trees, encounters roots smaller than 2", the wall of the trench adjacent to the trees shall be hand trimmed, making clear, clean cuts through the roots. All damaged, torn and cut roots shall be given a clean cut to remove ragged edges, which promote decay. Trenches shall be filled within 24 hours, but where this is not possible, the side of the trench adjacent to the trees shall be kept shaded with four layers of dampened, untreated burlap, wetted as frequently as necessary to keep the burlap wet. Roots 2" or larger, when encountered, shall be reported immediately to the Project Arborist, who will decide whether the Contractor may cut the root as mentioned above or shall excavate by hand or with compressed air under the root. Root is to be protected with dampened burlap.
- 8. Route pipes outside of the area that is 10 times the diameter of a protected tree to avoid conflict with roots.
- 9. Where it is not possible to reroute pipes or trenches, the contractor shall bore beneath the dripline of the tree. The boring shall take place not less than 3' below the surface of the soil in order to avoid encountering "feeder" roots.
- 10. Trees that have been identified in the arborist's report as being in poor health and/or posing a health or safety risk, may be removed or pruned by more than one-third, subject to approval of the required permit by the Planning Division. Pruning of existing limbs and roots shall only occur under the direction of a Certified Arborist.
- 11. Any damage due to construction activities shall be reported.

## SUMMARY OF POTENTIAL IMPACTS AND MITIGATION

- 1. <u>Pre-Construction Meeting to Review Tree Protection</u> No activities are to commence until after the meeting and inspection of tree protection is conducted.
- 2. <u>Early Investigation and Health Mitigation</u> Most critical area for investigation is along El Camino Real, just behind the sidewalk. The presence of Plane Tree roots of over one-inch in diameter will require root pruning prior to the use of excavation equipment. Project arborist must be present at the time the concrete pavement behind the sidewalk is removed to inspect for root presence.
- 3. Root Protection Zone (RPZ) The RPZ is initially set at a distance equal to one radial foot for every one inch is tree diameter (DBH). Tree protection fencing is generally placed at the limit of the RPZ. The RPZ of many of the City Street Trees planted along El Camino extends beyond the sidewalk and into the project site. Project arborist is to be present to supervise activities that encroach into the RPZ.
- 4. <u>Trunk and Scaffold Protections</u> Whenever the RPZ is encroached upon by equipment, trees must be armored against any potential mechanical injury.



- 5. <u>Necessary Root Pruning</u> Any necessary root pruning must be supervised or undertaken by project arborist. Root pruning occurs only after roots have been exposed by either hand, air or water excavation.
- 6. Soil Protection When possible, existing concrete paving is to remain in place to provide soil protection during construction activities. Exposed soil areas that are located within the designated RPZ must be protected from compaction using wood chip mulch and trenching plates of 1 1/8 inch plywood. Mitigation will be prescribed for areas of soil compaction identified by project arborist.

#### **EARLY INVESTIGATION**

The information gained from site analysis is utilized in the guidelines for root and soil protection.

<u>Soil Profile Examination</u> – The soil profile examination determines soil texture, compaction and moisture. Soil compaction is mitigated through the use of a water jet or possibly and air spade to improve soil gas exchange.

<u>Root Investigation</u> – Root presence, depth, size and amount are determined in critical areas. This information is vital to the understanding of the level of soil protection and the level of root loss that will likely occur.

#### **PRE-CONSTRUCTION ACTIVITIES**

These activities should be undertaken prior to initiation of construction activity. In addition to modifications to the project design to reduce tree impacts, all steps that improve the health of trees prior to construction will greatly improve the chance of survival.

<u>Designate Tree Root Protection Zone (RPZ)</u> –The tree Root Protection Zone designates an area surrounding a tree or grouping of trees that is to be fenced off from all access until designated by a certified arborist. The RPZ is commonly defined as one (1) foot radial distance for every one (1) inch in tree diameter (DBH). Initial RPZ for all trees are provided in the survey data in Table 1.

The City Street Trees on El Camino, all London Plane, have an RPZ as much as 13 feet that extends into the project site. All will require root protection when the existing pavement is removed.

<u>Tree Root Protection Zone Fencing</u> – Fencing must be inspected and approved prior to the beginning of any demolition of grading activities. Tree protection fencing shall be 6' tall chain link type, secured to the existing concrete pavement if not yet removed. After pavement removal, steel posts driven two-feet into the ground at a spacing of 10 feet to support the tree protection fencing. Fencing shall have signage in place stating: "Tree Protection Area - Do Not Enter". It is understood that there will be encroachment into the RPZ. When moved, tree fencing is installed in the new location in the same manner.

<u>Trunk and Scaffold Protection</u> – All trunk and scaffold protection measures are subject to prior inspection and approval by project arborist. Whenever construction activity must occur inside the tree protection zone, the base of the tree and the first eight-feet of the trunk must be protected. Protection is generally provided by wrapping the trunk up to the first branch with 10 wraps of orange plastic



construction fencing or use of straw waddles wrapped around the tree. Additional protection can be provided by either straw bales or use of vertical 2x4 boards strapped to the tree. Arborist may require any or all of the trunk protection measures depending upon the situation. Arborist approval will be required for acceptance of the measures used.

Root Pruning – Root pruning is best conducted in the late fall and in advance of construction activities. Root pruning is preceded by careful hand, air or water excavation to first expose the roots. Root pruning is conducted by arborist using sharp tools. Severed roots are immediately sprayed with a sugar solution (6 oz. granulated sugar per gallon of water) and covered with either burlap or soil. Pruning both the canopy and roots at the same time should be avoided if possible.

<u>Soil Protection</u> – Soil areas inside of the designated RPZ that are not fenced must be protected. Standard protection entails 6 inches of wood chips covered with ¾ inch plywood. If equipment is to be used, first place 12 inches of wood chip mulch on the soil surface. Place either trenching places or 1 1/8 inch plywood connected with metal straps on the wood chips. Soil protections must remain in place until the completion of construction activities.

<u>Supplemental Irrigation</u> – Arborist will designate supplemental irrigation based upon the monitoring of soil moisture conditions during construction. Supplemental irrigation will be applied prior to the application of mulch and thereafter as per arborist direction.

<u>Mulching</u> – Use of four to six inches of organic mulch (wood chips are best) on soil surface will reduce soil compaction and evaporative soil moisture loss. Recommended material is wood chips generated from tree trimming. Fresh redwood, incense cedar and walnut chips are not acceptable, nor is palm generated mulch.

#### TREE PROTECTION DURING CONSTRUCTION

The level of arborist monitoring of the project can be quite variable, depending upon the degree of encroachment into root systems and the early levels of contractor compliance with the tree protection guidelines. In this situation, all trees to be protected are located outside of the construction site. It is true that the roots of the London Plane trees on El Camino Real do extend into the project site.

<u>Pre-Construction Meeting</u> – It is important that construction crew understands the tree protection requirements. All personnel working on site are to be provided an orientation to tree preservation measures and rules by the arborist assigned to monitor tree preservation. All tree protection measures must be in place and approved by project at this time. Confirmation of compliance will be sent to City Arborist.

<u>Observe Fenced RPZ</u> – This area is off limits to all personnel, equipment, materials storage, or any other activities. Fencing may be relocated only under arborist supervision.

<u>Demolition Activities</u> – If possible, the existing City sidewalk should remain in place for the duration of construction activities. All demolition activities include removal of pavement or structures are considered to be part of the construction project. The same restrictions on the use of equipment and encroachment into the designated root protection zone apply to all such activities. Project arborist must supervise all activities where encroachment into the RPZ occurs.



#### **WORK ACTIVITIES OCCURING WITHIN THE DESIGNATED RPZ**

Due to the relatively tight space, it appears that many activities will occur inside of the designated 36 foot RPZ. Under such circumstances the following protections are required.

<u>Arborist Supervision</u> – An arborist shall monitor trees throughout all phases of development to ensure tree protection measures are in place. Retain above mentioned protection measures until after final inspection.

<u>Root Protection</u> – Areas where roots cannot be fenced require protection from contaminants and compaction. The effects of foot traffic can be mitigated through the use of six (6) inches of wood chip mulch and ¾ inch plywood placed on top.

When equipment is to be used inside of the designated RPZ, soil must be covered with 12 inches of wood chips and two layers of ¾ inch plywood or one layer of 1 1/8 inch plywood or metal trench plates.

<u>Soil Moisture Monitoring and Control</u> – Water stress is detrimental to tree health, particularly during the spring. Supplemental irrigation is required whenever tree roots are uncovered or severed due to trenching or grading. Open trenches with exposed roots require minimum two layers of damp burlap or other acceptable covering at all times. An arborist will determine the amount of supplemental watering required based upon soil moisture investigation and weather conditions.

Required Method of Excavation Within Critical Root Zone — Carefully hand excavation or **tunneling** shall be the accepted method for installing underground utilities. All soil excavation within the TPZ shall be done with either supersonic air tools, pressurized water, or hand tools prior to any root pruning.

<u>Sidewalk Replacement</u> – If the City sidewalk is replaced, it is best for root protection to wait until the project is near completion. Project arborist must be present to monitor activities. It is recommended that base material under the concrete pavement be "clean crushed rock"<sup>1</sup>. This has been shown to reduce the potential for future root related pavement displacement.

#### POST CONSTRUCTION MITIGATION

All valuable trees which have been impacted in any manner (root loss, soil moisture changes, or necessary pruning) will require mitigation to offset the adverse impact and maintain the level of vigor in the tree prior to being impacted impact. Trees that were not vigorous prior to construction will require extra care.

<u>Monitoring Tree Health</u> – Regular visual inspection of trees will aid in assessing where further mitigation is required. Tree decline should be recorded and referenced against pre-construction health assessment. Leaf and stem insects and fungal pathogens are a sign of poor tree health (low energy reserves).

Monitoring of Soil Moisture – It is important that significant changes in soil moisture levels within tree root zones be identified early, prior to visible evidence of tree decline. Moisture should be monitored

 $<sup>^{\</sup>rm 1}$  "Comparison of Method to Reduce Sidewalk Damage from Tree Roots" by E. Thomas Smiley



by visual inspection using a soil probe or through the use of tensiometers placed at key locations. Supplemental irrigation is best provided during middle and late spring. In cases where trees have suffered root loss, supplemental irrigation will be required for a number of years in the area where roots were severed.

<u>Mitigation of Soil Compaction</u> – The level and depth of soil compaction must be assessed and mitigated as necessary. Mitigation of soil compaction in areas where roots are present must minimize root loss. Tools most suitable to mitigate soil compaction are the water jet or air spade.


<u>Continued Mulching</u> – If the area behind the sidewalk on El Camino is not paved, it would be best to mulch the exposed soil area. Mulch is extremely beneficial in creating a healthy root environment. A regular program of mulch application is recommended to help retain soil moisture, provide a source of nutrients, and help control weeds. The continued use of good quality compost as a mulch is beneficial as a source of nutrition.

<u>Fertilization</u> – Prior to fertilization, soil analysis and possibly leaf tissue analysis must be undertaken. Trees should be fertilized only when the nutritional limitations have been identified. Leaf tissue analysis is another excellent tool for this determination. Excessive nitrogen fertilization is known to draw sucking insects (aphid, scale, etc.) to the plants and provide nutrition to fungal pathogens in the soil.

<u>Pest Management Program</u> – Healthy trees do not generally have serious pest problems. Stressed trees are attractive hosts to pathogens, which can contribute to decline and eventual death. Pest management is prescribed when monitoring indicates a need and tree health is in decline.

## End





June 2, 2016

Mr. Christian Bonner City Arborist The City of Menlo Park 701 Laurel Street Menlo Park, CA 94025

Re: Station 1300 at 1300 El Camino Real

Contract Arborist Project Review

1300 El Camino Real and Derry Lane Heritage Tree Survey

Dear Mr. Bonner:

The Planning Division for the City of Menlo Park is studying a submittal to develop certain parcels collectively known as 1300 El Camino Real. The project is entitled Station 1300. Fujiitrees Consulting (FTC) was retained to complete a project review of the Tree Survey submitted by the applicant.

## Background

Pursuant to Chapter 13.24 – Heritage Trees of the Menlo Park Municipal Ordinance certain trees are regulated by the City. As used in this chapter "heritage tree" (verbatim) means:

- A tree or group of trees of historical significance, special character or community benefit, specifically designated by resolution of the city council;
- 2. An oak tree (Quercus) which is native to California and has a trunk with a circumference of 31.4 inches (diameter of 10 ten inches) or more, measured at fifty –four (54) inches above natural grade. Trees with more than one trunk shall be measured at the point where the trunks divide, with the exception of trees that are under twelve (12) feet in height, which will be exempt from this section.
- 3. All trees other than oaks which have a trunk with a circumference of 47.1 inches (diameter of fifteen (15 inches) or more, measured fifty –four (54) inches above natural grade. Trees with more than one trunk shall be measured at the point where the trunks divide, with the exception of trees that are under twelve (12) feet in height which will be exempt from this section. (Ord. 928 s 1 (part), 2004)

**Walt Fujii, RCA®**Consulting Arborist

415.699.6269

24701 Broadmore Ave Hayward, CA 94544

walt@fujiitrees.com fujiitrees.com

ASCA Registered Consulting Arborist® No. 402
ISA Certified Arborist No. WE2257A
ISA-TRAQ Tree Risk Assessment Qualification
CA DPR Qualified Applicator Certificate No. 82521





In addition, all development projects are to submit a land survey that complies with Boundary and Topographical Survey Requirements for the City of Menlo Park. This includes "Locations of existing trees greater than six inches in diameter with the diameter at standard height (54 inches), species, drip line and graphical representation of the trunk size;".

FTC was informed that trees greater than six in trunk diameter at the height of 54 inches are to be included in all required tree inventories conducted for development projects.

The proposed development plans for the Station 1300 project will impact existing Heritage trees, making the development plans subject to the Heritage Tree Ordinance.

## **Assignment**

Specifically, the following items were to be addressed by FTC:

- 1. Visually verify the tree species and size recorded by the Project Arborist.
- 2. Make note of any significant tree suitable for preservation.
- 3. Make recommendations to the Planning Department to either approve or deny the Heritage Tree Removal Application.
- 4. The Planning Division for the City of Menlo Park requested FTC to prepare a tree summary matrix. Table 1 Tree Summary was completed using a template provided by the Planning Division.

For purposes of clarity, Table 1 – The Tree Summary was presented in three parts; Project Arborist, SBCA Heritage Tree Survey, FTC Tree Survey and lastly both tables combined into one table.

Note: This peer review would be equivalent to the work typically conducted by the City Arborist for development projects.

## **Summary of Findings**

#### Site Conditions

On May 16, 2016 FTC visited the project site of Station 1300 located at 1300 El Camino Real in the City of Menlo Park, California. Existing site trees were observed to be in a general state of disrepair with little attention given to acceptable pruning practices.

Of particular concern was tree 12, a coast redwood which overhangs the sidewalk and a portion of El Camino Real. This redwood exhibits significant branch dieback with a slight trunk lean toward the roadway.



Mature City Street Trees were observed to be well maintained but were not remarkable in structure or in health. A number of younger, smaller street trees, mainly coast live oaks were located by SBCA within the Right of Way of Garwood Way.

## Project Arborist Heritage Tree Survey

The Heritage Tree Survey and Tree Location Map completed by SBCA Tree Consulting was the subject of this FTC review.

Refer to Appendix 1, Heritage Tree Survey by SBCA for 110 inventoried trees.

According to the scope described in the SBCA Arborist Report, the tree survey includes all Heritage trees on or directly adjacent to parcels at 1300 El Camino Real and Derry Lane and all adjacent City Street Trees. FTC encountered five trees that were not included in the SBCA tree survey:

- Heritage tree 11.3 Italian cypress (Cupressus sempervirens) 15.2 inches in trunk diameter
- Heritage tree 24.1 Chinese tree of heaven (Ailanthus altissima) 18.4 inches at base
- Heritage tree 24.1 Chinese tree of heaven (Ailanthus altissima) 18.4 inches at base
- City Street Tree 30.1 Chinese tree of heaven (Ailanthus altissima) 7.5 inches at base
- City Street Tree 30.2 red oak (Quercus rubra) 2.5 inches in trunk diameter

Additionally, two palms were inventoried per industry standards but not per MPMC 13.24. (See Background) The palms were:

- Heritage tree 36 Canary Island date palm (Phoenix canariensis) 30.3 inches in trunk diameter
- Heritage tree 46 Mexican fan palm (Washingtonia robusta) 18.5 inches in trunk diameter

FTC contacted the City Arborist, Christian Bonner, for the minimum trunk diameter size that was to be inventoried. According to the City Arborist, all single stem trees greater than six inches in trunk diameter at 54 inches above grade and all multi stem trees greater than six inches in diameter just below the attached stems are to be inventoried.

It was decided that FTC should inventory those trees greater than six inches in trunk diameter in addition to any overlooked trees. Refer to Appendix 2, Supplemental Heritage Tree Survey by FTC for 38 inventoried trees.

Appendix 3 is an updated Tree Location Map prepared by SBCA and updated by FTC. Trees are approximately located and the map is not scaled.



### <u>Impacts to Heritage City Street Trees and City Street Trees</u>

A magnifying glass was necessary to discern features on the provided sheet TM-3 Topographic Boundary Survey. With that said, all inventoried trees that were not identified as City Street Trees appeared to be located on the subject property.

According to sheet TM-7, Preliminary Grading Plan and sheet TM-8, Preliminary Utility Plan the proposed limits of disturbance will include:

- The demolition of Derry Lane (removal of Heritage City Street Trees 27, 30 and City Street Trees 30.1 and 30.2)
- The improvement and extension of Garwood Way to Oak Grove Avenue (removal of Heritage City Street Trees 33-39, 64, 65, 76–100, 201–207)
- Sidewalk and utility improvements of Oak Grove Avenue (removal of City Street Trees 41-45)
- The installation of a bioretention area following the adjacent property lines of two existing businesses, Menlo Park Chevron and Jason's Café
- Sidewalk and utility improvements of El Camino Real (removal of City Street Tree 60) It should be noted that sheet L-1.0, Landscape Site Plan shows 14 unnumbered City Street Trees to be preserved when the actual count less City Street Tree 60 would be 13.

## Impacts to Existing On-Site Trees

According to sheet TM-7, Preliminary Grading Plan and sheet TM-8, Preliminary Utility Plan, all existing Heritage trees and Non-Heritage trees within the limits of disturbance will require removal for purposes of construction.

In terms of trees whose size, condition and location may warrant preservation, two trees were identified:

Tree 13.1 holly oak (Quercus ilex) 8.5 inches DBH
Tree 36 Canary Island palm (Phoenix canariensis) 30.3 inches DBH

## Conclusions

## Risk Posed by Tree 12

The location by a major roadway and the compromised structure of tree 12, a coast redwood, makes it a tree of great concern that should not be ignored.



## SBCA Heritage Tree Survey

Species identification and size were observed to be accurately recorded using the Heritage Ordinance as the guide.

Based on the information provided to FTC, those trees identified as City Street Trees in the SBCA tree survey were observed to be correctly categorized. Refer to Table 1.

SBCA assessments of structure and health for both private trees and City Street Trees were consistent with the overall findings of FTC.

## <u>Significant Trees for Preservation</u>

It is the opinion of FTC that tree 13.1 – holly oak and tree 36 – Canary Island pine should be considered for preservation. The Project Arborist should provide recommendations for the feasibility of preserving one or both trees.

## Recommendation for the Tree Removal Application

It is the opinion of FTC to accept the SBCA report with the amended tree survey.

It is the opinion of FTC to approve the Station 1300 Heritage Tree Removal Application.

#### Recommendations

- 1. FTC strongly recommends that the Applicant authorize the Project Arborist to take appropriate action to mitigate the risk presented by tree 12.
- 2. Accept Heritage Tree Removal Permit Application No. HTR2016-0072 per MPMC section 13.24.040 Permits;
  - a. Item 1. The condition of the tree or trees with respect to disease, danger of falling, proximity to existing or proposed structures and interference with utility services;
  - b. Item 2. The necessity to remove the tree or trees in order to construct proposed improvements to the property;
  - c. Item 4. The long-term value of the species under consideration, particularly lifespan and growth rate;
- 3. The applicant should apply for a Street Tree Removal Permit to be in compliance with MPMC Section 13.20.060.



4. Two trees should be considered for possible preservation: tree 13.1 – holly oak and tree 36 – Canary Island pine. The Project Arborist should provide recommendations for the feasibility of preserving one or both trees.

This concludes the FTC review of the 1300 El Camino Real and Derry Lane Heritage Tree Survey.

Kindly contact me with your questions.

Respectfully,

Walter Fujii, RCA®

Contract City Arborist



Attachments: Table 1 – Tree Summary

Appendix 1 – SBCA 1300 El Camino and Derry Lane Heritage Tree Survey

Appendix 2 – FTC Supplemental Tree Survey Appendix 3 – Updated Tree Location Map

Certificate of Performance

Terms and Conditions

# Tree Summary (Template provided by the Planning Division)

## SBCA Tree Survey

		On-site			n other parcels	s <sup>1</sup>		City ROW			Total		
	Existing	To Remain	To Be Removed	Existing	To Remain	To Be Removed	Existing	To Remain	To Be Removed	Existing	To Remain	To Be Removed	
Heritage Trees	47	0	47	0	0	0	9	0	9	56	0	56	
Non-Heritage Trees	0	0	0	0	0	0	54	15	39	54	15	39	

## FTC Supplemental Survey

		On-site		0	n other parcels	s <sup>1</sup>		City ROW			Total	
	Existing	To Remain	To Be Removed	Existing	To Remain	To Be Removed	Existing	To Remain	To Be Removed	Existing	To Remain	To Be Removed
Heritage Trees	3	0	3	0	0	0	0	0	0	3	0	3
Non-Heritage Trees	33	0	33	0	0	0	2	0	2	35	0	35

## **Combined Surveys**

		On-site		0	n other parcels	s <sup>1</sup>		City ROW			Total	
	Existing	To Remain	To Be Removed	Existing	To Remain	To Be Removed	Existing	To Remain	To Be Removed	Existing	To Remain	To Be Removed
Heritage Trees	50	0	50	0	0	0	9	0	9	59	0	59
Non-Heritage Trees	33	0	33	0	0	0	56	15	41	89	15	74

<sup>1/</sup> Per sheet TM-3 Topographic Boundary Survey, all inventoried trees that were not identified as City Street Trees were located on the subject property.

## **1300 El Camino Real and Derry Lane Heritage Tree Survey**

#### **COLUMN HEADING DESCRIPTIONS**

Tag# - Indicates the number tag attached to tree

Species - Scientific name

Common Name - Vernacular name

DBH - Diameter measured in inches at 4.5 feet above soil grade; For multiple stemmed trees, measurements were taken at the point where the trunks divide;

For palms, measurements are made from the tree base to the point where fronds emanate

Spread- In feet

Structure- Tree Structural Safety: E is Excellent, G is Good, F is Fair, P is Poor, H is Hazardous

Health - Tree Health: E is Excellent, G is Good, F is Fair, P is Poor, D is Dead or Dying

City Street Tree - Y is Yes, N is No Proposed Removal - Y is Yes, N is No

Notes - See below

#### ABBREVIATIONS AND DEFINITIONS

Embedded Bark (EB) - AKA Included Bark, this is a structural defect where bark is included between the branch attachment so that the wood cannot join. Such defects have a higher propensity for failure.

Codominant (CD) - A situation where a tree has two or more stems which are of equal diameter and relative amounts of leaf area. Trees with codominant primary scaffolding stems are inherently weaker than stems, which are of unequal diameter and size.

Notes

Codominant w/ Embedded Bark (CDEB) - When bark is embedded between codominant stems, failure potential is very high and pruning to mitigate the defect is recommended.

Poor Pruning (PP)- Past pruning practices considered unacceptable according to ANSI A300 Best Management Practices, Tree Pruning

Headed (H) - Generally considered poor pruning practice which removes the central leader and the internode.

Tag#	Species	Common Name	DBH	Spread	Structure	Health	City Street Tree	Proposed Removal	Notes
1	Sequoia sempervirens	Coast Redwood	28	25	G	F	N	Υ	Off color, Signs of stress, Botryosphaeria?
2	Ailanthus altissima	Chinese Tree of Heaven	28 @ base	36	F - P	F	N	Υ	Multi
3	Ailanthus altissima	Chinese Tree of Heaven	24 @ base	30	F - P	F	N	Υ	Multi
4	Ailanthus altissima	Chinese Tree of Heaven	24 @ base	15	F - P	F	N	Υ	Multi, Clump of 4 stems
5	Ailanthus altissima	Chinese Tree of Heaven	15 @ base	20	F-P	F	N	Υ	Multi, Clump of 3 stems

Tag#	Species	Common Name	DBH	Spread	Structure	Health	City Street Tree	Proposed Removal	Notes
6	Ailanthus altissima	Chinese Tree of Heaven	18 @ base	30	F - P	F	N	Υ	Multi, Clump of 3 stems
7	Ailanthus altissima	Chinese Tree of Heaven	30 @ base	45	Р	F	N	Υ	Multi, EB
8	Ailanthus altissima	Chinese Tree of Heaven	28 @ base	35	Р	F	N	Υ	Multi
9	Ailanthus altissima	Chinese Tree of Heaven	40 @ base	30	F-P	F	N	Υ	Multi
10	Acacia melanoxylon	Blackwood Acacia	24	35	Р	G	N	Υ	CDEB
11	Cupressus sempervirens	Italian Cypress	15 @ base	10	F	F	N	Y	CD, 2nd in a line of 7 cypress
12	Sequoia sempervirens	Coast Redwood HIGH RISK TREE - REQUIRES MITIGATION	54	40	P - H	P - D	N	Y	Significant tip dieback, Dead CD top, 27" x 10' (rotting) wound on side facing street, Slight lean to street
13	Jacaranda mimosifolia	Jacaranda	27 @ base	25	F	G	N	Y	Multi
14	Jacaranda mimosifolia	Jacaranda	28 @ base	30	Р	G	N	Υ	EB, Multi
15	Jacaranda mimosifolia	Jacaranda	26 @ base	25	F	G	N	Υ	Multi, PP
16	Jacaranda mimosifolia	Jacaranda	15	25	F	G	N	Υ	CD
17	Ailanthus altissima	Chinese Tree of Heaven	32 @ base	40	Р	F	N	Υ	Multi, CDEB, EB
18	Ailanthus altissima	Chinese Tree of Heaven	22 @ base	35	F-P	F	N	Υ	Multi, Basal damage, Metal in tree
19	Ailanthus altissima	Chinese Tree of Heaven	20 @ base	20	Р	F	N	Y	Multi, Clump of 6 stems, CDEB
20	Ailanthus altissima	Chinese Tree of Heaven	30 @ base	30	Р	F	N	Υ	Multi
21	Quercus agrifolia	Coast Live Oak	20 @ base	20	Р	F	N	Υ	Multi, EB
22	Ailanthus altissima	Chinese Tree of Heaven	48 @ base	70	Р	G	N	Υ	Multi, multi, EB, EB branch breakout

Tag#	Species	Common Name	DBH	Spread	Structure	Health	City Street Tree	Proposed Removal	Notes
23	Ailanthus altissima	Chinese Tree of Heaven	72 @ base	50	Р	F-G	N	Υ	Multi, Clump of 9 stems, EB
24	Afrocarpus gracilior	African Fern Pine	15	25	G	G	N	Υ	CD
25	Afrocarpus gracilior	African Fern Pine	15 @ base	20	Р	F	N	Υ	CDEB
26	Afrocarpus gracilior	African Fern Pine	15 @ base	15	Р	G	N	Υ	CDEB
27	Ailanthus altissima	Chinese Tree of Heaven	17 @ base	20	Р	F	Y	Υ	CDEB, PP, H
28	Quercus agrifolia	Coast Live Oak	23	50	F	F	N	Υ	PP, Wound at base, 20' from curb
29	Sequoia sempervirens	Coast Redwood	103 @ base	50	F	F	N	Υ	Multi, Off color, Signs of stress, 20' from curb
30	Sequoia sempervirens	Coast Redwood	32.5 @ base	30	G	G	Y	Υ	Hardscape displacement
31	Phoenix canariensis	Canary Island Date Palm							Gone
32	Phoenix canariensis	Canary Island Date Palm							Gone
33	Quercus agrifolia	Coast Live Oak	40.5	60	Р	G	Y	Y	Off site, 13' from property line, CD, Trunk rotted out on north side
34	Robinia pseudoacacia	Black Locust	30 @ base	25	Р	F	Y	Υ	On property line, Clump of 7 stems, Growing in fence
35	Ailanthus altissima	Chinese Tree of Heaven	24 @ base	40	Р	F	Υ	Υ	Multi, On property line, Clump of 10 stems, 5' from street
36	Phoenix canariensis	Canary Island Date Palm	20' of Clear Trunk	n/a	G	G	Y	Υ	Off site , 4' from street
37	Quercus lobata	Valley Oak	32	65	F	F	Y	Υ	Off site, 7' from property line, 2' from curb, Previous #53, Large (rotting) pruning wound, PP
38	Quercus agrifolia	Coast Live Oak	10	20	F	G	Y	Υ	Large breakouts, Pruning wounds, Lean for light
39	Quercus lobata	Valley Oak	23.5	40	F	Р	Y	Υ	8' from curb

Tag#	Species	Common Name	DBH	Spread	Structure	Health	City Street Tree	Proposed Removal	Notes
40	Ailanthus altissima	Chinese Tree of Heaven	20 @ base	20	F	F	N	Υ	Multi, Part of a large 70' long stand
41	Platanus x hispanica	London Plane Tree	12.5	20	Р	Р	Υ	Υ	Street tree, Pruning wounds, ID, Previously headed
42	Platanus x hispanica	London Plane Tree	12.5	30	Р	F	Υ	Υ	Street tree, Pruning wounds, ID, Previously headed
43	Platanus x hispanica	London Plane Tree	12.5	30	Р	F	Υ	Υ	Street tree, ID, Previously headed
44	Quercus agrifolia	Coast Live Oak	1	5	F	F	Υ	Υ	Good push of new growth
45	Pyrus kawakamii	Evergreen Pear	13	30	F	G	Υ	N	Large pruning wounds, CD
46	Washingtonia robusta	Mexican Fan Palm	7' of Clear Trunk	15	O	G	N	Υ	Close to building, Volunteer?
47	Platanus x hispanica	London Plane Tree	11	25	F	F-G	Υ	N	Street tree, Lean, CD
48	Platanus x hispanica	London Plane Tree	11	25	G	F-G	Υ	N	Lean
49	Platanus x hispanica	London Plane Tree	9	25	G	F-G	Υ	N	Lean
50	Platanus x hispanica	London Plane Tree	11.5	30	G	F-G	Υ	N	CD, Touching metal grate
51	Platanus x hispanica	London Plane Tree	11	30	G	G	Υ	N	CD, Touching metal grate
52	Platanus x hispanica	London Plane Tree	10.5	30	G	G	Υ	N	CD, Touching metal grate
53	Platanus x hispanica	London Plane Tree	11.5	30	G	G	Υ	N	CD, Touching metal grate
54	Platanus x hispanica	London Plane Tree	10	30	G	F-G	Υ	N	Large pruning wounds, CD, touching metal grate
55	Platanus x hispanica	London Plane Tree	10	30	G	F-G	Υ	N	No grate
56	Platanus x hispanica	London Plane Tree	8.5	30	G	F-G	Υ	N	
57	Platanus x hispanica	London Plane Tree	10	30	G	F-G	Υ	N	Touching metal grate
58	Platanus x hispanica	London Plane Tree	11	30	G	G	Υ	N	Lean
59	Platanus x hispanica	London Plane Tree	10	30	G	G	Υ	N	

Tag#	Species	Common Name	DBH	Spread	Structure	Health	City Street Tree	Proposed Removal	Notes
60	Platanus x hispanica	London Plane Tree	6	20	G	F	Υ	Υ	Smaller than others, likely shaded by adjacent redwood
61	Platanus x hispanica	London Plane Tree	7.5	20	G	F	Υ	N	
62	Ailanthus altissima	Chinese Tree of Heaven	18 @ base	45	Р	G	N	Υ	CDEB, Multi
63	Quercus agrifolia	Coast Live Oak	10.5 @ base	20	F-P	G	N	Υ	3 stems
64	Acacia melanoxylon	Blackwood Acacia	12.5	25	F	G	Υ	Υ	Lean, Trunk damage, 2-3' from curb
65	Acacia melanoxylon	Blackwood Acacia	8.5	25	G	G	Υ	Υ	Slight lean, 5' from end of pavement
66	Ailanthus altissima	Chinese Tree of Heaven	34.5 @ base	20	Р	G	N	Υ	Multi, Part of a large 70' long stand
67	Ailanthus altissima	Chinese Tree of Heaven	21 @ base	15	Р	G	N	Υ	Multi, Part of a large 70' long stand
68	Ailanthus altissima	Chinese Tree of Heaven	20 @ base	20	Р	G	N	Υ	Multi, Part of a large 70' long stand
69	Ailanthus altissima	Chinese Tree of Heaven	18 @ base	25	Р	G	N	Υ	Multi, Part of a large 70' long stand
70	Ailanthus altissima	Chinese Tree of Heaven	19 @ base	20	Р	G	N	Υ	Multi, Part of a large 70' long stand
71	Ailanthus altissima	Chinese Tree of Heaven	16 @ base	25	Р	G	N	Υ	Multi, Part of a large 70' long stand
72	Ailanthus altissima	Chinese Tree of Heaven	15 @ base	25	Р	G	N	Υ	Multi, Part of a large 70' long stand
73	Ailanthus altissima	Chinese Tree of Heaven	21 @ base	20	Р	G	N	Υ	Multi, Part of a large 70' long stand
74	Ailanthus altissima	Chinese Tree of Heaven	16 @ base	15	Р	G	N	Υ	Multi, Part of a large 70' long stand
75	Ailanthus altissima	Chinese Tree of Heaven	22 @ base	20	Р	G	N	Υ	Multi, Pruning left larger stumps
76	Quercus agrifolia	Coast Live Oak	1 3/4	5	G	G	Υ	Υ	Diameter taken below first branching
77	Quercus agrifolia	Coast Live Oak	1	5	G	F	Y	Υ	Diameter taken below first branching
78	Quercus agrifolia	Coast Live Oak	3 3/4	10	G	G	Υ	Υ	Diameter taken below first branching

Tag#	Species	Common Name	DBH	Spread	Structure	Health	City Street Tree	Proposed Removal	Notes
79	Quercus agrifolia	Coast Live Oak	4	10	F	G	Υ	Υ	CD
80	Quercus agrifolia	Coast Live Oak	4.5	20	F	G	Υ	Υ	Pruning wounds
81	Quercus agrifolia	Coast Live Oak	6	25	F	G	Υ	Υ	Large pruning wounds, CD
82	Malus sp.	Apple	3	5	G	G	Υ	Υ	
83	Quercus agrifolia	Coast Live Oak	3	10	G	G	Υ	Υ	Diameter taken below first branching. CD
84	Quercus agrifolia	Coast Live Oak	3	20	F	G	Υ	Υ	Diameter taken below first branching
85	Quercus agrifolia	Coast Live Oak	1	5	G	G	Υ	Υ	Diameter taken below first branching
86	Quercus agrifolia	Coast Live Oak	5 3/4	20	G	G	Υ	Υ	Diameter taken below first branching
87	Quercus agrifolia	Coast Live Oak	0.5	3	G	G	Υ	Υ	Diameter taken below first branching
88	Quercus agrifolia	Coast Live Oak	1	3	G	G	Υ	Υ	Diameter taken below first branching
89	Quercus agrifolia	Coast Live Oak	3/4	3	G	G	Υ	Υ	Diameter taken below first branching
90	Quercus agrifolia	Coast Live Oak	0.5	3	G	G	Υ	Υ	Diameter taken below first branching
91	Quercus agrifolia	Coast Live Oak	1.5	3	G	G	Υ	Υ	Diameter taken below first branching
92	Quercus agrifolia	Coast Live Oak	1	3	G	G	Υ	Υ	Diameter taken below first branching
93	Quercus agrifolia	Coast Live Oak	3.5	15	G	G	Υ	Υ	Diameter taken below first branching
94	Quercus agrifolia	Coast Live Oak	2	15	G	G	Υ	Υ	Diameter taken below first branching
95	Quercus agrifolia	Coast Live Oak	0.5	5	G	G	Υ	Υ	Diameter taken below first branching
96	Quercus agrifolia	Coast Live Oak	1.5	5	G	G	Υ	Υ	Diameter taken below first branching
97	Quercus agrifolia	Coast Live Oak	1.5	10	G	G	Υ	Υ	Diameter taken below first branching

Tag #	Species	Common Name	DBH	Spread	Structure	Health	City Street Tree	Proposed Removal	Notes
98	Ailanthus altissima	Chinese Tree of Heaven	4	20	G	F	Υ	Υ	
99	Ailanthus altissima	Chinese Tree of Heaven	3.5	20	F	F	Υ	Υ	
100	Ailanthus altissima	Chinese Tree of Heaven	7.5	25	G	Р	Υ	Υ	
201	Quercus agrifolia	Coast Live Oak	1.5	5	G	G	Υ	Υ	Diameter taken below first branching
202	Quercus agrifolia	Coast Live Oak	1	5	G	G	Υ	Υ	Diameter taken below first branching
203	Quercus agrifolia	Coast Live Oak	1.5	5	G	G	Υ	Υ	Diameter taken below first branching
204	Quercus agrifolia	Coast Live Oak	2.5	10	G	G	Υ	Υ	Diameter taken below first branching
205	Quercus agrifolia	Coast Live Oak	2	5	G	G	Υ	Υ	Diameter taken below first branching
206	Quercus agrifolia	Coast Live Oak	2.5	5	G	G	Υ	Υ	Diameter taken below first branching
207	Quercus agrifolia	Coast Live Oak	1	5	G	G	Υ	Υ	Diameter taken below first branching
208	Ailanthus altissima	Chinese Tree of Heaven	18 @ base	20	Р	G	N	Υ	Multi
209	Ailanthus altissima	Chinese Tree of Heaven	15 @ base	20	Р	G	N	Υ	Multi
210	Ailanthus altissima	Chinese Tree of Heaven	16 @ base	25	Р	G	N	Υ	Multi
211	Ailanthus altissima	Chinese Tree of Heaven	40 @ base	25	Р	G	N	Υ	Multi
212	Ailanthus altissima	Chinese Tree of Heaven	22 @ base	25	Р	G	N	Υ	Multi


## FTC Tree Survey

Tag #	Species	Common Name	DBH	Approximat e Spread in Feet	Structure	Health	City Street Tree	<sup>1</sup> Proposed Removal	Notes
1.1	Ailanthus altissima	Chinese Tree of Heaven	13 base	14	F-G	G	N	Y	
5.1	Ailanthus altissima	Chinese Tree of Heaven	5.8	30	Р	G	N	Υ	
5.2	Ailanthus altissima	Chinese Tree of Heaven	9.8	30	Р	G	N	Υ	
11.1	Cupressus sempervirens	Italian cypress	9.5 base	Shared Canopy 25 feet long	F	F	N	Υ	
11.2	Cupressus sempervirens	Italian cypress	11	Shared Canopy 25 feet long	F	G	N	Υ	
11.3	Cupressus sempervirens	Italian cypress	15.2	Shared Canopy 25 feet long	F	G	N	Υ	Heritage Tree
11.4	Cupressus sempervirens	Italian cypress	7	Shared Canopy 25 feet long	F	G	N	Υ	
11.5	Cupressus sempervirens	Italian cypress	11.7	Shared Canopy 25 feet long	F	G	N	Υ	
11.6	Cupressus sempervirens	Italian cypress	11.8	Shared Canopy 25 feet long	F	G	N	Υ	
11.7	Cupressus sempervirens	Italian cypress	13	Shared Canopy 25 feet long	F	G	N	Υ	
11.8	Cupressus sempervirens	Italian cypress	~6 stake	8	Р	G	N	Υ	
13.1	Quercus ilex	holly oak	8.5	10	F	G	N	Υ	Possible tree to relocate.
16.01	Ailanthus altissima	Chinese Tree of Heaven	6.5	16	F	F	N	Y	_
16.1	Acer palmatum	Japanese maple	9.8 base	10	Р	G	N	Υ	
16.2	Acer palmatum	Japanese maple	9.5 base	14	Р	G	N	Υ	

				Approximat e Spread in			City Street	<sup>1</sup> Proposed	
Tag #	Species	Common Name	DBH	Feet	Structure	Health	Tree	Removal	Notes
16.3	Prunus caroliniana	Carolina laurel cherry	10 base	Shared Canopy 45 feet long	F	G	N	Υ	
16.4	Prunus caroliniana	Carolina laurel cherry	11.5 base	Shared Canopy 45 feet long	Р	G	N	Υ	
16.5	Prunus caroliniana	Carolina laurel cherry	8 base	Shared Canopy 45 feet long	Р	G	N	Υ	
16.6	Prunus caroliniana	Carolina laurel cherry	7.5 base	Shared Canopy 45 feet long	Р	G	N	Υ	
16.7	Prunus caroliniana	Carolina laurel cherry	9.5 base	Shared Canopy 45 feet long	Р	G	N	Υ	
16.8	Prunus caroliniana	Carolina laurel cherry	7.7 base	Shared Canopy 45 feet long	Р	G	N	Υ	
16.9	Prunus caroliniana	Carolina laurel cherry	7.3 base	8	Р	F	N	Υ	
17.1	Ailanthus altissima	Chinese Tree of Heaven	9.5	30	Р	F	N	Υ	
17.2	Ailanthus altissima	Chinese Tree of Heaven	6.4	18	Р	G	N	Y	
24.1	Ailanthus altissima	Chinese Tree of Heaven	18.4 base	15	VP	G	N	Υ	Heritage Tree
24.2	Ailanthus altissima	Chinese Tree of Heaven	16.5 base	20	VP	G	N	Υ	Heritage Tree
24.3	Ailanthus altissima	Chinese Tree of Heaven	7.3	18	VP	G	N	Y	
24.4	Ailanthus altissima	Chinese Tree of Heaven	8	20	VP	G	N	Y	
26.1	Afrocarpus altissima	fern pine	11.2 base	28	Р	F	N	Υ	
26.2	Afrocarpus altissima	fern pine	9.7	15	VP	F	N	Y	
26.3	Afrocarpus altissima	fern pine	13.6 base	15	Р	F	N	Υ	
26.4	Afrocarpus altissima	fern pine	14 base	12	F	G	N	Υ	

				Approximat e Spread in			City Street Tree	Proposea	
Tag #	Species	Common Name	DBH	Feet	Structure	Health	1100	Removal	Notes
26.5	Prunus caroliniana	Carolina laurel cherry	6.4 base	5	Р	F	N	Υ	
26.6	Prunus caroliniana	Carolina laurel cherry	8.8 base	8	Р	F	N	Υ	
26.7	Ailanthus altissima	Chinese Tree of Heaven	6 base	10	VP	G	N	Υ	
26.8	Prunus caroliniana	Carolina laurel cherry	6.5 base	1.5	VP	VP	N	Υ	
30.1	Ailanthus altissima	Chinese Tree of Heaven	7.5 base	8	F	G	Y	Υ	City Street Tree
30.2	Quercus rubra	red oak	2.5	7	F	G	Y	Υ	City Street Tree

<sup>1/</sup> Y - Considered to be proposed for removal unless determined otherwise by the Project Arborist or Owner.



## **Certification of Performance**

That I have personally inspected the tree(s) and /or property referred to in this report and have stated my findings accurately. The extent of the evaluation and appraisal is stated in the attached report and the Terms and Conditions;

That I have no current or prospective interest in the vegetation or the property that is the subject of this report and I have no personal interest or bias with respect to the parties involved;

That the analysis opinions and conclusions stated herein are my own and are based on current scientific procedures and facts;

That my compensation is not contingent upon the reporting of a predetermined conclusion that favors the cause of the client or any other party nor upon the results of the assessment the attainment of stipulated results or the occurrence of any subsequent events;

That my analysis opinions and conclusion were developed and this report has been prepared according to commonly accepted Arboricultural practices;

I further certify that I am a Registered Consulting Arborist® by the American Society of Consulting Arborists (ASCA) and a Certified Arborist by the International Society of Arboriculture (ISA).

## **Disclosure Statement**

Arborists are tree specialists who use their education, knowledge, training and experience to examine trees and recommend measures to enhance the beauty and health of trees and attempt to reduce the risk of living near trees. Clients may choose to accept or disregard the recommendations of the arborist or to seek additional advice.

Arborists cannot detect every condition that could possibly lead to the structural failure of a tree. Trees are living organisms that fail in ways we do not fully understand. Certain conditions are often hidden within trees or below the ground. Arborists cannot guarantee that a tree will be healthy or safe under all circumstances or for a specific period of time. Likewise remedial treatments cannot be guaranteed.

Trees can be managed but they cannot be controlled. To live near trees is to accept some degree of risk.

Signed:

Date: 6/02/2016

Re

Walter Fujii, RCA®



# Fujiitrees Consulting TERMS AND CONDITIONS

The following terms and conditions apply to all oral and written reports and correspondence pertaining to the consultations, inspections and activities of Fujiitrees Consulting hereinafter referred to as "Consultant".

- 1. Any legal description provided to the Consultant is assumed to be correct. No responsibility is assumed for matters legal in character nor is any opinion rendered as to the quality of any title.
- 2. It is assumed that any property referred to in any report or in conjunction with any services performed by the Consultant, is not in violation of any applicable codes, ordinances, statutes, or other governmental regulations, and that any titles and ownership to any property are assumed to be good and marketable. Any existing liens and encumbrances have been disregarded.
- 3. Possession of this report or a copy thereof does not imply any right of publication or use for any purpose, without the express permission of the Consultant and the Client to whom the report was issued. Loss, removal or alteration of any part of a report invalidates the entire appraisal/evaluation.
- 4. The scope of any report or other correspondence is limited to the trees and conditions specifically mentioned in those reports and correspondence. The Consultant assumes no liability for the failure of trees or parts of trees, either inspected or otherwise. The Consultant assumes no responsibility to report on the condition of any tree or landscape feature not specifically requested by the named client.
- 5. No tree described in this report was climbed, unless otherwise stated. The Consultant cannot take responsibility for any defects, which could only have been discovered by climbing. A full root crown examination (RCX), consisting of excavating the soil around the tree to uncover the root crown and major buttress roots was not performed unless otherwise stated. We cannot take responsibility for any root defects, which could only have been discovered by such an inspection.
- 6. The Consultant shall not be required to provide further documentation, give testimony, be deposed, or attend court by reason of this appraisal/report unless subsequent contractual arrangements are made, including payment of additional fees for such services as described by the consultant or in the fee schedules or contract.
- 7. The Consultant offers no guarantees or warrantees, either expressed or implied, as to the suitability of the information contained in the reports for any purpose. It remains the responsibility of the client to determine applicability to his/her particular case.
- 8. Any report and the values, observations, and recommendations expressed therein represent the professional opinion of the Consultant, and the fee for services is in no manner contingent upon the reporting of a specified value nor upon any particular finding to be reported.
- 9. Any photographs, diagrams, graphs, sketches, or other graphic material included in any report, being intended solely as visual aids, are not necessarily to scale and should not be construed as engineering reports or surveys, unless otherwise noted in the report. Any reproductions of graphs material or the work produce of any other persons is intended solely for the purpose of clarification and ease of reference. Inclusion of said information does not constitute a representation by the Consultant as to the sufficiency or accuracy of that information.
- 10. Trees can be managed, but they cannot be controlled. To live near trees is to accept some degree of risk. The only way to eliminate all risk associated with trees is to eliminate all trees.
- 11. Payment terms are net payable upon receipt of invoice. All balances due beyond 30 days of invoice date will be charged a service fee of 1.5 percent per month (18.0% APR). All checks returned for insufficient funds or any other reason will be subject to a \$25.00 service fee. Advance payment of fees may be required in some cases.



# **Environmental Quality Commission**



## **REGULAR MEETING MINUTES - DRAFT**

Date: 6/22/2016
Time: 6:30 p.m.
Administration Building
701 Laurel St., Menlo Park, CA 94025

A. Vice Chair London called the meeting to order at 6:39 p.m.

## B. Roll Call

Present: DeCardy, Vice Chair London, Marshall, Chair Martin, Smolke

Absent: Bedwell, Dickerson

Staff: Environmental Services Manager Heather Abrams, Environmental Services Specialist

Sheena Ignacio

#### C. Public Comment

No Public Comment

## D. Regular Business

Vice Chair moved items D3 and D4 before D1

D1. Overview of the Facebook Campus Expansion Project, the Draft Environmental Impact Report (EIR), and Consideration of a Recommendation to the Planning Commission and City Council on a Request to Remove 274 Heritage Trees at 301-309 Constitution Drive (Attachment) – 1 hour – Kyle Perata, Senior Planner

Chair Martin arrives at 7:45 p.m.

**ACTION:** Motion and second (DeCardy/London) to recommend to the Planning Commission to approve the heritage tree removals based on the findings of the consulting arborist passes (5-0-2) (Yayes: Marshall, Smolke, DeCardy, Vice Chair London, Chair Martin; Absent/Abstain: Bedwell, Dickerson)

D2. Discuss and approve an updated EQC 2-Year Work Plan for submission to City Council (Attachment) – 1 hour – Chair Martin

**ACTION:** No action taken. The commission will discuss and approve the new EQC 2-Year Work Plan and subcommittee assignments at the August meeting.

Smolke leaves at 9:40 p.m.

D3. Change August EQC meeting date to August 31, 2016 – 2 mins – Chair Martin

**ACTION:** Motion and second (London/Marshall) to approve the date change for the August meeting passes (4-0-3) (Yayes: Vice Chair London, Marshall, DeCardy, Smolke; Absent/Abstain: Bedwell, Dickerson, Martin)

D4. Approve May 25, 2016 Environmental Quality Commission meeting minutes (Attachment) – 2 mins

**ACTION:** Motion and second (DeCardy/Marshall) to approve the EQC May minutes passes (4-0-3) (Yayes: London, Marshall, DeCardy, Smolke; Absent/Abstain: Bedwell, Dickerson, Martin)

## E. Reports and Announcements

- E1. Update on Peninsula Clean Energy 2 mins Heather Abrams, Environmental Programs Manager
- E2. Informational update on Zero Waste Plan and Solid Waste Rate Study, which will begin soon and continue through 2017 2 mins Heather Abrams, Environmental Programs Manager
- E3. Update on Peninsula SunShares campaign to offer low cost solar PV systems and Electric Vehicles 5 mins Sheena Ignacio, Environmental Programs Specialist
- E4. Future Agenda items
  - Heritage Tree removal appeal for 445 Oak Ct.

## F. Adjournment

Chair Martin adjourned the meeting at 9:54 p.m.

Meeting minutes taken by Commissioner Smolke

Meeting minutes prepared by Sheena Ignacio, Environmental Programs Specialist